



No.F6/DFS/MS/School/NDZ/2023/ 452

Dated: 03/07/2023

**FIRE SAFETY CERTIFICATE**

Certified that the Bright Way Public School located at Main 33 Foota Road Panchal Vihar, Shiv Vihar , Karawal Nagar, Delhi-110094, building comprised of Ground, First floor, Second floor & Third floor but school is running on Ground & First floor only owned / occupied by Bright Way Public School, was issued FSC vide letter No. F6/DFS/MS/School/2018/1382 dated 13.06.2018. The School building was re-inspected by the officer concerned of this department on 15/06/2023 in presence of Mr. Hemant Kumar (Manager) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with D.O.E circular No. F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 and that the building is fit for occupancy class "Educational" (Group-B) and with effect from 03/07/2023 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 03/07/2023 at New Delhi by.

(ATUL GARG)

DIRECTOR

DELHI FIRE SERVICE

o/c @

Copy to:-

1. The Principal, Bright Way Public School Main 33 Foota Road Panchal Vihar, Shiv Vihar , Karawal Nagar, Delhi-94.
2. The Dy. Director of Education, B- Block, Yamuna Vihar, Delhi-110053.

**Conditions for the validity of Fire Safety Certificate**

1. Fire Safety Certificate is valid for Ground & 1 upper floor only.
2. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
3. All the means of escape shall be kept free of all the type of obstruction all the time.
4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
6. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
7. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in).



## INSPECTION REPORT

1	Name & address of the building	Bright Way Public School located at Main 33 Foota Road Panchal Vihar, Shiv Vihar, Karawal Nagar, Delhi-110094.				
2	Building is comprised of	Ground + 3 upper floor only but 2 <sup>nd</sup> & 3 <sup>rd</sup> floor sealed. (School Running at Ground & first floor)				
3	Type of occupancy	Group B –Educational Building				
4	Type of case	Renewal				
5	Details of previous FSC	F6/DFS/MS/School/2018/1382 dated 13.06.2018				
6	Fire safety directives letter no.	F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011				
7	Date of inspection	15/06/2023				
8	Name of the inspecting officers	Yashwant Singh Meena ADO (L.N)				
9	Name of the designation of officer from the building side	Mr. Hemant Kumar (Manager)				
10	Year of construction	2002				
11	Applicant's letter no.	Outdoor Diary No.2644 dated 08/06/2023				
S.No	Minimum standard of fire prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR		
1	<b>Access to Building:</b>					
	A	Road width	6.0 mtrs.	10 mtrs.	MR	
	B	Gate width	NA	NA	NA	
	C	Width of internal road	NA	NA	NA	
2	<b>Number, Width, Type and Arrangement of Exits:</b>					
	A	Number of staircases				
		a	Upper floor	01 nos.	02 nos.	MR
		b	Basement	NA	NA	NA
	B	Width of staircases				
		a	Upper floor	1.5 mtrs	01 mtrs & 0.92 mtrs	MR
		b	Basement	NA	NA	NA
	C	Protection of exits		NA	NA	NA
		a	Fire check door	NA	NA	NA
		b	Pressurization	NA	NA	NA
	D	No. of continuous staircases to terrace		01no.	01 nos.	MR
	E	Width of corridor		1.50 mtrs.	1.50 mtrs.	MR
	F	Door size		1.0 mtrs	1.0 mtrs	MR
3	<b>Compartmentation:</b>					
	A	Fire check door		NA	NA	NA
	B	Sealing of electrical shafts		NA	NA	NA
	C	Fire rating of shaft door		NA	NA	NA
	D	Water curtain		NA	NA	NA
	E	Fire dampers		NA	NA	NA
4	<b>Smoke Management System:</b>					
	A	Basement		NA	NA	NA
	B	Upper floor		NA	NA	NA



<b>5.</b>	<b>Fire Extinguisher:</b>				
	<b>A</b>	Total numbers	04 nos.	10 nos.	MR
	<b>B</b>	Types	ABC/CO <sub>2</sub>	ABC/CO <sub>2</sub>	MR
	<b>C</b>	ISI marking	ISI Marked	Provided	MR
<b>6</b>	<b>First-Aid-Hose Reel:</b>				
	<b>A</b>	Total numbers of each floor	NA	NA	NA
	<b>B</b>	Length of hose reel hose	NA	NA	NA
	<b>C</b>	Nozzle diameter	NA	NA	NA
<b>7</b>	<b>Automatic Fire Detection and Alarming System:</b>				
	<b>A</b>	Type of detectors	NA	NA	NA
	<b>B</b>	Location of main panel	NA	NA	NA
	<b>C</b>	Location of repeater panel	NA	NA	NA
	<b>D</b>	Alternate source of power	NA	NA	NA
	<b>E</b>	Hooters	NA	NA	NA
<b>8</b>	<b>MOEFA:</b>		NA	NA	NA
<b>9</b>	<b>Public Address System:</b>		NA	NA	NA
<b>10</b>	<b>Automatic Sprinkler System:</b>				
	<b>A</b>	Basement	NA	NA	NA
	<b>B</b>	Upper floor	NA	NA	NA
	<b>C</b>	Sprinkler above false ceiling	NA	NA	NA
<b>11</b>	<b>Internal Hydrants:</b>				
	<b>A</b>	Size of riser/down-comer	NA	NA	NA
	<b>B</b>	Number of hydrants per floor	NA	NA	NA
	<b>C</b>	Hose box	NA	NA	NA
<b>12</b>	<b>Yard Hydrants:</b>				
	<b>A</b>	Total number of hydrants	NA	NA	NA
	<b>B</b>	Hose box	NA	NA	NA
<b>13</b>	<b>Pumping Arrangements:</b>				
<b>1</b>	<b>Ground level</b>				
	<b>A</b>	Discharge of main pump	NA	NA	NA
	<b>B</b>	Head of main pump	NA	NA	NA
	<b>C</b>	Number of main pumps	NA	NA	NA
	<b>D</b>	Jockey pump out put	NA	NA	NA
	<b>E</b>	Jockey pump head	NA	NA	NA
	<b>F</b>	Standby pump out put	NA	NA	NA
	<b>G</b>	Standby pump head	NA	NA	NA
	<b>H</b>	Auto starting /manual stopping	NA	NA	NA
	<b>I</b>	Pump house access	NA	NA	NA
<b>2</b>	<b>Terrace Level</b>				
	<b>A</b>	Discharge of pump	NA	NA	NA
	<b>B</b>	Head of the pump	NA	NA	NA
	<b>C</b>	Power supply	NA	NA	NA
	<b>D</b>	Auto starting of pump	NA	NA	NA



<b>14</b>	<b>Captive Water Storage for Fire Fighting:</b>			
	<b>A</b>	Underground tank capacity	NA	NA
	<b>B</b>	Draw-off connection	NA	NA
	<b>C</b>	Fire service inlet	NA	NA
	<b>D</b>	Access to tank	NA	NA
	<b>E</b>	Overhead tank capacity	NA	NA
<b>15</b>	<b>Exit Signage:</b>			
			NA	NA
<b>16</b>	<b>Provision of Lifts:</b>			
	<b>A</b>	Pressurization of lift shaft	NA	NA
	<b>B</b>	Pressurization of lift lobby	NA	NA
	<b>C</b>	Communication in lift car	NA	NA
	<b>D</b>	Firemen's grounding switch	NA	NA
	<b>E</b>	Lift signage	NA	NA
<b>17</b>	<b>Standby Power Supply:</b>			
			NA	NA
<b>18</b>	<b>Refuge Area:</b>			
	<b>A</b>	Total area	NA	NA
	<b>B</b>	Location	NA	NA
<b>19</b>	<b>Fire Control Room:</b>			
	<b>A</b>	Detector system panel	NA	NA
	<b>B</b>	Flow switch panel	NA	NA
	<b>C</b>	PA system panel	NA	NA
	<b>D</b>	Battery backup	NA	NA
	<b>E</b>	Building floor plans	NA	NA
<b>20</b>	<b>Special Fire Protection systems for protection of special Risks, if any:</b>			
			NA	NA

**Note:** - Building comprised of Ground, First floor, Second floor & 3<sup>rd</sup> floor but Management has given an undertaking dated 19.06.2023 placed at C- 33 that they will not use 2<sup>nd</sup> & 3<sup>rd</sup> floor for school purpose in any case (2<sup>nd</sup> & 3<sup>rd</sup> floor is sealed) . FSC is recommended for Ground & First Floor only.


The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education Circular no. F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011, the FSC issued vide letter no. F6/DFS/MS/School/2018/1382 dated 13.06.2018 is recommended to be renewed.




Signature of the Inspecting Officer  
 Name Yashwant Singh Meena  
 Designation ADO (L.N)


DO (E.D)

  
 21/06/2023

Dy. CFO (NBZ) on leave


CFO (H.R.)   
 22/6/2023

Director   
 27/6/2023



F.T. Letter is setup for sign. Please

Director   
 29/6/23

  
 27/6/2023