

C 31

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110 001.



No.F.6/DFS/MS/School/2023/SZ / 444

Dated: 27/06/2023

FIRE SAFETY CERTIFICATE

Certified that the New Jagdish Tara Lancers Public School running at ground & first floor in a building comprised of ground plus two upper floors located at C- 8,9,10, Maharani Enclave, Hastal Village, Uttam Nagar, New Delhi 110059, owned/occupied by New Jagdish Tara Lancers Public School was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/School/2017/SZ/520 dated 10/04/2017. The school building was re-inspected by the officer concerned of this department on 19/06/2023 in the presence of Mr. Manish Sharma (Manager) and found that School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises (Ground & first floor only) is fit for occupancy class "Educational" for a period of three years, subject to compliance of the conditions printed as under.

Issued on.....27/06/2023..... at New Delhi.


(Atul Gang)
Director
Delhi Fire Service


Copy to:-

1. The Principal,
New Jagdish Tara Lancers Public School, C-8,9,10, Maharani Enclave,
Hastal Village, Uttam Nagar, New Delhi 110059.
2. Director of Education,
Govt. of NCT of Delhi, Old Secretariat, New Delhi - 110054.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. The means of escape shall be kept unlocked and unobstructed, for unhindered evacuation of occupants in case of emergency.
3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
4. The trained staff should be available round the clock.
5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
7. This FSC is not valid for second floor.

N/15

INSPECTION REPORT

1. Name & address of the building : New Jagdish Tara Lancers Public School, C-8,9,10, Maharani Enclave, Hastal Village, Uttam Nagar, New Delhi 110059.
2. Building comprised of : G+2 upper floors but school running at ground & first floor only.
3. Type of Occupancy : Educational
4. Type of Case : Renewal
5. Details of Previous NOC : F.6/DFS/MS/School/2017/SZ/520 dated 10/04/2017 (G+1)
6. Fire Safety directives letter No : N/A
7. Date of inspection : 19/06/2023
8. Name of Inspecting Officer : A.D.O. R.K.Yadav
9. Name and designation of officers
From the building side : Mr. Manish Sharma (Manager)
10. Year of Construction : Before 2011 & 2019
11. Applicant's letter No. : Nil dated 30/06/2023

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	DOE Circular dt- 01/03/2011	Provided at site	Remarks MR/NMR
1.	Access to building			
	<ul style="list-style-type: none"> Road width Gate width Width of internal road 	<p>Accessible</p> <p>N/A</p> <p>N/A</p>	<p>4.3 m</p> <p>N/A</p> <p>N/A</p>	<p>M/R(9 m road is one length of hose (30 m) away</p> <p>N/A</p> <p>N/A</p>
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> Upper Floors Basements 	<p>02 No.'s</p> <p>N/A</p>	<p>02 No.'s</p> <p>N/A</p>	<p>M/R</p> <p>N/A</p>
	b. Width of staircases			
	<ul style="list-style-type: none"> Upper Floor Basements 	<p>1.5 & .75 m</p> <p>N/A</p>	<p>1.50 & 1.35 m</p> <p>N/A</p>	<p>MR</p> <p>N/A</p>
	c. Protection of exits			
	<ul style="list-style-type: none"> Fire check door Pressurization 	<p>N/A</p> <p>N/A</p>	<p>N/A</p> <p>N/A</p>	<p>N/A</p> <p>N/A</p>
	d. No. of continuous staircases to terrace	N/A	One	N/A
	e. Width of Corridor	1.5 m	1.80 m	M/R
	f. Door Size	1.0 m	1.0 m	M/R, (Students less than 45 in each class) ✓
3.	Compartmentation			
	<ul style="list-style-type: none"> Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers 	<p>N/A</p> <p>N/A</p> <p>N/A</p> <p>N/A</p> <p>N/A</p>	<p>N/A</p> <p>N/A</p> <p>N/A</p> <p>N/A</p> <p>N/A</p>	<p>N/A</p> <p>N/A</p> <p>N/A</p> <p>N/A</p> <p>N/A</p>
4.	Smoke Management System			
	<ul style="list-style-type: none"> Basements Upper floors 	<p>N/A</p> <p>Required</p>	<p>N/A</p> <p>Natural Ventilation</p>	<p>N/A</p> <p>M/R</p>
5.	Fire Extinguishers			
	<ul style="list-style-type: none"> Total numbers Types IS marking 	04 no's ABC/CO2 type ISI marked	<p>Provided</p> <p>Provided</p> <p>Provided</p>	<p>M/R</p> <p>M/R</p> <p>M/R</p>
6.	First-Aid Hose Reels			
	<ul style="list-style-type: none"> Total numbers on each floor Length of hose reel hose Nozzle diameter 	<p>N/A</p> <p>N/A</p> <p>N/A</p>	<p>Provided</p> <p>Provided</p> <p>Provided</p>	<p>M/R</p> <p>M/R</p> <p>M/R</p>

7.	Automatic fire detection and alarming system			
	• Type of detectors	N/A	N/A	N/A
	• Location of Main Panel	N/A	N/A	N/A
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	• Basement	N/A	N/A	N/A
	• Ground Floor	N/A	N/A	N/A
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	• Size of riser/down-comer	N/A	N/A	N/A
	• Number of hydrants per floor	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
12.	Yard Hydrants			
	• Total number of hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	• Ground Level			
	➤ Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main pump	N/A	N/A	N/A
	➤ Number of main pumps	N/A	N/A	N/A
	➤ Jockey Pump out put	N/A	N/A	N/A
	➤ Jockey pump head	N/A	N/A	N/A
	➤ Standby Pump out put	N/A	N/A	N/A
	➤ Standby Pump Head	N/A	N/A	N/A
	➤ Auto Starting/Manual Stopping	N/A	N/A	N/A
	➤ Pump House Access	N/A	N/A	N/A
	• Terrace level			
	➤ Discharge of pump	N/A	450 LPM	M/R
	➤ Head of the pump	N/A	30 M	M/R
	➤ Power Supply	N/A	Provided	M/R
	➤ Auto Starting of pump	N/A	Provided	M/R
14.	Captive Water Storage for fire fighting			
	• Underground tank capacity	N/A	N/A	N/A
	➤ Draw-off connection	N/A	N/A	N/A
	➤ Fire service inlet	N/A	N/A	N/A
	➤ Access to tank	N/A	N/A	N/A
	• Overhead Tank capacity	N/A	10,000 liters	M/R
15.	Exit Signage.	Required	Provided	MR

N/17

16.	Provision of Lifts.	No Lift		
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication In lift Car	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area.			
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19.	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2017/SZ/520 dated 10/04/2017 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note:- As per the undertaking submitted by the principal (placed at C-26), school running at ground plus one upper floor and second floor is not being used for school purpose.

R. K. Yadav
28/06/2023

Signature of Inspecting Officer
Name:- R.K.Yadav
Designation:- Asstt. Divisional Officer

Divisional Officer (South West)
Asst 22/6/23

CGO (S2)
23/6/2023

Director
29/6/23
Mr R.K. JNP