



C-43



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F.6/DFS/MS/School/2023/NDZ/150

Dated: 30/06/2023

FIRE SAFETY CERTIFICATE

Certified that the Motherhood Public School located at E-4/446, 4^{1/2} Pusta, Sonia Vihar, Delhi-110094, comprised of Small Basement (not in use), Ground & One upper Floor only, owned / occupied by Motherhood Public School, was issued Fire Safety Certificate vide letter No. F6/DFS/MS/School/2020/NDZ/102 Dt. 04/03/2020 (for Ground & One upper Floor only). The School building was re-inspected by the officer concerned of this department on 16/06/2023 in presence of Smt. Manju Rani (Manager) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with D.O.E. Circular No. F16/Estate/CC/FS/2011/3298 to 3398 Dated 01/03/2011 and that the building is fit for occupancy class "Educational" (Group-B) for Ground & One upper floor with effect from 30/06/2023 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 30/06/2023 at New Delhi by.

(ATUL GARG)
 DIRECTOR
 DELHI FIRE SERVICE

Copy to:-

1. The Manager, Motherhood Public School, E-4/446, 4^{1/2} Pusta, Sonia Vihar, Delhi-110094.
2. The Dy. Director of Education, B-Block, Yamuna Vihar, Delhi-110053.

Conditions for the validity of Fire Safety Certificate:

1. Fire Safety Certificate is valid for Ground & One Upper Floor only. Small Basement should not be used school purpose failing which FSC should be treated null & void.
2. All the fire safety arrangement provided therein shall be maintained in good working conditions at all times.
3. Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the Management.
4. The trained fire fighting staff should be available round the clock.
5. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
6. Basement shall be used strictly as per building by-Laws.
7. This certificate cannot be treated in any case for regularizations of unauthorized construction, if any.
8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.
9. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

11/14

- Name & address of the building: Motherhood Public School, E-4/446, 4^{1/2} Pusta Sonia Vihar, Delhi-110094
- Building is comprised of: Ground & One upper floor (There is also a Small Basement which is not in use)
- Type of Occupancy: Educational
- Type of Case: Renewal
- Details of previous NOC: F6/DFS/MS/School/2020/NDZ/102 Dt. 04/03/2020
- Fire Safety directives Letter No: DOE Cir 3298-3398 dated 01/03/2011
- Date of inspection: 16/06/2023
- Name of the Inspecting Officer: A K Jaiswal D O (E D)
- Name and designation of Officer from the building side: Sh Manju Rani (Manager)
- Year of Construction: 2011
- Applicant's letter No: MRLSSS/2023-24/5/28 Dated 31/05/2023

S.No	Minimum Standards on fire prevention and fire safety U/R 33	NBC Part IV Requirement	Provided at Site	Remarks
1	Access to building			
	• Road width	6 m	6 m ✓	MR
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
2	Number, Width, Type and Arrangement of Exits			
	a. Number of Staircases			
	• Upper Floor	01 nos	01 nos. & 1 Ramp ✓	MR
	• Basement	N/A	N/A	N/A
	b. Width of Staircases			
	• Upper Floor	1.50 m	1.50 m & 1.00m (Ramp) ✓	MR
	• Basement	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	d. No. of continuous staircases to terrace	01	01	MR
	e. Width of Corridor	1.50 m	Provided ✓	MR
	f. Door size	1.00 m	Provided ✓	MR
3	Compartmentation			
	• Fire check Door	N/A	N/A	N/A
	• Sealing of electrical Shafts	N/A	N/A	N/A
	• Fire rating of Shaft Door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4	Smoke Management System			
	• Basement	N/A	N/A	N/A
	• Upper Floor	N/A	N/A	N/A
5	Fire Extinguishers			
	• Total Numbers	04 nos	04 nos ✓	MR
	• Types	ABC & Co2	ABC & Co2	MR
	• IS Marking	ISI Marked	ISI Marked	MR

2

6	First-aid-Hose Reels			
	Total numbers of each floor	N/A	N/A	N/A
	• Length of hose reel hose	N/A	N/A	N/A
	• Nozzle diameter	N/A	N/A	N/A
7	Automatic fire detection and alarming system			
	• Type of detectors	N/A	N/A	N/A
	• Location of main panel	N/A	N/A	N/A
	• Location of repeater panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooter's Location	N/A	N/A	N/A
8	MOEFA	N/A	N/A	N/A
9	Public address System	N/A	N/A	N/A
10	Automatic Sprinkler System			
	• Basement	N/A	N/A	N/A
	• Upper Floor	N/A	N/A	N/A
	• Sprinkler above false Ceiling	N/A	N/A	N/A
11	Internal Hydrants			
	• Size of rise/down-comer	N/A	N/A	N/A
	• Number of Hydrants per Floor	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
12	Yard Hydrants			
	• Total number of Hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13	Pumping Arrangement			
	• Ground Level			
	➤ Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main Pump	N/A	N/A	N/A
	➤ Number of main Pumps	N/A	N/A	N/A
	➤ Jockey pump output	N/A	N/A	N/A
	➤ Jockey pump head	N/A	N/A	N/A
	➤ Standby pump output	N/A	N/A	N/A
	➤ Standby pump head	N/A	N/A	N/A
	➤ Auto starting/Manual stopping	N/A	N/A	N/A
	➤ Pump house access	N/A	N/A	N/A
	• Terrace Level			
	➤ Discharge of pump	N/A	N/A	N/A
	➤ head of the pump	N/A	N/A	N/A
	➤ Power supply	N/A	N/A	N/A
	➤ Auto Starting of pump	N/A	N/A	N/A
14	Captive Water Storage for Fire Fighting			
	• Underground tank capacity	N/A	N/A	N/A
	➤ Draw-off connection	N/A	N/A	N/A
	➤ Fire service inlet	N/A	N/A	N/A
	➤ Access to tank	N/A	N/A	N/A
	• overhead Tank capacity	N/A	N/A	N/A
15	Exit Signage	N/A	N/A	N/A

16	Provision of Lifts			
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication in lift car	N/A	N/A	N/A
	• Firemen's grounding switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector system panel	N/A	N/A	N/A
	• Flow switch panel	N/A	N/A	N/A
	• PA system panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building floor plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

Note:- 1. There is a small Basement (Area 17ft. X 10 ft.) and it is not in use. Undertaking regarding this is placed at C-41. This basement was also mentioned in previous FSC dated 04/03/2022.

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No. F6/DFS/MS/School/2020/NDZ/102 Dt. 04/03/2020 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Approved
19/06/2023
Signature of the Inspecting Officer
Name: Ashok Kumar Jaiswal
Designation: D.O (East Div.)

DY. C/O (NDZ)

27/06/23

C.F/O

23/06/2023

Director

27/06/23

Director

F.T. is added for sign. pl.

27/06/23

27/06/23