GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/EH/NDZ/2023/ 213

Dated: - 04.07.2023

FIRE SAFETY CERTIFICATE

Certified that the M/s Excuse Me Boss (Dee Restaurant Pvt. Ltd) located at F-14-15, Ground floor, Shivam House, Middle Circle, Connaught Place, New Delhi in a building comprised of Basement + Ground + 03 Upper floors but Restaurant is running at Ground floor only, was granted FSC by this department vide letter No.F6/DFS/MS/EH/NDZ/2020/23 dated 18/08/2020. Now, the premises was re-inspected by the officers concerned of this department on 27/06/2023 in the presence of Mr. Deepak and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Assembly Building (Group D), Restaurant at ground floor only and valid up to 31.03.2026 from the date of issue in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010.

Issued .0.4. R.7. 2.02.3. at New Delhi by.

DIRECTOR Delhi Fire Service

Copy to:-

1. The Chief Architect, NDMC, Palika Kendra, New Delhi. : to ensure the occupancy and deviation in construction if any.

2. The Addl. Commissioner of Police (Lic), Ist floor, PS Defence Colony, New Delhi Online ID

no. 2023040305053 dated 02.06.23.

3. The Manager, M/s Excuse Me Boss (Dee Restaurant Pvt. Ltd), F-14-15, Ground floor, Shivam House,

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction, use of occupancy, height of building, electric installation, set back area etc. shall be checked & verified by the concerned authority.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction,

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry. Any flammable material for interior decoration is prohibited.

INSPECTION REPORT

1. Name & address of the building M/s Excuse Me Boss (Dee Restaurant Pvt.

Ltd) located at F-14-15, Ground floor, Shivam House, Middle Circle, Connaught Place, New

Delhi. B + Gr. + 03 Upper floors,

2. Type of occupancy:- Assembly Building Group-D

Restaurant at ground floor only

Type of case:- Renewal

4. Details of previous FSC:- F6/DFS/MS/EH/NDZ/2020/23 dated

18/08/2020

5. Fire safety directives No.- N/A

6. Date of inspection:- 27/06/23

 Name of the inspecting officer:- Sh. Rajender Atwal (DO/CD) & Sh. Ravinder Singh (ADO/CC)

Name & designation of officer
 From the building side:-

From the building side:- Sh. Deepak

9. Year of construction:- Old Heritage

10. Applicant's letter No:- ID no. 2023040305053 dated 02.06.23.

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR	
1.	Access to Building				
	1) Road width	06m	Provided	MR	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Arrangement of Exits				
	A. Number of staircases	•			
	1. Upper floors	N/A	01	N/A	
	2. Basements	01	01	MR	
	B. Width of staircase				
	1. Upper floors	N/A	1.20 mtr.	N/A	
	2. Basements	1.20 mtr.	1.20 mtr.	MR	
	C. Protection of exits				
	1. Fire check door	Required	Provided	MR	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous staircase to terrace	01	01	MR	
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	2 mtr.	2 mtr.	MR	
3.	Compartmentation				
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
4.	Smoke Management System				
	1) Basements	30 ACPH	Mechanical	N/A	
	2) Upper floors	12 a/c per hour	Natural	MR	
5.	Fire Extinguishers				

	1) Total numbers	10 Nos.	12 Nos.	LVD.
				MR MR
	2) Types	ABC & CO2	ABC & CO2	MR 🦠
,	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &			
-	1) Type of detectors	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
-14	5) Hooter's Location	N/A	N/A	N/A
0				-
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System	B		100
	1) Basement	Required	Provided	MR
	2) Upper floors (Gr. Floor)	Required	Provided	MR
7	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
1	1) Size of riser/down-comer	N/A	N/A	N/A
5	Number of hydrants per floor	N/A	N/A	N/A
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants	IVA.	IVA	IVA
141	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement	T		1.0.2
10.	1) Ground level	N/A	N/A	N/A
F	a) Discharge of main pump	N/A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump		N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual stopping	N/A	N/A	N/A
	2) Terrace level			KIIZA
	a) Discharge of pump	900 & 180 LPM	900 & 180 LPM	MR
	b) Head of pump	30 mtr.	30 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
14.	Captive Water Storage for F			
	Under ground tank capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A

	b) Fire service inlet	Required	Provided	MR
	c) Access to tank	Required	Provided	MR
F 15	d) Over head tank capacity	5000 ltr.	5000 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
1	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	N/A
1	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			NA

The fire protection systems provided in the building were randomly tested, checked and

found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, we may renew the FSC issued vide letter no. F6/DFS/MS/EH/NDZ/2020/23 dated 18/08/2020, under rule 35(6) of the Delhi Fire Service rules 2010. Accordingly, reply letter is prepared and put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name :- Rajinder Atwal Designation :- DO (CD) Signature of the Inspecting Officer

Name :- Ravinder Singh

Designation :- ADO (CC)