GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2023/126 Dated: 03/07/2023

FIRE SAFETY CERTIFICATE

Nagar, New Delhi- 110008 was granted Fire Safety Certificate vide this department letter No. F.6/DFS/MS/GH/SZ/2020/75 dated 25.02.2020, for building comprised of basement, stilt, ground plus three upper floors, using basement as storage, stilt as parking ground floor as waiting lobby & hall, first, second & third floor each having 11 guest rooms respectively (total 33 guest rooms only). The premises was re-inspected by the officers concerned of this department on 23.06.2023 in presence of Mr. Mohit Shah, Owner of the guest house, and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) for basement as storage, stilt as parking ground floor as waiting lobby & hall, first, second & third floor each having 11 guest rooms respectively (total 33 guest rooms only), with effect from 03/07/2023 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 03/07/2023 at New Delhi by.

Director Delhi Fire Service

Application Id No. 2023061410877 dated 19.06.2023

Following Fire Safety Directives must be adhered to:

- No occupancy used above third floor and basement used for storage purpose only shall be strictly adhered by Owner/Occupier.
- All the means of escape shall be kept free of all type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire
 equipments and method of smooth and speedy safe evacuation of occupants in
 case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- All comments / directions of licensing department shall always be permitted and followed.
- The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building : M/s The Exotica Grand guest house, 1/12, West Patel

Nagar, New Delhi- 110008

2. Type of Occupancy

: Lodging House 3. Building Composition

: Said guest house building comprised of Basement, Stilt, ground plus three upper floors, using basement as storage, stilt as parking. ground floor as waiting lobby & hall, 1st, 2nd & 3rd floor each having 11 guest rooms respectively (total 33 guest rooms) pantry and one

staff room on terrace, which is sealed by owner.

4. Type of Case : Renewal

Details of previous NOC : F.6/DFS/MS/GH/SZ/2020/75 dated 25.02.2020

6. Fire Safety directives letter No : N/A.

Date of inspection : 23.06.2023

8. Name of the Inspecting Officers: P.V. Rathee, Asstt. Divisional Officer (SRD)

Name and designation of officers

from the building side : Mr. Mohit Shah, Owner

	Access to building Road width Gate width Width of internal road Number, Width, Type & Arrangeme a. Number of staircases Upper Floors Basements b. Width of staircases	N/A	Provided Directly accessible from N/A	m road N//		
	Gate width Width of internal road Number, Width, Type & Arrangeme a. Number of staircases Upper Floors Basements	N//A D N/A ent of Exits	Directly accessible from	road N//		
	Width of internal road Number, Width, Type & Arrangeme Number of staircases Upper Floors Basements	N/A ent of Exits				
	Number, Width, Type & Arrangeme a. Number of staircases Upper Floors Basements	ent of Exits	N/A -	N//		
	a. Number of staircases • Upper Floors • Basements		a a a a a a a a a a a a a a a a a a a			
	Upper FloorsBasements	01	•			
	Upper FloorsBasements	01				
	Basements	O1	Provided	MR being old o		
	100000000000000000000000000000000000000	02	Provided	MR		
	b. Width of staircases					
	Width of staircases Upper Floors	1.25 mts.	1.28 mts.	1.28 mts. MR		
		1.25 mts.	1.25, 1.23 mts	MR being old cas		
	Basements	1.25 III.3.	1.25, 1.25 mts			
	c. Protection of exits	1.00	725 255576			
	Fire check door	Required	Provided	MR		
	Pressurization	N/A	N/A	N/A		
	e. No. of continuous staircases to terrace	01	01	MR		
	g. Width of Corridor	1.25 mts	1.45 mts	MR		
	h. Door Size	Old case	Old case Provided (0.87 mt.) MR bei			
	Compartmentation.	D : 1	0 11.1	546		
	 Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain 	Required	Provided	MR		
		Required N/A	Sealed N/A	MR		
			N/A N/A	N/A		
		N/A		N/A N/A		
	Fire Dampers	N/A	N/A N/A			
	Smoke Management System.					
	Basements	30 a/c per hour				
	Upper floors	12 a/c per hour	Natural ventilation	n MR		
Ď.	Fire Extinguishers					
	Total numbers	12	Provided	MR		
	• Types	CO ₂ , ABC type	CAMBOTT TO THE	MF		
	IS marking	ISI marked	Provided	MI		

6	First-Aid Hose Reels.	1/-18	7		
	 Total numbers on each floor 	01	Provided		MR
	 Length of hose reel hose 	30 m	Provided		MR
	Nozzle diameter	5 mm	Provided		MR
7	Automatic fire detection and alarmi	ng system.			
	 Type of detectors 	Carbon Mon	oxide Provide	ed	MR
	 Location of Main Panel 	Require	Required Provided near re		MR
	 Location of Repeater Panel 	N/A N/A			N/A
	 Alternate source of power 	Require	d Provide	ed	MR
	Hooters' Location	N/A	N/A		N/A
8	MOEFA	Require	d Provide	d	MR
9	Public Address System.	Require			MR
10	Automatic Sprinkler System.				- CONT. (7/2)
	Basement	Required	Provided		MR
	Upper Floor	N/A	N/A		N/A
	 Sprinkler above false ceiling 	N/A	N/A		N/A
11	Internal Hydrants	1 1 1 1 1 1 1			13/23
	Size of riser/down-comer	N/A	80 mm provided	1	N/A
	 Number of hydrants per floor 	N/A	01 No.		N/A
	Hose Box	N/A	01 No.		N/A
12	Yard Hydrants.		0,,,,,	_	1471
	Total number of hydrants	N/A	N/A		N/A
	Hose Box	N/A	N/A		N/A
13	Pumping Arrangements.		W 100 51		*******
	Ground Level		4	-	1001 1001
	 Discharge of main Pump 	N/A	N/A	N	/A
	 Head of Main pump 	N/A	N/A	N.	/A
	Number of main pumps	N/A	N/A	N/	/A
	Jockey Pump out put	N/A	N/A	N/	'A
	 Jockey pump head 	N/A	N/A	N/	Α
	 Standby Pump out put 	N/A	N/A	N/	
	 Standby Pump Head 	N/A			
	 Auto Starting/ Manual 		N/A	N/	
	stopping	N/A	N/A	N/	A
	Pump House Access	N/A	N/A	N/.	A
	Terrace level		/j' .		
	 Discharge of pump 	450 LPM	450 LPM	MI	2
	 Head of the pump 	40 mts each	40 mts	MI	
	- Power Supply	Required	Provided	MF	2
	 Auto Starting of pump 	Required	Provided	MF	
4	Captive Water Storage for fire fighting				
	Underground tank capacity	N/A	N/A	N/A	
	 Draw-off connection 	N/A	N/A	N/A	\
	Fire service inlet	N/A	N/A	N/A	
	Access to tank	N/A			
	Overhead Tank capacity	10,000 lts	N/A Provided (10,000 lts)	N/A MR	
_		CONTRACTOR OF THE PARTY OF THE			
5	Exit Signage. Provision of Lifts.	Required	Provided	MR	

1	N-10						
	 Pressurization of Lift Shaft 	N/A	N/A	N/A			
	 Pressurization of Lift lobby 	N/A	N/A	N/A			
	 Communication In lift Car 	Required	Provided	MR			
	 Fireman's Grounding Switch 	Required	Provided	MR			
	Lift Signage	Required	Provided	MR			
17	Standby power supply	Required	Provided	MR			
18	Refuge Area.						
	- Total Area	N/A	N/A	N/A			
	- Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	Two ABC type fire extinguisher found provided near elect. panel	MR			

The fire protection systems provided in the building were checked at random and found satisfactory at the time of inspection.

Note:- Owner/Occupier has submitted an affidavit that we will not use any type of occupancy above 3rd floor, Fire Curtain provided in basement staircases. (Undertaking placed at C-60).

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter F.6/DFS/MS/GH/SZ/2020/75 dated 25.02.2020, renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Accordingly, DFA is put up for approval & signature please.

Name of the Inspecting officer P.V. Rathee

Asstt. Div. Officer (SRD)

26/ 11

27 61 2029

Sineeta Mg

2 T P4

Anysoy