

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/Mercantile/2023/SZ/326

Dated: 07/07/2023

FIRE SAFETY CERTIFICATE

Certified that the Local Shopping Complex located at Plot No 1 to 7, Lado Sarai, New Delhi 110030 comprised of 02 Tire Basement, Ground plus Three upper floors owned/occupied by Three owners (P.M Overseas Pvt Ltd, Hotel Hans Pvt Ltd & Prominent Developers Pvt Ltd) was issued FSC by this department vide letter no. F6/MS/DFS/2004/1697 dated 03/08/2004 for Plot No 1, 2 & 3 and F6/MS/DFS/2004/1698 dated 03/08/2004 of Plot No 4, 5, & 6 & F6/MS/DFS/1204/1699 dated 03/08/2004 for Plot No 7. The premise was re-inspected by the officers concerned of this department on 04/07/2023 in the presence of Mr. Veer (Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy Class (Mercantile Building) with effect from 07/07/2023 for period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Rules 2010.

Issued on <u>07 107 /</u>2023 at New

DIKEÇTOR DELHI FIRE SERVICE

Copy to: -

- 1. P.M Overseas Pvt Ltd, Hotel Hans Pvt Ltd & Prominent Developers Pvt Ltd, Shopping Complex located at Plot No 1 to 7, Lado Sarai, New Delhi 110030
- 2. The Joint Commissioner of Police, Lic Branch 1st Floor, PS Defence Colony, New Delhi-110049
- 3. Dy. Director (Bldg) C & I Central Unit Building Section, DDA, Vikas Sadan, INA New Delhi

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. The basements shall be used as per the provisions of UBBL-2016/NBC.
- 4. All the staff members must know the correct method of operation of fire fighting system.
- This fire safety certificate may not be treated as regularization (Clause 2.8 of UBBL-2016)
 of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' provided in the First schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."





1	INSPECT	TON REPORT		अल्सद	
T	Name & Address of the Building	Local Shopping	2		
		Local Shopping Complex located at Plot No 1 to 7, Lado Sarai, New Delhi 110030			
2	Type of Occupancy	Mercantile Building			
3	Building Comprised of	02 tire Basement, Ground plus 03 Upper Floor			
4	Type of Case	Renewal Cround plus 03 Upper Floor			
5					
	THE REAL PROPERTY AND ADDRESS OF THE PERSON	F6/MS/DFS/2004/1697 dated 03/08/2004 for Plot No 1,2 & 3 and F6/MS/DFS/2004/1698 dated 03/08/2004			
	7 No. 1	01 FIOL NO 4, 3, & 6 & F6/MS/DFS/1204/1600 1			
		05/00/2004 IOF Prominent Developers Ded Las			
6	Fire \$afety Directives Letter No	FO/MS/DFS//BP/2	000/769 dated 25/04/2000	Con Dian NI	
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1,2 & 3 and F6/MS/DFS/BP/2000/770 dated			
	today.	F6/MS/DFS/BP/2000/771 dated 25/04/2000 for			
	to min				
7	Date of Inspection	Prominent Developers Pvt Ltd			
8	Name of the Inspecting Officers	04/07/2023			
9	Name & Designation of Officers	DO (SD) & ADO (BCP)			
-	from the building side	Mr. Veer (Manager			
10	Year of construction	2000			
11	Applicant letter No.	Gmail dated 08/06/2023			
S.	Minimum standards on Fire Prevention and	As per old NOC	Provided at Site		
No.	Fire Safety U/R 33	Requirements	Provided at Site	Remarks	
1	Access to Building.	requirements	CONTRACTOR OF THE STATE OF THE	MR/NMR	
	Road width	Required	60 mtr	MR	
	Gate width	Required	06 mtr	MR	
	Width of internal road	Required	06 mtr	MR	
2	Number, width, type & arrangement of exits.	required	oo mu	IVIK	
	Number of Staircase				
	Upper floors.	02 mtr	Provided	MR	
	Basement floor.	02 + 02 ramp	Provided	MR	
	Width of Staircase		A SHIP TO SHIP	IVIK	
	Upper floors	1.50m each	Provided	MR	
	Basement floor	1.50m & 2 mtr	Provided	MR	
	Protection of exits	0 1 2	Mark The Inches	TVLIC .	
	Fire check door	Required	Provided	MR	
	Pressurization	N/A	N/A	N/A	
	No. of continuous staircase to terrace	02 Nos	Provided	MR	
	Width of corridor	N/A	N/A	N/A	
	Door size	Required	Provided	MR	
3	Compartmentation.		0.000	IVIIC	
	Fire check door.	Required	Provided	MR	
	Sealing of electrical shafts.	Required	Provided	MR	
	Fire rating of shaft door.	Required	Provided	MR	
	Water curtain	Required	Provided	MR	
	Fire dampers.	Required	Provided	MR	
1	Smoke Management system.			IVIX	
	Basement	30 ACPH	Mechanical	MR	
	Upper floors	12 ACPH	Natural	MR	
5	Fire Extinguishers.	1.0		IVIIC	
	Total numbers	Required	54 Nos	MR	
	Types	ABC/CO ₂	ABC & CO ₂	MR	
	ISI Marking	Required	Provided	MR	
5	First Aid Hose Reels.		1 - 10 II OF III I	IVIIC	
	Total numbers on each floor.	Doguin. 1	Audi - Both side of Screen	1.	
	Length of hose-reel hose. Nozzle Diameter	Required	Bt2 No & 01 at each floor	MR	
		30m	Provided	MR	
_	Difflings	5mm	Provided	MR	
Š	Automatic fire detection & alarming system.	100	A PART OF PROPERTY	-	
	Type of detectors	Smoke / Heat & Beam	The second secon		

m

1/12	
h ,	

	4/		आ	ज़ादी क
_				ज़ादी का अमृत महोत्स
-	Location of Main Panel	Required	Provided	MR
All II	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	Required	Provided	MR
-	Hooter's location	Required	Provided	. MR
8	MOEFA	Required	Provided	MR
9	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System	Z91		- IVIIC
10 3	Basement	Required	Provided	MR
SIND	Upper floor	Required	Provided	MR
11	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.	6 T		NAME OF TAXABLE PARTY.
APRILL A	Size of Riser/Down-comer	Required	Provided	MR
n "	Number of Hydrant per floor Hose box.	Required	Provided	MR
12		Required	Provided	MR
12	Yard Hydrants.			
	Total number of hydrants.	Required	Provided	MR
13	Hose box.	Required	Provided	MR
13	Pumping arrangements.		TOTAL DESIGNATION	201
	Ground Level		to Tree	THE RESERVE
	Discharge of main pump.	2850 LPM	Provided	MR
	Head of main pump.	70m	Provided	MR
	Number of main pumps.	01 No	Provided	MR
	Jockey Pump output. Jockey Pump head.	180 LPM	Provided	MR
	Standby Pump output.	70m	Provided	MR
	Standby Pump head.	2850 LPM	Provided	MR
	Auto Starting/Manual Stopping.	70m	Provided	MR
	Pump house access.	Required	Provided	MR
	2.700 a	Required	Provided	MR
	Terrace Level		Part Date A	21963
	Discharge of pump. Head of pump.	450 LPM	Provided	MR
	Power supply.	39 m	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.	Required	Provided	MR
	Underground tank capacity.	25 000 1	Ta III	The state of the s
	Draw-off connection.	25,000 ltr	Provided	MR
	Fire Service Inlet.	Required	Provided Provided	MR
	Access to tank.	Required Required	Provided	MR
	Overhead tank capacity.	50,000 ltr	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	Required	Flovided	MR
	Pressurization of lift shaft.	Required	Provided	Lym
	Pressurization of lift lobby.	Required	Provided	MR
	Communication in lift car.	Required	Provided	MR
	Fireman's switch.	Required	Provided	MR
	Lift signage.	Required	Provided	MR
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area	Loquitou	2.071000	MR
1	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A N/A
19	Fire Control Room.		1.111	IN/A
A	Detector system panel.	N/A	N/A	N/A
1	Flow switch panel.	N/A	N/A	N/A N/A
	PA system panel.	N/A	N/A	N/A N/A
	Battery backup.	N/A	N/A	N/A N/A
	D 71 0 1			
	Building floor plan.	N/A	I N/A	NI/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A Required	N/A Provided	N/A MR

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/MS/DFS/2004/1697 dated 03/08/2004 for Plot No 1,2 & 3 and F6/MS/DFS/2004/1698 dated 03/08/2004 of Plot No 4, 5, & 6 & F6/MS/DFS/1204/1699 dated 03/08/2004 for Prominent Developers Pvt Ltd, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer

Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)

CFO (HQ)

e synature of . I letter in forthe for