6-29



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No. F.6/DFS/MS/EH/2023/SZ/2/6

Dated. 19.17.12023

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s Monsoon located at R-4, LGF, Ground Floor, Worldmark-1, Aerocity, New Delhi 110037 in the building comprised of 3B + Mezz. + Ground plus 06 Upper floors owned/occupied by The Melting Pot Food Company have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of this department on 30/06/2023 on in the presence of Mr. Prem and that the premise is fit for occupancy class Group-D Assembly Building (Restaurant at Ground Floor only) and validity upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 10 107/2023 at New Delhi by

DELHI FIRE SERV

Copy to: =

1. The Dy. Health Officer, Public Health Department, MCD, Dhasa Bus Stand, Najafgarh Delhi 110043 (Ref. MHA Portal ID 2023061711098 dated 17/06/2023)

Conditions for the validity of Fire Safety Certificate: -

All the means of escape/entry/exit shall be kept free from any obstruction.

All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

All the staff members must know the correct method of operation of fire fighting

The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016),

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

INSPECTION REPORT

1. Name & address of the building: M/s Monsoon (The Melting Pot Food Company), R-4, LGF, Ground Floor, Worldmark-1, Aerocity, Delhi-37.

Type of Occupancy : Assembly (E/H)

Type of Case : New Details of previous NOC : Nil

Fire Safety directives Letter No.: NBC (Part-IV) Date of inspection : 30/06/2023 Name of the Inspecting Officer : D.O. (South)

Name and designation of Officer

from the building side : Mr. Prem Year of Construction : 2015

0. Applica

S No	Minimum standards on fire prevention and fire safety U/R 33	NBC Requirements	Provided at site	Remarks MR/NM R				
1.	Access of building FSC F6/DFS/MS/Mixed/SZ/2021/09 dated 08/03/2021							
	Road width	6 mtr	6 mtr	MR				
	Gate width	N/A	N/A	N/A				
	Width of internal road	N/A	N/A	N/A				
2.	Number, width, Type & Arrangements of exits							
	a. Number of staircases	. 5 20	en hard to goding!	n				
	Upper floors	N/A	N/A	N/A				
	Basements	N/A	N/A	N/A				
	b. Width of staircases			Thu / T				
	Upper floors	N/A	N/A	N/A				
	Basements	N/A	N/A	N/A				
	c. Protection of exits	V/45	- viidlisii	4				
	Fire check door	N/A	N/A	N/A				
	Pressurization	N/A	N/A	N/A				
	d. No of continuous staircase to terrace	N/A	N/A	N/A				
	e. Width Of Corridor	N/A	N/A	N/A				
	f. Door Size	1.50mtr x 2	1.50 mtr each	MR /				
3.	Compartmentation	P 10 1 1						
	Fire check door	N/A	N/A	N/A				
	 Sealing of electrical shafts 	N/A	N/A	N/A				
	 Fire Rating of shaft door 	N/A	N/A	N/A				
	Water Curtain	N/A	N/A	N/A				
	Fire Dampers	N/A	N/A	N/A				
4.	Smoke managements System	6301034	position and	Interior -				
	Basements	N/A	N/A	N/A				
	Ground Floor	Required	Provided	MR				
5.	Fire Extinguishers	La page and						
	Total numbers	2	2	M/R				
	Types	ISI marked ABC/CO ₂	Provided	M/R				
	IS marking	Required	Provided	M/R				
	Tight 2		d seed of second					

б.	First – Aid Hose Reels	1	F	Provid	ed by Worldmark	manageme	ent	
-	Total numbers on			Provi	Provided			
	each floor							
	 Length of hose reel hose 	30 N	itr.	Provi	ided Av	MR	y jż.	
	Nozzle diameter	5 mm		Provided		MR	Maria India	
	Automatic fire detection and alarming system							
	Type of detector		N/A		N/A	N/A		
	Location of Main Panel		N/A		N/A	N/A		
	Location of Repeater Panel		N/A		N/A	N/A		
	Alternate source of power		N/A		N/A	N/A		
		Hooters' Location			N/A	N/A		
	W COURS CONTRACTOR OF THE CONT		Required		Provided	MR		
8.	MOEFA		N/A		N/A	N/A	R.	
9.	Public Address System		N/P	5	ypatry well time	A Idmines	ric h	
0.	Automatic Sprinkler System	101/0	HIJES		Provided	N/A		
	Ground Floor	N/A	31	101	N/A	N/A	No. 7	
1	Upper Floor	N/A	(%)		N/A N/A	N/A		
	 Sprinkler above false 	N/A			N/A	IV/A		
	ceiling	(Provided by Worldm		ided by Maridman	k manage	ment)		
1.	Internal Hydrants		1	-	Provided	r manage	MR	
T	 Size of riser/down- cor 	omer		0 mm	Provided	milk is	MR	
	 Number of hydrants per floor 		1		Provided		.viix	
1-	Hose Box	1		1	Provided	- Ph.	MR	
2.	Yard Hydrants							
۷.	Total number of	N/A		1	N/A	N/A		
	hydrants	1.4			1 5 talk	m)13		
	Hose Box	N/A		N/A	N/A			
3.	Pumping Arrangements			(Provi	ded by World mai	rk manage	ement)	
J	Ground Level			7	a grant the	STATE OF		
100.00	Discharge of main pump	N/A			N/A	N/A		
197	Head of main pump	N/A			N/A	N/A		
	Number of main pumps	N/A	_		N/A	N/A		
<u> </u>		N/A	/A		N/A	N/A		
100	Jockey pump head	N/A		* 1	N/A	N/A		
A		N/A			N/A	N/A	(
	Standby Pump Head	N/A			N/A	N/A	\	
>	Auto Staring/Manual	N/A			N/A	N/A	1	
	stopping				real party to square	77		
A	Pump House Access	N/A			N/A	N/A	\	
•	Terrace level		-	*				
	Discharge of pump	450	LPM	F	Provided	MR	Marian III	
	Head of the pump	40 N	ITR	F	Provided	MR	03	
	Power supply	1 3 3 X X X X	uired		Provided	MR	d)	
1	Auto starting of pump		uired		Provided	MR		
	Captive water Storage for firefighting (Provided by World mark management)						on+)	
14.					ACT CHICAGO CONTRACTOR			
	 Underground tank capacity 	N/A		N/A		N/A		
	> Draw of connection	N/A		N/A		N/A		
	>							
	Fire service inlet	N/A		N/A!		N/A	N/A	
	N	NI/A		N/A		N/A		
	Access to tank	N/A			N/A	14/4	•	

15	Exit Signage	N/A	N/A	N/A
16.	Provision of Lifts			
	Pressurization of Lift Shaft	N/A	N/A	N/A
	 Pressurization of lift lobby 	N/A	N/A .	N/A
	Car	N/A	N/A	N/A
	> Fireman's Grounding Switch	N/A	N/A	N/A
	➤ Lift Signage	N/A	N/A	N/A
17		N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	
18.	Refuge Area	N/A	N/A	N/A
	> Total area > Location	N/A	N/A	N/A
10	Fire control room			
19.	> Detector system panel	N/A	N/A	N/A
	> Flow Switch Panel	N/A	N/A	N/A
	> PA System Panel	N/A	N/A	N/A
		N/A	N/A	N/A
	➤ Battery backup	N/A	N/A	N/A
	➤ Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of special Risks, if any;	11/2		

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 251 dated 24/06/2021.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Signature of the Inspecting Officer
Name: Sh. M.K Sharma

Designation: DO (South)

t)

Diverto 1

COLLY

FTP1)

DO/ Suth

MILL