



No.F6/DFS/MS/School/NDZ/2023/473

Dated: 13/07/2023

FIRE SAFETY CERTIFICATE

Certified that the Mayur Mordern Public School locted at Ch. Todar Mal Marg, St. No.4/6, Karawal Nagar Extn., Rama Garden, Delhi-110094, building comprised of Ground floor Only, owned / occupied by Mayur Mordern Public School, was issued FSC vide letter No. F6/DFS/MS/School/2018/NDZ/1832 dated - 07/08/18. The School building was re-inspected by the officer concerned of this department on 04/07/2023 in presence of Mrs. Neeru Choudhary (Principal) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with D.O.E circular No. F16/Estate/CC/Fire Safety/2011/3298 to 3398 Dated- 01/03/11and that the building is fit for occupancy class "Educational" (Group-B) with effect from 13/07/2023 for a period of (three years) in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 13/07/2023 at New Delhi by.


(ATUL GARG)
DIRECTOR

Copy to:-

1. The Principal, Mayur Mordern Public School, Ch. Todar Mal Marg, St. No.4/6, Karawal Nagar Extn., Rama Garden, Delhi-110094.
2. The Dy. Director of Education, EDMC, Udyog Sadan, Plot No.419, FIE, Patparganj Industrial Area, Delhi-110092.

Conditions for the validity of Fire Safety Certificate

1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
2. All the means of escape shall be kept free of all the type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1	Name & address of the building	Mayur Mordern Public School Ch. Todar Mal Marg, St. No.4/6, Karawal Nagar Extn., Rama Garden, Delhi-110094.				
2	Building is comprised of	Ground floor Only				
3	Type of occupancy	Educational Building				
4	Type of case	Renewal				
5	Details of previous FSC	F6/DFS/MS/School/2018/NDZ/1832 dated 07/08/18				
6	Fire safety directives letter no.	F16/Estate/CC/Fire Safety/2011/3298 to 3398 Dated 01/03/11				
7	Date of inspection	04/07/2023				
8	Name of the inspecting officers	Yashwant Singh Meena, ADO (L.N)				
9	Name of the designation of officer from the building side	Mrs. Neeru Choudhary (Principal)				
10	Year of construction	2005				
11	Applicant's letter no.	Email Dated-20/06/2023				
S.No	Minimum standard of fire prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR		
1	Access to Building:					
	A	Road width	06 mtrs.	06 mtrs.	MR	
	B	Gate width	NA	NA	NA	
	C	Width of internal road	NA	NA	NA	
2	Number, Width, Type and Arrangement of Exits:					
	A	Number of staircases				
		a	Upper floor	NA	NA	NA
		b	Basement	NA	NA	NA
	B	Width of staircases				
		a	Upper floor	NA	NA	NA
		b	Basement	NA	NA	NA
	C	Protection of exits				
		a	Fire check door	NA	NA	NA
		b	Pressurization	NA	NA	NA
	D	No. of continuous staircases to terrace				
	E	Width of corridor				
	F	Door size				
			01 mtrs	01 mtrs	MR	
3	Compartmentation:					
	A	Fire check door				
	B	Sealing of electrical shafts				
	C	Fire rating of shaft door				
	D	Water curtain				
	E	Fire dampers				
4	Smoke Management System:					
	A	Basement				
	B	Upper floor				


5.	Fire Extinguisher:				
	A	Total numbers	02 nos.	06 nos.	MR
	B	Types	ABC&CO ₂	ABC&CO ₂	MR
	C	ISI marking	ISI Marked	ISI Marked	MR
6	First-Aid-Hose Reel:				
	A	Total numbers of each floor	NA	NA	NA
	B	Length of hose reel hose	NA	NA	NA
	C	Nozzle diameter	NA	NA	NA
7	Automatic Fire Detection and Alarming System:				
	A	Type of detectors	NA	NA	NA
	B	Location of main panel	NA	NA	NA
	C	Location of repeater panel	NA	NA	NA
	D	Alternate source of power	NA	NA	NA
	E	Hooters	NA	NA	NA
8	MOEFA:		NA	NA	NA
9	Public Address System:		NA	NA	NA
10	Automatic Sprinkler System:				
	A	Basement	NA	NA	NA
	B	Upper floor	NA	NA	NA
	C	Sprinkler above false ceiling	NA	NA	NA
11	Internal Hydrants:				
	A	Size of riser/down-comer	NA	NA	NA
	B	Number of hydrants per floor	NA	NA	NA
	C	Hose box	NA	NA	NA
12	Yard Hydrants:				
	A	Total number of hydrants	NA	NA	NA
	B	Hose box	NA	NA	NA
13	Pumping Arrangements:				
1	Ground level		NA	NA	NA
	A	Discharge of main pump	NA	NA	NA
	B	Head of main pump	NA	NA	NA
	C	Number of main pumps	NA	NA	NA
	D	Jockey pump out put	NA	NA	NA
	E	Jockey pump head	NA	NA	NA
	F	Standby pump out put	NA	NA	NA
	G	Standby pump head	NA	NA	NA
	H	Auto starting /manual stopping	NA	NA	NA
	I	Pump house access	NA	NA	NA
2	Terrace Level				
	A	Discharge of pump	NA	NA	NA
	B	Head of the pump	NA	NA	NA
	C	Power supply	NA	NA	NA
	D	Auto starting of pump	NA	NA	NA





W X 90/

14	Captive Water Storage for Fire Fighting:			
	A	Underground tank capacity	NA	NA
	B	Draw-off connection	NA	NA
	C	Fire service inlet	NA	NA
	D	Access to tank	NA	NA
	E	Overhead tank capacity	NA	NA
15	Exit Signage:			
16	Provision of Lifts:			
	A	Pressurization of lift shaft	NA	NA
	B	Pressurization of lift lobby	NA	NA
	C	Communication in lift car	NA	NA
	D	Firemen's grounding switch	NA	NA
	E	Lift signage	NA	NA
17	Standby Power Supply:			
18	Refuge Area:			
	A	Total area	NA	NA
	B	Location	NA	NA
19	Fire Control Room:			
	A	Detector system panel	NA	NA
	B	Flow switch panel	NA	NA
	C	PA system panel	NA	NA
	D	Battery backup	NA	NA
	E	Building floor plans	NA	NA
20	Special Fire Protection systems for protection of special Risks, if any:			

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education Circular no.F16/Estate/CC/Fire Safety/2011/3298 to 3398 Dated- 01/03/11 the FSC issued vide letter no. F6/DFS/MS/School/2018/NDZ/1832 dated 07.08.2018 is recommended to be renewed.


5/7/2023
Signature of the Inspecting Officer
Name: Yashwant Singh Meena
Designation : ADO (L.N)

~~D.O. (ED)~~ 
05/07/2023
DY. C.F.O. / CA/23 
C.F.O. 
6/7/2023
Director/ED 
07/12
AOD/LN