

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2023/SZ/222

Dated: 12/07/2023

FIRE SAFETY CERTIFICATE

West Wing, Upper Ground Floor, TDI South Bridge, Nehru Place Metro Station, Nehru Place, New Delhi-110019 in the building comprised of Basement, Lower Ground Floor & Upper Ground Floor owned/occupied by A unit of Nando's Karnataka Restaurants Pvt. Ltd was issued FSC by this department vide letter No. F6/DFS/MS/2020/SZ/157 dated 05/11/2020. The premise was re-inspected by the officer concerned of this department on 06/07/2023 in the presence of Mr. Sameer and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Assembly Group-D" (Eating House) and validity upto 31/03/2026 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 as below.

Issued on 12 07/2023 at New Delhi by

(APUL GARG)

DELHI FIRE SERVICE

Copy to: -

1. The Joint C.P. (Licensing), First Floor, Police Station Defence Colony, New Delhi-110049

2. The Dy. Health Officer, South MCD, Public Health Department, Central Zone, Lajpat Nagar, New Delhi-110024 (Ref. MHA Portal ID 2023061510961 dated 14/06/2023)

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. The basement shall be used strictly in accordance with BBL.
- 4. All the staff members must know the correct method of operation of fire fighting system.
- 5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

W 110

	INSPEC	TION REPORT	// 5) ==				
1	Name & Address of the Building	M/s NANDOS A Unit of Nandos Karnataka Restauran Pvt Ltd) Outlet J West Wing, Upper Ground Floor Epicuria TDI South Bridge, Nehru place Metro Station New Delhi 110019					
	A Charles of the second of the						
Plan	tenant. Is not						
2	Type of Occupancy	Group D Assembly D '11' To a					
3	Building Comprised of	Group-D Assembly Building, Eating house at UGF only					
4	Type of Case	Basement, Lower ground floor & upper ground floor Renewal					
5	Details of Previous NOC						
6	Fire Safety Directives Letter No	F6/DFS/MS/2020/SZ/157 dated 05/11/2020					
7	Date of Inspection	F6/DFS/MS/2022/SZ/434 dated 29/09/2022 (Mall NOC) 06/07/2023					
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)					
9	Name & Designation of Officers	Mr. Sameer					
12	from the building side	Wit. Sallice					
10	Year of construction	2009					
11	Applicant letter No.		0023061510061 dated 14	106/2022			
		MHA Portal ID 2023061510961 dated 14/06/2023					
S. No.	Minimum standards on Fire Prevention	Old NOC	Provided at Site	Remarks			
	and Fire Safety U/R 33	Requirements	- TO THAT BY	MR/NMR			
1	Access to Building.	Mall Noc F6/DFS/MS/2022/SZ/434 dated 29/09/2022					
	Road width	10.3	The second second				
	Gate width	30 mtr 6 mtr	Provided*	MR			
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	6 mtr	Provided*	MR			
	Width of internal road		Provided*	MR			
2	Number, width, type & arrangement of ex	its.	The second second				
M.	The state of the s						
	a) Number of Staircase						
	> Upper floors.	02 Nos	04 Provided*	MR			
	Basement floor.	02 Nos					
	b) Width of Staircase		Provided & Maintained by Mall				
	> Upper floors	1.50 mtr	1.80 mtr each	MR			
	> Basement floor	1.50 mtr	1.80 mtr each MR				
	c) Protection of exits		vided & Maintained by				
ind Ind	Fire check door	Required	Provided*	MR			
	> Pressurization	Required	Provided*	MR			
	d) No. of continuous staircase to terrace	Required	Provided*	MR			
	e) Width of corridor	Required	Provided*	MR			
	f) Door size	2m	2.3m, 2m & 2m	MR			
3	Compartmentation.	Provid	Provided & Maintained by TDI Mall				
3	The state of the s	The second secon					
	Fire check door.	Required	Provided*	MR			
y 11	Sealing of electrical shafts.	Required	Provided*	MR			
del	Fire rating of shaft door.	Required	Provided*	MR			
10	Water curtain	N/A	N/A	N/A			
	Fire dampers.		1771				
4	Smoke Management system.	Provided & Maintained by Mall					
	Basement	30 ACPH	Provided*	MR			
	Upper floors	12 ACPH	Provided*	MR			
5	Fire Extinguishers.		Signed to most with the				
5	A STATE OF THE PARTY OF THE PAR	OCNI-	10 No.	MD			
	Total numbers	06 Nos	10 Nos	MR MR			
	Types	ABC/CO ₂	ABC-07 & CO ₂ -03				
4 - 1	ISI Marking	ISI marked	Provided MR				
6	First Aid Hose Reels.		ded & Maintained by TI				
-	Total numbers on each floor.	01 near restt.	Provided*	MR			
. 1	Length of hose-reel hose.	30m	Provided*	MR			
	Nozzle Diameter	5mm	Provided*	MR			
4	The state of the s		the state of the s	MIX			
7	Automatic fire detection & alarming system	m. Provided & Ma	aintained by Mall				
	Type of detectors	N/A	Provided*	MR			
	Location of Main Panel	N/A	Provided*	MR			
			Provided* MR				
- 1	 Location of Repeater Panel 	Required	D11-10	MD			





500	The same of the sa		आजाही			
	the deciment he will be sent and		अमृत	ा महोत्सव महोत्सव		
	Alternate source of power	Required	Provided*	100		
	Hooter's location	Required	Provided*	M		
8	MOEFA	Required	Provided	M		
9	Public Address System	N/A	N/A	M		
10	Automatic Sprinkler System			N/A		
000	Basement	Required	Provided*	TDI Mall		
	Ground floor.	Required	Provided*	MI		
	Sprinkler above false ceiling	Required	Provided*	MI		
11	Internal Hydrants.	1111				
	Size of Riser/Down-comer	Provided & Maintained by Mall Required Provided* MR				
	Number of Hydrant per floor	Required		MF		
	Hose box.		Provided*	MF		
12	Yard Hydrants.	Required	Provided*	MR		
13	Total number of hydrants.	Damin 1	D 11.14			
	Hose box.	Required	Provided*	MR		
	Pumping arrangements.	Required	Provided*	MR		
	Ground Level					
	Discharge of main pump.	Provided & Maintained by Mall				
	Head of main pump.	2280 LPM	Provided*	MR		
	Number of main pumps.	70 m	Provided*	MR		
	> Jockey Pump output.	02	Provided*	MR		
	> Jockey Pump head.	280 &180 LPM	Provided*	MR		
	Standby Pump output.	70 m	Provided*	MR		
	> Standby Pump head.	2280 LPM	Provided*	MR		
	Auto Starting/Manual Stopping.	70 m	Provided*	MR		
	> Pump house access.	Required	Provided*	MR		
	Terrace Level	Required	Provided*	MR		
	Discharge of pump.	N/A	27/4	27/4		
ji.	> Head of pump.	N/A N/A	N/A	N/A		
	Power supply.	N/A	N/A N/A	N/A		
	Auto starting of pump.	N/A	N/A N/A	N/A		
14	Captive water storage for fire fighting.		led & Maintained by	N/A		
	Underground tank capacity.	1,00,000 ltr	Provided*	MR		
	> Draw-off connection.	Required	Provided*	MR		
	Fire Service Inlet.	Required	Provided*	MR		
	> Access to tank.	Required	Provided*	MR		
	Overhead tank capacity.	10,000 ltr	Provided*	MR		
	Exit Signage.	Required	Provided	MR		
15	Provision of Lifts.	Provided & Maintained by Mall				
15 16	Pressurization of lift shaft.	N/A N/A N/A				
		N/A	N/A	N/A		
	 Pressurization of lift lobby. 					
	 Pressurization of lift lobby. Communication in lift car. 	N/A	N/A	N/A		
	. I	N/A N/A	N/A N/A			
	Communication in lift car.			N/A		
	Communication in lift car. Fireman's switch.	N/A N/A	N/A N/A	N/A N/A		
16	 Communication in lift car. Fireman's switch. Lift signage. 	N/A	N/A	N/A N/A		
16	 Communication in lift car. Fireman's switch. Lift signage. Standby Power Supply	N/A N/A	N/A N/A Provided	N/A N/A MR		
16	Communication in lift car. Fireman's switch. Lift signage. Standby Power Supply Refuge Area	N/A N/A Required	N/A N/A Provided	N/A N/A MR		
16	Communication in lift car. Fireman's switch. Lift signage. Standby Power Supply Refuge Area Total area	N/A N/A Required N/A N/A	N/A N/A Provided N/A N/A	N/A N/A MR N/A N/A		
16 17 18	Communication in lift car. Fireman's switch. Lift signage. Standby Power Supply Refuge Area Total area Location Fire Control Room.	N/A N/A Required N/A N/A Provid	N/A N/A Provided N/A N/A N/A ed & Maintained by	N/A N/A MR N/A N/A Mall		
16 17 18	Communication in lift car. Fireman's switch. Lift signage. Standby Power Supply Refuge Area Total area Location Fire Control Room. Detector system panel.	N/A N/A Required N/A N/A Provid Required	N/A N/A Provided N/A N/A N/A ed & Maintained by Provided*	N/A N/A MR N/A N/A Mall		
16 17 18	Communication in lift car. Fireman's switch. Lift signage. Standby Power Supply Refuge Area Total area Location Fire Control Room. Detector system panel. Flow switch panel.	N/A N/A Required N/A N/A Provid Required Required	N/A N/A Provided N/A N/A N/A ed & Maintained by Provided* Provided*	N/A N/A MR N/A N/A Mall MR		
16 17 18	Communication in lift car. Fireman's switch. Lift signage. Standby Power Supply Refuge Area Total area Location Fire Control Room. Detector system panel. Flow switch panel. PA system panel.	N/A N/A Required N/A N/A Provid Required Required Required Required	N/A N/A Provided N/A N/A N/A ed & Maintained by Provided* Provided* Provided*	N/A N/A MR N/A N/A Mall MR MR		
16 17 18	Communication in lift car. Fireman's switch. Lift signage. Standby Power Supply Refuge Area Total area Location Fire Control Room. Detector system panel. Flow switch panel. PA system panel. Battery backup.	N/A N/A Required N/A N/A Provid Required Required Required Required Required	N/A N/A Provided N/A N/A ed & Maintained by Provided* Provided* Provided* Provided*	N/A N/A MR N/A N/A N/A Mall MR MR MR MR		
16 17 18	Communication in lift car. Fireman's switch. Lift signage. Standby Power Supply Refuge Area Total area Location Fire Control Room. Detector system panel. Flow switch panel. PA system panel.	N/A N/A Required N/A N/A Provid Required Required Required Required	N/A N/A Provided N/A N/A N/A ed & Maintained by Provided* Provided* Provided*	MR		



Note: - * Provided & Maintained by Epicuria, TDI Mall Nehru place Metro Station, New Delhi 110019.

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/2020/SZ/157 dated 05/11/2020, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer

Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP

CFO (HQ)

As opporound, F.T. better in pontrip for four signature Pl