

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

गानादी अमृत महोजन

No. F6/DFS/MS/School/WZ/2023/ 468

Dated: 11/07/2023

FIRE SAFETY CERTIFICATE

Colony, Nangloi, New Delhi-110041, comprised of Ground + 01 Upper Floor only owned/occupied by Nigam Prathmik Vidyalaya, was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/School/2020/148 Dated 09.04.2020. The said premise was re-inspected by the officer concerned of this department on 27.06.2023 in the presence of Ms. Nirmala (Principal) and found that the premises / building have deemed complied with the fire prevention and fire safety requirements in accordance D.O.E., GNCT of Delhi, Circular no.3298-3398 dated 01-03-2011 and that the premises/building is fit for occupancy class "Educational Building" Group B with effect from 11/07/2023 for a period of three years, subject to compliance of the conditions, printed below.

Delhi Fire Service

Copy to: -

1. The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi - 110054.

 The Principal, Nigam Prathmik Vidyalaya (Girls), 2/I Located at Camp No. 1, J.J. Colony, Nangloi, New Delhi-110041.

Following fire safety directives must be adhered to:-

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
- Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing Department shall always be permitted and followed.
- The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name and address of the building: Nigam Prathmik Vidyalaya (Girls) 2/I, Located at

Camp No. 1, J.J. Colony, Nangloi, New Delhi-

110041

: Educational (G + 01 Upper Floor only) 2. Type of Occupancy

: Renewal 3. Type of Case

: F6/DFS/MS/School/W7/2020/148 Dated 09.04.2020 4. Details of previous NOC

: D.O.E Circular no.3298-3398 dated 01-03-2011 Fire Safety directives Letter No.

: 27.06.2023 6. Date of inspection

: Aman Kumar Lathar, ADO (JWP) 7. Name of the Inspecting Officer

8. Name and designation of Officer

: Ms. Nirmala (Principal) from the building side

: 2008 Year of Construction

: 309 dated 13.04.2023

S No	Applicant's letter No. : 3 Minimum standards on fire prevention and fire safety U/R 33	D.O.E. Circular No. 3298-3398 Dated 01.03.0211/ as per FSC dated 09.04.2020	Provided at site	Remarks MR/NMR
	Chuilding		Provided	MR
1.	Access of building • Road width	06 m	Provided	MR
-	Gate width	05 m	NA	NA
	Width of internal road	NA		
	Number, width, Type & Arrangem	ents of exits		
2.	a. Number of staircases		02	MR
	a. Number of starredses	01	NA	NA
	Upper floors	NA	NA	
- 1	Basements Width of staircases	12	m x 2	MR(Old Case)
	b. Width of staffcases	1.5 111	NA NA	NA
	 Upper floors Basements Protection of exits Fire check door Pressurization No of continuous 	NΛ	INA	
		= 4:40:11	NA	NA
-1		NA	NΛ	NA
		NΛ	Provided	MR
		01	Provided	
	etaircase to terrace	1.5	Provided	MR
	e. Width Of Corridor	1.5 m	Provided	MR
	f. Door Size	1 m	NA	
-	Compartmentation	NA	NA	NA
3.	Fire check door	NΛ	NΛ	NA
	 Scaling of electrical shafts Fire Rating of shaft door Water Curtain 	NA	NA	NA
		NA	NΛ	NA
		NA	NA NA	NA
		NA	INA	
		A STATE OF THE PARTY OF		
	Fire Dampers Smoke managements System		NA	NA
4	Smoke managements	NA	NΛ	NA
	Basements George	NA	1474	
1	Upper floors		06 nos.	MR
5	Fire Extinguishers	05 nos.	Provided	MR
T	Total numbers Types	ABC & CO ₂ ISI marked	Provided	MR
	TypesISI marking	1SI marked		

			١	1
- 1	~	•	١	٠

6.	First – Aid Hose Reels	1201		
	Total numbers on each floor	NA	NA	N/
	Length of hose reel hose	NA	NA	N/
	Nozzle diameter	NA	NA	N/
7.	Automatic fire detection and alarming sy	vstem		1
	Type of detectors	NA	NA	NA
	Location of Main Panel	NA	NA	NA NA
	Location of Repeater Panel	NA	NA NA	NA NA
	Alternate source of power	NA	NA NA	NA NA
	Hooters' Location	NA	NA	NA
8.	MOEFA	NA		
9.	Public Address System	NA	NA NA	NA
10.	Automatic Sprinkler System	NA .	INA	NA
	Basements	NA	NΛ	NA
	Upper Floor	NA	NA	NA NA
	Sprinkler above false ceiling	NA	NA NA	NA NA
11.	Internal Hydrants:	Tell Editoria	141	INA
	Size of riser/down- comer	NA	NA	NA
	Number of hydrants per floor	NA	NA	NA
	Hose Box	NA	NA	NA
12.	Yard Hydrants			14/1
	 Total number of hydrants 	NA	NA	NA
4	Hose Box	NA	NA	NA
13.	Pumping Arrangements:	The Landson		1471
	Ground Level			-
	Discharge of main pump	NA	NA	NA
	Head of main pump	NA	NA	NA
	Number of main pumps	NA	NA	NA
	> Jockey pump out put	NA	, NA	NA
	> Jockey pump head	NA	NA	NA
	Standby Pump out put	NA	NA	NA
	> Standby Pump Head	NA	NA	NA
	Auto Staring/Manual stopping	NA	NA	NA
	> Pump House Access	50%	CONTRACTOR OF THE	
	Terrace level	NΛ	NA	NA
	> Discharge of pump	N. M. M. C.	2 10 10 10	3 7
	> Head of the pump	NA	NA	NA
	> Power supply	NA	NA	NA
	> Auto starting of pump	NA	NA	NA
1.4		NA	NA	NA
14.	Captive water Storage for fire fighting:	APPENDE	MATERIAL N	
	Under ground tank capacity '	NA	NA	NA
	> Draw off connection	, NA	NA	NA
	Fire service inlet	NA	NA	NA
	Access to tank	NΛ	NA	NA
15	Overhead Tank capacity Evit Signage	NA	NA	NA
15 16.	Exit Signage Provision of Lifts	NA	NA NA	NA
10.				
	> Pressurization of Lift Shaft	NA	NA	NA
	 Pressurization of lift lobby Communication in lift Car 	NA	NA	NA
10	Fireman's Grounding Switch	NΛ	NA	NA
	Lift Signage	NA NA	NA NA	NA NA
	The same of the sa	NA	NA	NA
17.	Standby power supply	NA	NA	NA
10	Refuge Area			111
8.	A Total acce	111	***	
8.	> Total area	NA	NA	NA
8.	➤ Total area ➤ Location	NA NA	NA NA	NA NA

19.	Fire control room			
	> Detector system	NA	NA	NA
	panel	NA	NΛ	NA
	Flow Switch Panel	NΛ	NA	NA
	> PA System Panel	NΛ	NA	NA
	> Battery backup > Building Floor Plans	NΛ	NA	NA
20.	Special Fire Protection Systems for Protection of special Risks, if any;	NΛ	NA	NA

Fire protection systems provided in the building were checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety requirements as per D.O.E. Circular no. 3298-3398 dated 01.03.2011, letter vide issued Certificate Safety Fire of renewal F6/DFS/MS/School/WZ/2020/148 Dated 09.04.2020 is recommended.

Accordingly DFA is put up for approval please.

ADO (JWP)

Su) For John 1)
Su) For letter is added for your signature pl.

\$1114 |
-06107/25

And Gup,