GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELIII FIRE SERVICE: NEW DELHI- 110001

भाजादी न अमृत महोत्सव

No.F6/DFS/MS/Hospital/SZ/2023/340

Dated: 19 07 2023

FIRE SAFETY CERTIFICATE

Issued on...1.9.10.7.1.2.0.2.3...at New Delhi by

thi Fire Service

Copy to:-

- The Medical Superintendent Nursing Home, Directorate of General of Health Services, 3rd floor, DGD Building, S-1, School Block, Shakarpur, New Delhi-92.
- 2. The Owner/Occupier, M/s Artemis Lite (A Unit of Artemis Medicare Services Ltd.), A-1, New Friends Colony, New Delhi-25.

Conditions for the validity of Fire Safety Certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 8. Basement shall be used as per NBC/UBBL.
- Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

N/25

1	Name	& ad	dress of the building	M/s Artemis Lite (A Unit of Artemis Medicare Servi Ltd.), A-1, New Friends Colony, New Delhi-25.				
2	Building is comprised of			Basement + Ground + 03 upper floors				
3	Type of occupancy			Institutional Building Group 'C' Hospital				
4	Type			Renewal				
5	Details of previous FSC Fire safety directive letter no.			F6/DFS/MS/Hospital/2020/SZ/448 dated 03.11.2020 F6/DFS/MS/BP/2013/Hospital/04 dated 02/01/2013				
6								
7	Date of inspection			10.07.2023				
8	Name of the inspecting officers			Manoj Kumar Sharma, DO (SD) & Rajesh Kumar Shukla ADO (M. Road)				
9	-		e designation of officer uilding side	Mr. Shubham Tondon (Divisional Manager, Busines Operation & Development)				
10	Year	of cor	nstruction	2012				
11	Appli	cant's	s letter no	Outdoor Diary No. 2046 dated 17.05.2023				
S.N	o Mir	nimu venti	m Standards on fire	Requirement as per NBC/UBBL	Provided at Site	Remarks MR/NMR		
1	Acc	ess t	o building	J100 1				
	A	Ro	oad width	9.0 mtrs.	12.0 mtrs	MR		
	В	Ga	ate width	5.0 mtrs.	5.0 mtrs	MR		
	C	_	idth of internal road	NA	NA	NA		
2	_	_	, Width, Type and Arran	gement of Exits				
	A	N	lumber of staircases/ramp					
		a	Upper floor	2 nos.	2 nos.	MR		
		Ь	Basement	2 nos.	2 nos.	MR		
	В	a	Width of staircases Upper floor	2.0 mtrs & 1.50 mtrs	2.0 mtrs (Iron) & 1.30 mtrs	MR (Old case)		
		ь	Basement	1.25 mtrs	1.40 mtrs (Iron) & 1.30 mtrs	MR		
	C	C Protection of exits		THE REPORT OF THE PARTY OF THE				
		a	Fire check door	Required in basement	Provided	MR		
	-	b	Pressurization	NA	NA	NA		
	D	17710 07	o. of continuous staircases terrace	2 nos.	2 nos.	MR		
	E		idth of corridor	1.5 mtrs	1.5 mtrs	MR		
	F		or size	1.0 mtrs	1.0 mtrs			
4			rtmentation	1.0 mas	1.0 mus	MR		
	A			Required in basement	Provided	MR		
	В	Sea	ling of electrical shafts	NA	NA	NA		
	C	D Water curtain E Fire dampers		NA	NA	NA		
	D			NA	NA	NA		
				NA	NA	NA		
	Smoke Management System.			(0)				
	A			Mechanical/ Natural	Exhaust fans	MR		
	В	Upp	per floor	Mechanical/ Natural	Exhaust fans	MR		



			inguisher			1 m		
1	A	Total	numbers 1	2 nos.	12 nos.	MR		
	В	Туре		CO ₂ & ABC &WCO ₂	CO ₂ & ABC &WCO ₂	MR		
	C	101		SI marked	ISI marked	MR		
	1500		-unitaring	or manea				
	First-Aid-Hose Reels.			l no.	1 no.	MR		
	A Total numbers of each free.		I Hallious of Cach thes.	30 mtrs	30 mtrs	MR		
	В		gui of nose reel nese			MR		
	C		Lie didilieter	5 mm	5 mm	IVIK		
7	Automatic Fire Detection and Alarming System.							
	A Type of detectors		pe of detectors	Heat & Smoke	Provided	MR		
	В	_	cation of main panel	Ground floor	Provided	MR		
	C		cation of repeater panel	NA .	NA	NA MB		
	D	_	ernate source of power	Required	Provided Provided	MR MR		
	E	Ho	oters	Audible in entire building	Flovided	IVIK		
8	M	OEF	Δ	Required	Provided	MR		
(A)	12,000	STATE OF THE CO.		NA	NA	NA		
9	Public Address System. NA NA NA NA Automatic Sprinkler System.							
10	A		ement	Required	Provided	MR		
	B		per floors	NA	NA	NA		
		554.5		Carrier Ann Carl	J. Zing Settin	NA		
	C	_	inkler above false ceiling	NA	NA	INA		
11	-	The Control Property	l Hydrants	Table 1	1.198.25.01.070	1.45		
	-	A Size of riser		100 mm	Provided	MR		
		B Number of hydrants per floor		1 no.	1 no.	MR		
	C	C Hose Box		1 no.	l no.	MR		
12	Yard Hydrants.							
	A	A Total number of hydrants		NA	NA	NA		
	В	B Hose Box		NA	NA	NA		
13	Pumping Arrangements.							
	A	Gr	ound Level	w	in In			
		a	Discharge of main Pump	1620 LPM	1620 LPM	MR		
		b	Head of Main Pump	60 m	60 m	MR		
		c	Number of main pumps	1 no.	l no.	MR		
		d	Jockey pump out put	180 LPM	180 LPM	MR		
		e	Jockey pump head	60 m	60 m	MR		
		f	Standby pump out put	1620 LPM	1620 LPM	MR		
		g	Standby pump head	60 m	60 m	MR		
		h	Auto starting /manual stopping		Provided	MR		
		i	Pump House Access	Required	Provided	MR		
	B Terrace Level							
		a	Discharge of pump	NA	NA	NA		
		b	Head of the Pump	NA	NA	NA		
		c	Power supply	NA	NA	NA		
		d	Auto Starting of pump	NA	NA	NA		

M/s Artemis Lite (A Unit of Artemis Medicare Services Ltd.), A-1, New Friends Colony, New Delhi-25

4	Cap	tive Water Storage for Fire Fightin	Provided	MR		
	A Underground tank capacity		50,000 Ltrs Required	Provided	MR	
	B	Draw-off connection	Required	Provided	MR	
	C	Fire service inlet	Required	Provided	MR	
	n	Access to tank	10,000 ltrs	10,000 ltrs	MR	
	F	Overhead Tank capacity	Required	Provided	MR	
15	Exit Signage.					
20110	Dravision of Lifts.		TNA /	NA	NA	
16	1	Pressurization of Lift Shaft	NA	NA	NA	
	A	Pressurization of Lift lobby	NA	Provided	MR	
	В	Communication in lift car	Required	Provided	MR	
	C	Firemen's grounding switch	Required	Provided	MR	
	D	Firemen's grounding	Required	Provided	MR	
17	Standby Power Supply					
18	Refuge Area.		NA	NA	NA NA	
	A	Total area	NA	NA	1471	
		Location			TATA	
19	Fire Control Room		NA	NA	NA	
-	A	Detector system panel	NA	NA	NA	
	В	Flow switch panel	NA NA	NA	NA	
	C	PA system panel	Data Par	NA	NA	
	D	Battery backup	NA	NA	NA	
	-	Building Floor Plans	NA ind	ABC type fire	MR	
20	Special Fire Protection systems for protection of special Risks, if any:		Required	extinguishers provided for HT < panel		

LGENDS - Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided But Not Functional (PNF).

During inspection, the Hospital Management informed that the Hospital name has been changed from 'Bansal Hospital (A Unit of National Hospital Pvt. Ltd.),' to 'M/s Artemis Lite (A Unit of Artemis Medicare Services Ltd.).'

The fire protection system was randomly checked and tested and was found functional at the time of inspection.

In view of the deemed compliance of minimum standards of fire prevention and fire safet **FSC** the Rules, the under F6/DFS/MS/Hospital/2020/SZ/448 dated 03.11.2020 is recommended to be renewed under Rule 3 required of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Name Manoj Kumar Sharma

Designation DO (SD)

Signature of the Inspecting Officer Name Rajesh Kumar Shukla Designation ADO (M.Road)