## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

No.F6/DFS/MS/EH/NDZ/2023/ 23/

Dated: 19 /07/2023

## FIRE SAFETY CERTIFICATE

Certified that the M/s Karim Restaurant situated at S-517, School Block, Shakarpur, Delhi-110092 (Ground floor only) in a building comprised of Basement + Ground + 3 Upper floor, owned / occupied Karim Restaurant have complied with the Fire Prevention and Fire Safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and verified by the officers concerned of this department on 07/07/2023 in the presence of Mr. Mujeeb Rehman and found that the building/premises is fit for occupancy class "Assembly" (Group D) Eating House / Bar (Restaurant at Ground floor only) and valid up to 31/03 /2.24 (Three years) in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued 1907/2023 at New Delhi by.

DELHI FIRE SERVICE

Copy to:-

1. The Manager, M/s Karim Restaurant situated at S-517, School Block, Shakarpur, Delhi-110092

2. Join Commissioner of police (Lic.), Ist Floor, P.S Defence Colony, New Delhi-24 w.r.t.-MHA portal ID-2023063011784 dated:30.06.2023

## Condition for the validity of fire safety certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2 Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

The trained fire fighting staff should be available round the clock.

- Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6 The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7 The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.

Basement shall be used strictly as per Building By-Laws 1983.

The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

Nan	ne & address of the building						
		PECTION REPORT  M/s Karim Restaurant situated at S-517, School Block Shakarpur, Delhi-110092.					
	lding is comprised of	Basement + ( (storage), Gro	Basement + Ground + 3 Upper floors, Basement (storage), Ground floor (Restaurant), 1st floor to 3rd				
Тур	e of occupancy	Assembly Building (Restaurant)  New Case					
Тур	e of case						
Details of previous FSC		N/A					
Fire	safety direction letter no.	N/A					
Date of inspection		07/07/2023					
Nan	ne of the inspecting officers	Sh. A.K.Jaiswal, DO (ED) & Sh. Yashwant Singh					
Name of the designation of officer Mr. Mujeeb Rehman From the building side				7 -1 1-			
		2002					
App	olicant's letter no.	Application No	o. I.D -2023063011	784 dated:30.06.23			
Min	imum standard of Fire	4		Remarks MR/NMR			
		Las	T 00	TMP			
		Committee and the committee of the commi		MR N/A			
				N/A			
			1471				
A	No. of staircase:		MI TO LET ME				
5,51	Paramande and American Street and	N/A	N/A	N/A			
		N/A	N/A	N/A			
R							
		N/A	N/A	N/A			
		N/A	N/A	N/A			
С	Protection of Exits						
	a) Fire check door	Required	Provided	MR			
	b) Pressurization	N/A	N/A	N/A			
D	No. of continuous staircase to terrace:			N/A			
E	Width of the corridor			N/A			
F	Door size	1.50 mtrs x2	1.50 mtrs each	MR			
Con	partmentation:		Ta	Lvan			
A			TO CO. T. P. C. T. STORY (1974)	MR			
В	opening	3346		N/A N/A			
	Water curtain			N/A			
			N/A	N/A			
A	Basements	N/A		N/A			
В	Upper floors	N/A	N/A	N/A			
Fire	extinguishers						
A	Total numbers	1970-1970-1970-19		MR			
В	Types	ABC & CO2	ABC & CO2	MR			
С	ISI marking	Required	Provided	MR			
	Typ Deta Fire Date Nam Nam From Yea App Min Pre Acc A B C D E F Con A B C D E F Con B B C D E S B C B B C B B C B B C B B C B C B B C B B C B B C B B C B B C B B C B B C B B C B B C B B B C B B B C B B B B C B	Fire safety direction letter no.  Date of inspection  Name of the inspecting officers  Name of the designation of officer  From the building side  Year of construction  Applicant's letter no.  Minimum standard of Fire  Prevention and Fire Safety U/R 33  Access to Building  A Road width  B Gate width  C Width of internal roads  Number, Width, Type & Arrangem  A No. of staircase:  a) Upper floor  b) Basements  B Width of the staircase:  a) Upper floors  b) Basements  C Protection of Exits  a) Fire check door  b) Pressurization  D No. of continuous staircase to terrace:  E Width of the corridor  F Door size  Compartmentation:  A Fire check doors  B Sealing of horizontal & vertical opening  C Fire rating of shaft doors  D Water curtain  E Fire dampers  Smoke management System:  A Basements  B Upper floors  Fire extinguishers  A Total numbers  B Types	Type of occupancy Type of case  New Case  Details of previous FSC  N/A  Fire safety direction letter no.  Date of inspection  Name of the inspecting officers  Name of the designation of officer  From the building side  Year of construction  Application No.  Minimum standard of Fire  Prevention and Fire Safety U/R 33  Access to Building  A Road width  B Gate width  C Width of internal roads  N/A  Number, Width, Type & Arrangement of Exits  A No. of staircase:  a) Upper floor  b) Basements  N/A  B Width of the staircase:  a) Upper floors  b) Basements  N/A  C Protection of Exits  a) Fire check door  b) Pressurization  N/A  D No. of continuous staircase to terrace:  E Width of the corridor  A Fire check doors  B Sealing of horizontal & vertical opening  C Fire rating of shaft doors  N/A  B Upper floors  N/A  D Water curtain  N/A  E Fire dampers  N/A  B Upper floors  N/A  B Upper floors  N/A  D Water curtain  N/A  E Fire dampers  N/A  B Upper floors  N/A  B Upper floors  N/A  B Upper floors  N/A  C Sealing of horizontal & vertical opening  C Fire rating of shaft doors  N/A  B Upper floors  N/A  B Smoke management System:  A Basements  N/A  B Upper floors  N/A  B Basements  N/A  B Upper floors  N/A  B Upper floors  N/A  B Basements  N/A  B Upper floors  N/A  B Basements  N/A  B Basement	Type of occupancy Type of case  Details of previous FSC N/A  Fire safety direction letter no. Date of inspection Name of the inspecting officers Name of the designation of officer From the building side Year of construction Applicant's letter no.  Minimum standard of Fire Prevention and Fire Safety U/R 33 Access to Building A Road width O 9 mtrs Gate width N/A N/A Number, Width, Type & Arrangement of Exits A No. of staircase:  a) Upper floor b) Basements N/A Width of the staircase:  a) Upper floors N/A			

6	-	irst Aid Hose Reel	01=2	01 no.	MR		
	A	Total no. at each floor	01no.	30 mtrs	MR		
	B	Length of hose reel	30 mtrs 5 mm	5 mm	MR		
	C	Nozzle diameter		) min	ININ		
7	Automatic Fire Detection and Alarm System  A Type of detectors Heat/ Smoke Provided MR						
	A	Type of detectors		Provided	MR		
	B	Location of main Panel	Required	Provided	N/A		
	C	Location of repeater panel	Required	Provided	MR		
	D	Alternate power source	Required	Provided	MR		
	E	Hooter's location	Near Gate	Provided	MR		
8		DEFA	Required	N/A	N/A		
9		blic Address System	N/A	N/A	IN/A		
10	11/4						
	A	Basement	N/A	N/A	N/A		
	B	Upper floor	N/A	N/A	N/A N/A		
	C		N/A	N/A	N/A		
11	_	ernal Hydrants	1100	D	MR		
	A	Size of the riser/down comer	100 mm	Provided			
	B	No. of hydrants per floor	01 no.	Provided	MR		
	C	Hose box	01 no.	Provided	MR		
12	Yard Hydrants						
	A	Total no. of hydrants	N/A	N/A	N/A		
	B		N/A	N/A	N/A		
13							
	A	Ground Level					
	1000	a) Discharge of main pump	N/A	N/A	N/A		
		b) Head of Main Pump	N/A	N/A	N/A		
		c) Number of Main Pump	N/A	N/A	N/A		
		d) Jockey Pump out put	N/A	N/A	N/A		
		e) Jockey Pump Head	N/A	N/A	N/A		
		f) Standby Pump out put	N/A	N/A	N/A		
		g) Standby Pump Head	N/A	N/A	N/A		
		h)Auto Starting/ Manual stopp	ing N/A	N/A	N/A		
	B Terrace Level						
		a) Discharge of Pump	450 LPM	450 LPM	MR		
		b) Head of terrace pump	30 mtrs	30 mtrs	MR		
		c) Power supply	Required	Provided	MR		
		d) Auto starting of pump		Provided	MR		
14	Ca	otive Water Storage for Fire F		Tiovided	IVIK		
14	A	Underground tank capacity	N/A	N/A	N/A		
1		Draw off connection	N/A	N/A	N/A N/A		
- 1		Fire Service Inlet	N/A	N/A	N/A		
ſ	_	Access to tank	N/A	N/A	N/A N/A		
F		Overhead tank capacity	20,000 ltrs	Provided	MR		
-					IVIK		
	D						
15	D Exi	Signage	Required	Provided	MR		
15 16	D Exi Pro	t Signage vision of lift	Required	Provided	MR		
15 16	D Exi Pro	t Signage vision of lift Pressurization of lift shaft	Required N/A	Provided N/A	MR N/A		
15 16	D Exi Pro A B	t Signage vision of lift Pressurization of lift shaft Pressurization of lift lobby	N/A N/A	N/A N/A	MR N/A N/A		
15 16	Exi Pro A B	t Signage vision of lift Pressurization of lift shaft Pressurization of lift lobby Communication in lift car	N/A N/A N/A	N/A N/A N/A	N/A N/A N/A		
15	Exi Pro A B C D	t Signage vision of lift Pressurization of lift shaft Pressurization of lift lobby	N/A N/A	N/A N/A	MR N/A N/A		

18	Refuge Area M14						
	A	location	N/A	N/A	N/A		
Т	В	Total area	N/A	N/A	N/A		
<sub>h</sub> 19	Fir	Fire Control Room					
	A	Fire Detection System panel	N/A	N/A	N/A		
	В	Flow switch panel	N/A	N/A	N/A		
	C	P A system panel	N/A	N/A	N/A		
	D	Battery backup	N/A	N/A	N/A		
	E	Building floor plan	N/A	N/A	N/A		
20	Special Fire Protection for special risk if any						
	A	Special Fire Protection system for Protection of Special Risk, if any:	NA	NA	NA		

Note:- The applicant has submitted an undertaking that he has punctured the two temporary (SPS) rooms on terrace and it is now not habitable and he will also not use these temporary rooms in any case (C-18). Photograph of punctured rooms also attached (C16 & C17).

The fire protection system was randomly checked and tested and was found functional at the time of inspection. The shortcomings issued vide letter no.

F6/DFS/MS/EH/NDZ/2022/178 dated 11.02.2022 by this department have been rectified by the management.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, it is recommended to grant Fire Safety Certificate under Rules 37 of Delhi Fire Service Rules 2010 for Ground Floor only.

Signature of the Inspecting Officer

Name: A.K. Jaiswal Designation: DO (ED)

Signature of the Inspecting Officer
Name: Yashwant Singh Meena

Designation: ADO (L.N)

Dy.CFO (MDZ)

Colopo Colopo

Dinector/

\$\frac{1}{47} | \frac{2023}{2023}

ADD/LIN

F.T. Letter is purup for SignoPlease

17/7/2023

Uplocded