

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/School/WZ/2023/575

Dated: 27/07/2023

Director

FIRE SAFETY CERTIFICATE

Certified that the St. Mathew's School Located at A-6, Paschim Vihar, New Delhi-110069, comprised of Ground + 03 Upper Floor only was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/WZ/2019/910 Dated 29.04.2019. The said premise was re-inspected by the officer concerned of this department on 14.07.2023 in the presence of Sh. Krishan (Librarian) and found that the premises / building have deemed complied with rule 33 Delhi Fire Service Rules, 2010 and that the premises/building is fit for occupancy class "Educational Building" Group B with effect from 27/07/2227 for a period of three years in accordance with Rule 36 unless renewal under Rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under Rule 38 of the DFS Rules, 2010, printed below.

Issued on .27.10.7.1.2023.. at New Delhi by.

Copy to: -

1. The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi - 110054.

2. The Principal, St. Mathew's School, A-6, Paschim Vihar, New Delhi-110069.

Following fire safety directives must be adhered to:-

1. All the means of escape shall be kept free of all type of obstruction all the time.

 All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

 All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.

Any deviation, with regards to construction, ventilation, occupation, electric installation etc.
 may be got verified from the concerned authorities.

 The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.

6. All comments / directions of licensing Department shall always be permitted and followed.

7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building: St. Matthew's School, Located at A-6, Paschim Vihar, New Delhi-110069.

2. Type of Occupancy

: Educational (G + 03 Upper Floor only)

3. Type of Case

: Renewal

4. Details of previous NOC

: F6/DFS/MS/WZ/2019/910 dated 29.04.2019

5. Fire Safety directives Letter No.: NBC (Part-IV)/Cr. No. 3298-3398 dated

01.03.2011

6. Date of inspection

: 14.07.2023

7. Name of the Inspecting Officer : Aman Kumar Lathar, ADO (JWP)

8. Name and designation of Officer

from the building side

: Sh. Krishan (Librarian)

9. Year of Construction

: 2005

10. Applicant's letter No.

: email dated 29.05.2023

No	Minimum standards on fire prevention and fire safety U/R 33	and fire safety and fire safety 3398 dated 01.03.2011 /as per FSC dated 29.04.2019		Provided at site	Remarks MR/NMR			
	Access of building							
	Road width	Accessible 06 m		•				
	 Gate width 	4.5 m 💌	403		MR(Old Case) NA			
	 Width of internal road 	NA	NA		NA			
2	Number, width, Type & Arrangements of exits							
	a. Number of staircases	Make and a second secon) (D				
	Upper floors	02 04						
	Basements	NA	NA		NA			
	b. Width of staircases	16 10 105 01 101			1 1 1 1 1 1			
	Upper floors		1.5m 3 x 135 cm & 1 x 131 c					
	Basements	NA	NA		NA			
	c. Protection of exits							
1	Fire check door	NA	Land Com-	NA	NA			
	Pressurization	NA		NA	NA			
	d. No of continuous staircase to terrace	01	P	rovided	MR			
	e. Width Of Corridor	1.5mtr	Corne Firm	180 cm	MR			
	f. Door Size	1mtr	100	113 cm	MR			
3.	Compartmentation		A PLANT	L LX				
	Fire check door	- NA		NA				
	Sealing of electrical shafts	NA		NA				
	Fire Rating of shaft door	NA		NA				
	Water Curtain Fire Development	NA		NA				
4.	Fire Dampers	NA		NA				
٠.	Smoke managements System NA NA NA							
	Basements	NA NA		NA				
5.	• Upper floors	NA	- 0,	NA	NA			
٥.	Fire Extinguishers		1000					
	Total numbers	12 nos.		15 nos.				
	• Types	ABC & CC	2	Provided				
	IS marking	ISI marked	i	Provided				

Provided Provided Provided Provided NA PROVIDEN NA N	MR MR NA						
NA N	NA NA NA NA NA NA NA NA						
NA N	NA						
NA NA NA NA NA NA NA NA NA Provided	NA						
NA N	NA NA NA NA NA NA						
NA NA NA NA NA NA NA NA Provided	NA NA NA NA NA						
NA NA NA NA NA NA NA Provided	NA NA NA NA						
NA NA NA NA NA NA Provided	NA NA NA NA						
NA NA NA NA Provided	NA NA NA						
NA NA NA Provided	NA NA						
NA NA NA Provided	NA						
NA NA NA Provided	NA						
n Provided							
n Provided	N ATA						
	NA						
Provided	d MR						
	d MR						
ed Provided	d MR						
Hose Box Required Provided MR 2. Yard Hydrants							
NA	NA						
NA	NA						
*							
Pumping Arrangements: Ground Level							
NA	NA						
NA	NA						
NA	NA						
ŇA	NA						
NA	NA						
NA	NA						
NA	NA						
NA	NA						
NA	NA						
	M CONTRACTOR						
om & Provid	ded MR						
180 lpm							
Mtr Provid	ded MR						
ired Provid	ded MR						
aired Provid							
- A							
IA NA	A NA						
IA NA							
uired Provi	ided MF						
IA N							
0 ltrs. Prov							
uired Prov							
Exit Signage Required Provided MF Provision of Lifts							
IA N.	A NA						
JA N.							
JA N							
JA N							
	A NA						
IA I AI	A N						
N N							
100	A N						
NA N	A N.						
	NA N						

19.	Fire control room							
	Detector system panel	NA	NA	NA				
3	> Flow Switch Panel	NA	NA	NA				
	> PA System Panel	NA	NA	NA				
	> Battery backup	NA	NA	NA				
	➤ Building Floor Plans	NA	NA	NA				
20.	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA	NA				
	Fire protection systems provided in the building were checked and found							
	functional at the time of inspection. Shortcomings issued vide letter							
	F6/DFS/MS/School/WZ/2022/167 Dated 08.04.2022 are rectified.							

In view of the deemed compliance of the minimum standards of fire prevention and fire safety requirements under the rules, renewal of Fire Safety Certificate issued vide letter no. F6/DFS/MS/WZ/2019/910 dated 29.04.2019 is recommended under rule 37 of the Delhi Fire Service Rule, 2010 under DFS Act 2007

Accordingly DFA is prepared & put up for approval please.

ADO (JWP)

Defo(MICC)

M.K. CHATTOPAUHYAY

For letter is pret-up for your organituse M.

Diestol