



C 7

75
आजादी का
अमृत महोत्सव

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/EH/WZ/2023/ 245

Dated: 01/08/2023

FIRE SAFETY CERTIFICATE

Certified that the **Copper Chimney (A Unit of Deluxe Caterers Pvt. Ltd.)**, located at Unit No. G 6, Ground Floor, Vishal Complex, District Centre, Rajouri Garden, New Delhi – 110027, running at Ground Floor only in a building comprised of 02 Basement + Ground + 04 Upper Floor was issued FSC to mall vide this department letter no. F6/DFS/MS/2023/79 dated 14/02/2023, the building/premises was inspected by the officer concerned of this department on 22/07/2023 in the presence of Sh. Vipin Kumar and found that the said premises/building have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises/building is fit for occupancy class “Assembly” (Group - D) with effect from 01/08/2023 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010. Conditions Printed Overleaf.

Issued on 01/08/2023.. at New Delhi by.

(Atul Garg)
Director

Copy to: -

1. The owner/occupier, Copper Chimney (A Unit of Deluxe Caterers Pvt. Ltd.), located at Unit No. G 6, Ground Floor, Vishal Complex, District Centre, Rajouri Garden, New Delhi – 110027. Online Application ID no. 2023070812216 dated 15/07/2023
2. The Joint Commissioner of Police, Licensing Unit, 1st floor, Police Station, Defence Colony, New Delhi. (adlcp.lic-dl@nic.in)
3. The Dy. Health Officer, SDMC, West Zone, Vishal Enclave, Rajouri Garden, New Delhi 110027. (dhwest_zone@gmail.com)

INSPECTION REPORT

1. Name & address of the building : Copper Chimney (A Unit of Deluxe Caterers Pvt. Ltd.),
Located at Unit No. G 6, Ground Floor, Vishal Complex,
District Centre, Rajouri Garden, New Delhi – 110027.
2. Type of Occupancy : Eating House /Assembly Occupancy
3. Type of Case : New ✓
4. Details of previous NOC : Nil
5. Fire Safety directives letter No : Nil
6. Date of inspection : 22/07/2023
7. Name of the Inspecting Officers : Sarabjeet Singh ADO(MN)
8. Name and designation of officers
from the building side : Sh. Vipin Kumar
9. Year of Construction : 2022 (As Per MHA Portal)
10. Applicant's letter No. : Online application ID No. 2023070812216 dated 15/07/2023

*** The Said Restaurant is running at Ground floor in Vishal Complex is comprised of 02 Basement + Ground + 04 Upper Floors FSC was issued vide this dept. letter no. F6/DFS/MS/2023/79 dated 14/02/2023.**

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	BBL /NBC Requirement	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	12 mts	Provided	MR
	• Gate width	4.5 mts	Provided	MR
	• Width of internal road	06 mts	Provided	MR
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	NA	Located At G.F.	NA
	• Basements	NA	NA	NA
	b. Width of staircases			
	• Upper Floors	NA	Located At G.F.	NA
	• Basements	NA	NA	NA
	c. Protection of exits			
	• Fire check door	NA	NA	NA
	• Pressurization	NA	NA	NA
	e. No. of continuous staircases to terrace	NA	NA	NA
	f. Width of Corridor	NA	NA	NA
	g. Door Size	1.5 mtr X 2	Provided	MR
3	Compartmentation. Common With Mall			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4	Smoke Management System.			
	• Basements	NA	NA	NA
	• Upper floors	Required	Provided	MR
5	Fire Extinguishers			
	• Total numbers	5 nos. CO ₂ , ABC type ISI marked	Provided	MR
	• Types		Provided	MR
	• IS marking		Provided	MR

6	First-Aid Hose Reels. Common with Mall			
	• Total numbers on each floor	01	Provided	MR
	• Length of hose reel hose	30 mm	Provided	MR
	• Nozzle diameter	05 mm	Provided	MR
7	Automatic fire detection and alarming system.			
	• Type of detectors	Smoke & Heat	Provided	MR
	• Location of Main Panel	Required	Provided	MR
	• Location of Repeater Panel	NA	NA	NA
	• Alternate source of power	Required	Provided	MR
	• Hooters' Location	Required	Provided	MR
8	MOEFA	Required	Provided	MR
9	Public Address System.	NA	NA	NA
10	Automatic Sprinkler System.			
	• Basement	NA	NA	NA
	• Upper Floor	Required	Provided	MR
	• Sprinkler above false ceiling	Required	Provided	MR
11	Internal Hydrants Common With Mall			
	• Size of riser/down-comer	150 mm	Provided	MR
	• Number of hydrants per floor	01	Provided	MR
	• Hose Box	01	Provided	MR
12	Yard Hydrants. Common With Mall			
	• Total number of hydrants	NA	NA	NA
	• Hose Box	NA	NA	NA
13	Pumping Arrangements. Common With Mall			
	• Ground Level			
	➤ Discharge of main Pump	NA	2850 LPM	NA
	➤ Head of Main pump	NA	90 m	NA
	➤ Number of main pumps	NA	02 + 1 for water contain	NA
	➤ Jockey Pump out put	NA	02 x 180 LPM	NA
	➤ Jockey pump head	NA	90 m	NA
	➤ Standby Pump out put	NA	2850 LPM	NA
	➤ Standby Pump Head	NA	90 M	NA
	➤ Auto Starting/ Manual stopping	NA	Common with the mall	NA
	➤ Pump House Access	NA	Common with the mall	NA
	• Terrace level			
	➤ Discharge of pump	NA	NA	NA
	➤ Head of the pump	NA	NA	NA
	➤ Power Supply	NA	NA	NA
	➤ Auto Starting of pump	NA	NA	NA
14	Captive Water Storage for fire fighting. Common With Mall			
	• Underground tank capacity	NA	02 Lakh Ltr Provided	NA
	➤ Draw-off connection	NA	Provided	NA
	➤ Fire service inlet	Required	Provided	MR
	➤ Access to tank	NA	Provided	NA
	• Overhead Tank capacity	NA	20,000 ltr Provided	NA
15	Exit Signage.	Required	Provided	MR


84/


N/S


16	Provision of Lifts.			
	• Pressurization of Lift Shaft	NA	NA	NA
	• Pressurization of Lift lobby	NA	NA	NA
	• Communication In lift Car	NA	NA	NA
	• Fireman's Grounding Switch	NA	NA	NA
	• Lift Signage	NA	NA	NA
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	➤ Total Area	NA	NA	NA
	➤ Location	NA	NA	NA
19	Fire Control Room			
	• Detector System Panel	NA	NA	NA
	• Flow Switch Panel	NA	NA	NA
	• PA System Panel	NA	NA	NA
	• Batter backup	NA	NA	NA
	• Building Floor Plans	NA	NA	NA
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were checked and found functional at the time of inspection.


Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.


 Signature of the Inspecting Officer
 Name: Sarabjeet Singh
 Designation: ADO (MN)


 As per enclosed drawing 2nd/Alternative exit is not clear. clarify.


 DO (West) / DO (Sh. M. K. C.) on leave
 ADO (Motinagar)

Sir, 2nd exit is passing through fire corridor resubmitted pl. Sir


 27/7/2023
 Director


 25/7/2023