

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/Business/2023/SZ/ 367

Dated: 02 /28 /2023

FIRE SAFETY CERTIFICATE

Certified that the **Deepali Building** located at 92, Nehru Place, New Delhi 110019 comprised of Basement, ground plus 08 upper floors owned/occupied by Om Apartment Pvt. Ltd was issued NOC by this department vide letter No F.6/MS/DFS/2003/2338 dated 30-09-2003. The premise was re-inspected by officer concerned of this department on 26/07/2023 in the presence of Mr. Rajesh Soni and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that building is fit for occupancy class "**Business Occupancy**" with effect from 0 2 / 08 / 2023 for period of **Three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued 02 08 /2023 at New Delhi by

DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. Mr. Rajesh Soni, Deepali Building located at 92, Nehru Place, New Delhi 10019.

The Executive Engineer (Bldg) Municipal Corporation of Delhi, Dr. SPM Civic Centre, Minto Road, New Delhi 110002.

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The basement shall be used as per the provisions of UBBL /NBC Part- IV.
- The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL- 2016), if any.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

N121

आज़ादी का अमृत महोत्सव

	INSPECTI	ON REPORT	(1) (A) P		
1	Name & Address of the Building	Deepali Buildin	ng, 92, Nehru Place, New	Delhi 110010	
2	T-ma of Occupancy	Dusiness Group-E"			
3	Building Comprised of	Basement, Ground + 08 upper floors.			
4	Toma of Case	Renewal			
5	Details of Previous NOC	F.6/MS/DFS/2003/2338 Dated 30-09-2003			
6	Fire Safety Directives Letter No	(12 bare minimum fire safety points)			
7	Date of Inspection	26/07/2023			
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)			
9	Name & Designation of Officers from the building side	Mr. Rajesh Soni			
10	Year of construction	1988			
11	Applicant letter No.	Outdoor diary no 3859 dated 18/07/2023			
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33			Remarks MR/NMR	
1	Access to Building.	1 1 1 1 1 1	No odrona (multi-sa)		
-	Road width	Accessible	Provided (01 side)	MR	
100	Gate width	Required	Provided	MR	
	Width of internal road	-NA-	-NA-	-NA-	
2	Number, width, type & arrangement of exits.			-117-	
	a) Number of Staircase		we comply belt 4	Profit	
VI-	> Upper floors.	01 No	01 main & 01 spiral SC	MR (old case)	
M	> Basement floor.	01 No	01 No	MR (old case)	
H	b) Width of Staircase		-2	Time (one case)	
16	> Upper floors	1.25 mtr	1.25 mtr	MR (old case)	
10	> Basement floor	1.25 mtr	1.25 mtr		
W. 7	c) Protection of exits	3(1) - 1 , 11-1	ners and district in	MR (old case)	
Per 1	> Fire check door	Required	Provided	MR	
	> Pressurization	Required	Provided	The Target of th	
241.	d) No. of continuous staircase to terrace	02 Nos		MR	
	e) Width of corridor	-NA-	Provided	MR	
K	n Door size	-NA-	-NA-	-NA-	
3	Compartmentation.	-NA-	-NA-	-NA-	
	Fire check door.	Required	Provided) AD	
17	Sealing of electrical shafts.			MR	
7.1	Fire rating of shaft door.	Required	Provided	MR	
185	Water curtain	Required	Provided	MR	
14	Fire dampers.	-NA-	-NA-	-NA-	
4.	The late of the la	-NA-	-NA-	-NA-	
7.	Smoke Management system.	00 1 5555	rethigs2 fix	A STATE	
	Basement	30 ACPH	Provided	MR	
W.	Upper floors	12 ACPH	none -NA-	-NA-	
5.	Fire Extinguishers.	YALA DI	rita material participation of		
16	Total numbers	28 Nos	50 Nos	MR	
4	Types	ABC / W.COZ	CO2, W.CO2 & ABC	MR	
56 a	ISI Marking	ISI marked	Provided	MR	
6.	First Aid Hose Reels,	- Indikod	Tiovided	MIK	
	Total numbers on each floor.	01 Nos	01 37	1 3/0	
7		MANAGE CONTRACT	01 Nos	MR	
	Length of hose-reel hose.	30m	Provided	MR	
-	Nozzle Diameter	5mm	Provided	MR	
7	Automatic fire detection & alarming system.		mood from Fee	4 1 .01	
1.7	Type of detectors	Required	Heat & Smoke	MR	



4

N/22

	100		The state of the s	
	Location of Main Panel	Required	Ground floor	MR
	 Location of Repeater Panel 	-NA-	-NA-	-NA-
1	 Alternate source of power 	Required	Provided	MR
	Hooter's location	Each floor	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	-NA-	-NA-	-NA-
10.	Automatic Sprinkler System	1	property of	N. I
	Basement	Required	Provided	MR
_	Upper floors	-NA-	-NA-	-NA-
	 Sprinkler above false ceiling 	-NA-	-NA-	-NA-
11.	Internal Hydrants.		THE WINE PLANTS OF THE PARTY OF	
	 Size of Riser/Down-comer 	Required	Provided	MR
_ 1	 Number of Hydrant per floor 	Required	Provided	MR
Sept.	Hose box.		Provided	MR
12.	Yard Hydrants.	Required	Provided	IVIK
	Total number of hydrants.	774	NI	NA
		-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
13.	Pumping arrangements.			
	Ground Level		Carried and the same of the sa	
-	Discharge of main pump.	-NA-	-NA-	-NA-
	Head of main pump.	-NA-	-NA-	-NA-
m Da	Number of main pumps.	-NA-	-NA-	-NA-
E MARKET	> Jockey Pump output.	-NA-	-NA-	-NA-
	> Jockey Pump head.	-NA-	-NA-	-NA-
- 1	Standby Pump output.	-NA-	-NA-	-NA-
	 Standby Pump head. Auto Starting/Manual Stopping. 	-NA-	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
17	. The same of the	-NA-	-NA-	-NA-
5	Terrace Level		INTERIOR DE EURO	
	> Discharge of pump.	Booster pump	900 LPM	MR
	> Head of pump.	Required	Provided	MR
10	> Power supply.	Required	Provided	MR
7.	> Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for fire fighting.		The state of the s	4
5.6	Underground tank capacity.	35,000 Ltrs	Provided	MR .
	> Draw-off connection.	Required	Provided	MR
16	Fire Service Inlet.	Required	Provided	MR
1.5-	Access to tank.	Required	Provided	MR
1	Overhead tank capacity.	25,000 Ltrs	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.		ti de la constant	IVIK
	Pressurization of lift shaft.	Required	Provided	100
	Pressurization of lift lobby.	Required	Provided	MR
62 11	Communication in lift car.	Required	Provided	MR
ž,	Fireman's switch.	Required	Provided	MR
-	Lift signage.	Required		MR
17.	Standby Power Supply		Provided	MR
	1	Required	62KVA(DG Set)	MR
18.	Refuge Area	er = molerieses	A CONTRACTOR	
	Total area	-NA-	-NA-	-
	Location	-NA-	GENERAL	-NA-
19.	Fire Control Room.	-11/1-	-NA-	-NA-
	Detector system panel.	Paguinal	ROLL NO THE THE TARK THE	
	Detector system panel.	Required	Provided	MR

m

equired equired	-NA- Provided	-NA-
		MR
	Provided	MR
equired	Provided	MR
-NA-		-NA-
	equired -NA-	equired Provided

ction system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 1175 dated 05/06/2023.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and safety measures as required under the rules, the FSC issued vide letter no F.6/M\$/DFS/2003/2338 dated 30-09-2003, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)

CFO (HO)

approved, F.T. Lettre en putup for

Ny

Ollodings