

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2023/SZ | 535

Dated: 07/08/2023

FIRE SAFETY CERTIFICATE

Certified that the New Era Public School, Mayapuri Road, New Delhi-110064, comprised of two blocks namely Main Block and Primary Block. Each block having basement, ground floor plus two upper floors, having total 58 rooms in Main block (Including Classrooms, labs, staffrooms, one multipurpose hall, one badminton hall & offices etc. Basement is used for storage), and 24 rooms including classrooms, one Multi purpose hall etc. basement vacant in Primary Block owned/occupied by New Era Public School was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/School/2020/SZ/302 dated 24/08/2020. The School building was re-inspected by the officer concerned of this department on 28/07/2023 in the presence of Sh. Arvind Sharma (Admin Officer) and found that School building have deemed complied the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class "Educational" for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on 07/08/2023 at New Delhi.

Director Delhi Fire Service

Copy to:-

- The Principal, New Era Public School, Mayapuri Road, New Delhi-110064
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

7. Basement shall be used as per the building bye laws.

- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its
- 10. Fire Safety Certificate will be null and void if hall on second and third floor in primary block is used as Multi purpose hall for assembly purpose.

INSPECTION REPORT

New Era Public School, Mayapuri Road, New Delhi-110064. Name & address of the building:

Two blocks namely Main Block & Primary Block. Each block is Building comprised of

having Basement, ground plus two upper floors.

Type of Occupancy 3. Educational Type of Case Renewal

F6/DFS/MS/School/2020/SZ/302 dated 24/08/2020 Details of Previous NOC

6. Fire \$afety directives letter No : N/A 7. Date of inspection 28/07/2023 Name of Inspecting Officer A.D.O. R.K. Yadav

Name and designation of officers

Sh. Arvind Sharma (Admin Officer) From the building side

S. No.	Minimu	cant's letter No. : Form "J' im Standards on fire prevention and ty U/R 33	'dated Nil Requirement as per FSC dt. 24.08.2020		Remarks MR/NMR			
1.	Access	to building			N/D			
		Road width	Accessible (06 mtrs.)	12 mtrs	MR			
		Gate width	4.5 mtrs N/A	05 mtrs N/A	MR N/A			
	•	Width of internal road	N/A	IN/A	N/A			
2.	Number, Width, Type & Arrangement of Exits							
		ber of staircases	A STATE OF THE STA					
		Upper Floors	04 No's in M-Blk	07 No's in M-Blk	MR			
	•	Basements	02 no. P-Blk 02 No's in each block	02 no. P-Blk 02 No's in each block	MR			
	b. Widt	h of staircases	1.50 m	M-Blk 1.59, 1.58, 1.56				
	•	Upper Floor	0.000.000.000	1.54, 1.50, 1.50 & 1.65 m P-Blk 1.50 & 1.50 n				
	•	Basements	1.50 & .75 m	M-blk 1.50 & 1.50 m P-blk 1.45 & 1.42 m	MR in M-blk &			
	c. Prote	ction of exits						
	•	Fire check door	Required in basement	Provided	MR			
	•	Pressurization	of M. Block N/A	N/A	N/A			
			N/A	IN/A	IN/A			
	d. No.	of continuous staircases to						
	terra		Required	Four	MR			
	THE THE TOTAL CONTROL OF THE TOTAL CONTROL OT THE TOTAL CONTROL OF THE TOTAL CONTROL OF THE TOTAL CONTROL OT THE TOTAL CONTROL OF THE T	h of Corridor	1.50 m	M-blk 3.40 & 1.80 m P-blk 1.80 m	MR			
	f. Doo	r Size	1.0 m in CR 1.50 m in Audi.	1.10 m in CR 1.85, 1.55 & 1.50 (including frame) in	old case			
3.	Compa	tmentation		The state of the state of	y Billio I I a			
5-0.5	000004770-0007	Fire check door	N/A	N/A	N/A			
		Sealing of electrical shafts	N/A		63M8040			
		Fire Rating of shaft door		N/A	N/A			
		Water Curtain	N/A	N/A	N/A			
		Fire Dampers	N/A	N/A	N/A			
	2010		N/A	N/A	N/A			
1.	Smoke I	Janagement System		TO COMPANY				
	•	Basements	Required	Exhaust fans are	e MR			
	• 1	Upper floors	Required	Natural ventilation	MR			
5.	Fire Extinguishers							
	• *	Total numbers	30 no.'s	Provided	140			
		Гуреѕ	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		MR			
			ABC/CO ₂ /W CO ₂ type	Provided	MR			
).		S marking	ISI marked	ISI marked	MR			
		l Hose Reels	X					
		Total numbers on each floor Length of hose reel hose	04 no.'s in M blk & 01 no. in P blk	Provided	MR			
		Nozzle diameter	30 mtrs	Provided	MR			
			5 mm	Provided	IVIIX			

N	5

ý.	Automatic fire detection and alarming system			1
	Type of detectors	N/A	N/A	1
	Location of Main Panel	N/A	N/A N/A	N/A
	Location of Repeater Panel	N/A N/A		N/A
	Alternate source of power	N/A N/A	N/A N/A	N/A
	Hooters' Location	N/A	N/A N/A	N/A
	MOEFA	N/A	N/A	N/A N/A
	Public Address System	N/A	Provided	N/A
0.	Automatic Sprinkler System			1.00
	Basement	Required	Provided	MR
	Ground Floor	N/A	N/A	N/A
1.	Sprinkler above false ceiling Internal Hadronete	N/A	N/A	N/A
1.	Internal Hydrants Size of riser/down-comer	N/A	100	NIA
	Number of hydrants per floor	N/A N/A	100 mm M blk 02 & P blk	N/A N/A
	Hose Box		01	
		N/A	M blk 02 & P blk 01	N/A
2.	Yard Hydrants		1 01	
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	 Head of Main pump Number of main pumps 	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A	N/A
	 Standby Pump Head Auto Starting/Manual Stopping 	N/A	N/A	N/A
	Auto Starting Manuar Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level	450 1 004 (02 '-)	450 LPM (02 no.'s) &	MD
	Discharge of pump	450 LPM (02 no.'s)	180 LPM (02 no.'s)	MR
	> Head of the pump	40 mtrs	Provided	MR
	 Power Supply Auto Starting of pump 	Required	Provided	MR MR
	Auto Starting of pump	Required	Provided	MIK
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	25,000 ltrs Provided	N/A
	> Draw-off connection	N/A	N/A	N/A
	> Fire service inlet	N/A	Provided	N/A
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	15000 ltrs	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts. Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift Shalt Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	Required	Provided	MR
	Fireman's Grounding Switch	Required	Provided	MR
	Lift Signage	Required	Provided	MR
				N/A
17	Standby nower supply	N/A	Provided	IVA
17.	Standby power supply	N/A	Provided	IVA
17. 18.	Standby power supply Refuge Area. > Total Area	N/A	Provided N/A	N/A

L

Fir	Control Room Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
- 1	Building Floor Plans	N/A	N/A	N/A
+	cial Fire Protection System for Protection	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found

functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter number F6/DFS/MS/School/2020/SZ/302_dated_24/08/2020_renewal_under_Rule_37_of the Delhi_Fire Service_Rules_2010 is recommended.

Note:- As per declaration submitted by the owner/occupier one multipurpose hall in primary wing is used for sports/dance purpose only.

Signature of Inspecting Of

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

D.O. (South West)

31/7/23

Follow

Asy 2XI

Letter 16

I hetter is put up for sign.

DIRECTOR MOM

4/8/2023