#### GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

ग्राजादी वा अमृत महोत्सव

No. F6/DFS/MS/EH/SZ/2023/249

Dated: 09 08 2023

#### FIRE SAFETY CERTIFICATE

Certified that the M/s Suprasaad Restaurant Pvt. Ltd., located at property no. 101, Ground floor, Old Ishwar Nagar, Main Mathura Road, New Delhi-25, is running at ground floor of the building comprised of Two tier Basements, Ground + 08 upper floors, owned & occupied by M/s Suprasaad Foods Pvt. Ltd has complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by a team of officers concerned of Fire Service on 02.08.2023 in the presence of Smt. Suchita Garg (owner) and that the building/premises is fit for occupancy Class Group 'D' (Assembly) with effect from 09.08.1.2023 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on ....0.9. 0.8. 20.2.3....at New Delhi by

Delhi Fire Service

11 02/0/23 N

Ref: Online ID no. 2023072112950 dated 21.07.2023.

#### Copy to:-

1. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi

 M/s Suprasaad Foods Pvt. Ltd., located at Property no. 101, Ground floor, Old Ishwar Nagar, Main Mathura Road, New Delhi-25.

### Conditions for the validity of Fire Safety Certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 8. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

## INSPECTION REPORT

1.	Name and address of the building:	M/s Suprasaad Foods Pvt. Ltd., located at Property no. 101, Ground floor, Old Ishwar Nagar, Main Mathura Road, New Delhi-25.	
2.	Building is comprised of	Two tier Basements, Ground + 08 upper floors (Restaurant is running at Ground floor of the building)	
3.	Type of occupancy	Assembly -(Restaurant)	
4.	Type of case:	New case	
5.	Details of previous FSC:	No	
6.	Fire safety directives no.:	NBC Part IV/UBBL- 2016	
7.	Date of inspection:	02.08.2023.	
8.	Name of the inspecting officer:	Manoj Kumar Sharma, DO (SD) & Rajesh Kumar Shukla, ADO (M. Road)	
9.	Name and designation of the officer from the building side:	Suchita Garg (Owner)	
10	Year of construction:	2023	
11	Reference letter no.:	Online ID no. 2023072112950 dated 21.07.2023.	

-		ince letter no.;	Tomme ID III	o. 2023072112950 da	ted 21.07.2023	
S.N o	Pre U/I	nimum standard of Fire evention and Fire Safety R 33	Requirements (as per NBC 2016/ UBBL 2016)	Provide at site	Remarks MR/NMR	
1		ess to Building:				
			6.0 mtrs.	9.0 mtrs.	MR	
	В	Gate width	NA	NA	NA	
	C	Width of internal roads		NA	NA	
2	Number, Width, Type & Arrangement of Exits:					
	A	restaurant at Ground noor only				
		a) Upper floor	NA	NA	NA	
		b) Basements	NA	NA	NA	
	В	Width of the Staircase:	Restau	rant at Ground floo	ronly	
		a) Upper floors				
		i Main staircase	NA	NA	NA	
		ii Atl. staircase	NA	NA	NA	
		b) Basements	NA	NA	NA	
	C	Protection of Exits				
		a) fire check door	NA	NA	NA	
		b) pressurization	NA	NA	NA	
	D	No. of continuous staircase to terrace	NA	NA	NA	
	E	Width of the corridor	NA	NA	NA	
	F					
		a Main exit	1.50 mtrs.	Provided	MR	
		b Alternate exit	1.50 mtrs.	Provided	MR	
3	Compartmentation:					
	A	Fire check doors	NA	NA	NA	
	В	Sealing of horizontal & vertical opening	NA	NA	NA	
	C	Fire rating of shaft doors	NA	NA	NA	
	D	Water curtain	NA	NA	NA	
	E	Fire dampers	NA	NA	NA	
4	Smoke Management System:					
	A	Basements	NA	NA	NA	
	В	Upper floors	NA	NA	NA	
5	Fire Extinguishers:					
	A	Total numbers	06 no.	06 nos	MR	
	В	Types	ABC +CO <sub>2</sub>	ABC +CO <sub>2</sub>	MR	
	C	ISI marking	ISI marked	ISI marked	MR	

6	F	irst Aid Hose reel: Common system pro	wided & maintain	ad L. I. ii ii	
	A	Total no. at each floor	01 no.	ed by building mana	
	В		30 m	01 no.	MR
	C	Nozzle diameter	5 mm	30 m	MR
7	A	utomatic Fire Detection and Alarm Sy	otom (ADAS).	5 mm	MR
	A	Type of detectors	NA NA	10.	
	В		NA NA	Smoke/heat	NA
		Location of repeater panel		Ground floor	NA
	D		NA	NA	NA
	E		NA	NA	NA
	-	The state of the s	NA	Audible in entire	NA
8	М	OEFA:		building	
9		Public Address Systems Required Provided		MR	
10	A	utomatic Sprinkler System:	NA	NA	NA
	A	Basement System:	1514		
		Upper floor	NA	NA	NA
	C		NA	Provided	NA
11	_	ternal Hydrants:	NA	NA	NA
11					
		Size of down comer/riser	100 mm	150 mm	MR
	C	No. of hydrants per floor Hose box	1 no	1 no	MR
12	_		l no.	l no.	MR
14		Total		The second secon	
	A	Total no. of hydrants	NA	6 nos.	MR
13	B		NA	6 nos.	MR
13	A	Management	em Provided & ma	nintained by building	
	A	Ground Level			
		a) Discharge & head of main pump	2850 LPM & 80 M	Provided	MR
		b) Number of main pump	1 no.	Provided	MR
	ŀ	c) Discharge & head of jockey pump	180 LPM & 80 M	Provided	MR
		d) Discharge & head of standby pump	2850 LPM & 80 M	Provided	MR
		e) Auto starting/ manual stopping	Required	Provided	MR
	В	Terrace Level : Common system Provi	ided & maintained	by building	IVIIX
		a) Discharge of terrace pump	450 LPM	Better system provided	NA
		b) Head of terrace pump	NA		NA
		c) Alternate power supply	NA		NA
		d) Auto starting of pump	NA		NA NA
4	Сар			Provided & maintained	
		Underground tank capacity	NA	A SECURITION OF THE PARTY OF TH	NA
1		Draw off connection	NA		NA
	С	Fire service inlet	NA		NA
	E .	Access to tank	NA		NA
	_	Overhead tank capacity	20,000 Liters		MR
5		Signage:	Required	and the second second	Salara Salara
5		vision of lift:	Required	Provided	MR
	_	Pressurization of lift shaft	NIA I	NIA I.	1.4
1			NA		NA
ł					NA
ŀ					NA
-	_	10 1			NA
7	EI	Lift signage	NA	NA N	١A
$\rightarrow$					ИR

M/s Sandoz Restaurants Pvt. Ltd., located at Shop no. 101, Ground floor, Old Ishwa Nagar, Main Mathura Road, New Delhi-25.





M/s Sandoz Restaurants Pvt. Ltd., located at Shop no. 101, Ground floor, Old Ishwa Nagar, Main Mathura Road, New Delhi-25.

18	Refuge Area:				
	A	location	NA	NA	NA
	B	Total area	NA	NA	NA
19	Fire Control Room:				
	A	Fire detection system panel	NA	NA	NA
	В	Flow switch panel	NA	NA	NA
	C	P a system panel	NA	NA	NA
	D	Battery backup	NA	NA	NA
	E	Building floor plan	NA	NA	NA
20	Special Fire Protection for special risk if any				
	A Special Fire Protection system for Protection of Special Risk, if any:				NA

# Meeting requirement (MR), Not meeting requirement (NMR), Not applicable (NA), Not Provided (NP) Provide but not functional (PNF).

During the course of inspection it was observed that the restaurant is running at ground floor of the building. This restaurant is a part of the Premises bearing KH. no. 222, Revenue Estate of Village Bahapur, Mathura Road, New Delhi which has been already issued the FSC by this department vide letter no. F.6/DFS/MS/Business/2021/SZ/582 dated 24.11.2022

#### Note:-

The fixed fire installation has been provided & maintained by the building management which is common to the entire building. The installed system is of higher capacity and category then required for the individual restaurant and same was found functional at the time of inspection.

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under Rule 33, it is recommended to grant Fire Safety Certificate under Rules 35(3) of Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name Manoj Kumar Sharma

Designation DO (SD)

Signature of the Inspecting Officer Name Rajesh Kumar Shukla

Designation ADO (M. Road)

CFD, Mued 81/2023

Dinectar My

Nyeur

puty with ografula

0 d /6/53