



F6/DFS/MS/NDZ/2023/ 375

Dated: 08/08/2023

**FIRE SAFETY CERTIFICATE**

Certified that The Galleria Mall located at Plot No. 1-B, District Center, Mayur Vihar Phase -1, New Delhi, building comprised of Basement, Ground & Two Upper Floors, owned / occupied by The Galleria Mall, was issued FSC vide letter No. F6/DFS/MS/2020/NDZ/312 dated 17/08/2020. The premises were inspected by the team of officers concerned of this department on 25/07/2023 in presence of Mr. Rakesh Kumar (Manager) and observed that all the Fire Prevention and Fire Safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with rule 33 of the Delhi Fire Service Rule, 2010 and that the building is fit for occupancy class "Mercantile Building" (Group-F) with effect from 08/08/2023 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 08/08/2023 at New Delhi by.

  
(ATUL GARG)  
DIRECTOR

DELHI FIRE SERVICE

o/c @

**Copy to: -**

1. Mr. Rakesh Kumar (Manager), Galleria Condominium, Plot No. 1B, District Center, Mayur Vihar Phase -1, New Delhi-110092.

**Conditions for the validity of Fire Safety Certificate**

1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form 'J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
2. All the means of escape shall be kept free of all the type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
5. The basement shall be used strictly as per the provision of building bye laws.
6. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
7. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in).



## INSPECTION REPORT

1	Name & address of the building	DLF Galleria Mall at Plot No. 1B, District Center, Mayur Vihar Phase -1, New Delhi.		
2	Building is comprised of	Basement, Ground & Two Upper Floors.		
3	Type of occupancy	Mercantile		
4	Type of case	Renewal		
5	Details of previous FSC	F6/DFS/MS/2020/NDZ/312 dated 17/08/2020 ✓		
6	Fire safety directives letter no.	F.6/DFS/MS/2011/642/dated-11/04/2011 ✓		
7	Date of inspection	25.07.2023		
8	Name of the inspecting officers	Sh. A.K. Jaiswal, DO (ED) & Sh. Yashwant Singh Meena ADO (L.N)		
9	Name of the designation of officer from the building side	Mr. Rakesh Kumar (Manager)		
10	Year of construction	2008		
11	Applicant's letter no.	Outdoor Diary No.3723 dated 12/07/2023		
S.No	Minimum standard of fire prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR
1	<b>Access to Building:</b>			
	A Road width	12 mtrs.	24 mtrs.	MR ✓
	B Gate width	NA	NA	NA
	C Width of internal road	06 mtrs.	06 mtrs.	MR
2	<b>Number, Width, Type and Arrangement of Exits:</b>			
	<b>A Number of staircases</b>			
	a Upper floor	06 nos.	06 nos.	MR
	b Basement	09 nos.	09 nos. + 01 Ramp	MR
	<b>B Width of staircases</b>			
	a Upper floor	1.25 mtrs	1.5 mtrs.	MR
	b Basement	1.25 mtrs	1.5 mtrs. & 1no. of 1.75 mtrs.	MR ✓
	<b>C Protection of exits</b>			
	a Fire check door	Required	Provided	MR
	b Pressurization	Required	Provided	MR
	D No. of continuous staircases to terrace	02nos.	02 nos.	MR
	E Width of corridor	1.50 mtrs.	03 mtrs.	MR
	F Door size	1.0 mtrs	1.0 mtrs	MR
3	<b>Compartmentation:</b>			
	A Fire check door	Required	Provided	MR ✓
	B Sealing of electrical shafts	Required	Provided	MR
	C Fire rating of shaft door	2 hrs.	2 hrs.	MR
	D Water curtain	NA	NA	NA
	E Fire dampers	Required	Provided	MR
4	<b>Smoke Management System:</b>			
	A Basement	30 A/C per hour	30 a/c per hour	MR
	B Upper floor	12 A/C per hour	12 a/c per hour	MR

W A

✓

5.	<b>Fire Extinguisher:</b>			
A	Total numbers	70 nos.	70 nos.	MR
B	Types	ABC/CO <sub>2</sub>	ABC/CO <sub>2</sub>	MR
C	ISI marking	ISI Marked	Provided	MR
6	<b>First-Aid-Hose Reel:</b>			
A	Total numbers of each floor	05 nos.	05 nos.	MR
B	Length of hose reel hose	30 mtrs.	30 mtrs.	MR
C	Nozzle diameter	05 mm	05 mm	MR
7	<b>Automatic Fire Detection and Alarming System:</b>			
A	Type of detectors	Heat or smoke	smoke	MR
B	Location of main panel	Control Room	Provided	MR
C	Location of repeater panel	Reception	Provided	MR
D	Alternate source of power	Battery & DG Set	Provided	MR
E	Hooters	Different Location	Different Location	MR
8	<b>MOEFA:</b>	Required	Provided	MR
9	<b>Public Address System:</b>	Required	Provided	MR
10	<b>Automatic Sprinkler System:</b>			
A	Basement	Required	Provided	MR
B	Upper floor	Required	Provided	MR
C	Sprinkler above false ceiling	Required	Provided	MR
11	<b>Internal Hydrants:</b>			
A	Size of riser/down-comer	150 mm	150 mm	MR
B	Number of hydrants per floor	05 nos.	05 nos.	MR
C	Hose box	05 nos.	05 nos.	MR
12	<b>Yard Hydrants:</b>			
A	Total number of hydrants	06 nos.	08 nos.	MR
B	Hose box	06 nos.	08 nos.	MR
13	<b>Pumping Arrangements:</b>			
1	<b>Ground level</b>			
A	Discharge of main pump	4500 LPM	4500 LPM	MR /
B	Head of main pump	60 mtrs.	60 mtrs.	MR
C	Number of main pumps	02 nos.	02 nos.	MR
D	Jockey pump out put	450 LPM	450 LPM	MR
E	Jockey pump head	60 mtrs.	60 mtrs.	MR
F	Standby pump out put	4500 LPM	4500 LPM	MR
G	Standby pump head	60 mtrs.	60 mtrs.	MR
H	Auto starting /manual stopping	Required	Auto	MR
I	Pump house access	Required	Provided	MR
2	<b>Terrace Level</b>			
A	Discharge of pump	900 LPM	900 LPM	MR
B	Head of the pump	60 mtrs	60 mtrs	MR
C	Power supply	Required	Auto	MR
D	Auto starting of pump	Required	Provided	MR

W X



14	<b>Captive Water Storage for Fire Fighting:</b>			
A	Underground tank capacity	4,50,000 liters.	4,50,000 liters.	MR
B	Draw-off connection	Required	Provided	MR
C	Fire service inlet	Required	Provided	MR
D	Access to tank	Required	Provided	MR
E	Overhead tank capacity	20,000 liters	20,000 liters	MR
		Required	Provided	MR
15	<b>Exit Signage:</b>			
16	<b>Provision of Lifts:</b>			
A	Pressurization of lift shaft	Required	Provided	MR
B	Pressurization of lift lobby	Required	Provided for Basement	MR
C	Communication in lift car	Required	Provided	MR
D	Firemen's grounding switch	Required	Provided	MR
E	Lift signage	Required	Provided	MR
17	<b>Standby Power Supply:</b>			
18	<b>Refuge Area:</b>			
A	Total area	NA	NA	NA
B	Location	NA	NA	NA
19	<b>Fire Control Room:</b>			
A	Detector system panel	Required	Provided	MR
B	Flow switch panel	Required	Provided	MR
C	PA system panel	Required	Provided	MR
D	Battery backup	Required	Provided	MR
E	Building floor plans	NA	NA	NA
20	Special Fire Protection systems for protection of special Risks, if any:	NA	Manually Operated CO <sub>2</sub> fire extinguishers provided.	MR

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Mercantile the FSC issued vide letter no. F6/DFS/MS/2020/NDZ/312 dated 17/08/2020 is recommended to be renewed.

Signature of the Inspecting Officer  
Name: A.K. Jaiswal  
Designation: DO (ED)

Signature of the Inspecting Officer  
Name: Yashwant Singh Meena  
Designation: ADO (L.N)

Dy. CFO (NDZ)

DO (ED) + ADO (LN)  
Specimen with Dy CFO (NDZ) with ADO (L.N) & need follow

11/8/2023

Dy CFO (NDZ)

11/8/23

11/8/23