GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F6/DFS/MS/2023/WZ/School/ 570

FIRE SAFETY CERTIFICATE

Dated: 22/08/2023

Certified that the Nursery School (Rohini Educational Society), F-Block, Prashant Vihar, Rohini, Delhi-110085 comprised of Basement + Stilt + Ground + 02 upper floors was inspected by the officer concerned of this department on 03.08.2023 in the presence of Mr. R. N. Jindal (Owner) and found that the said premises have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules,2010 and that the premise is fit for occupancy Group B Educational for with effect from 22 08 2023 for a period of 03 (Three) years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 22/08/2023.. at New Delhi by

(Aful Garg) DIRECTOR Ph; 011-23414000

012

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sect. Delhi - 54.

2. The Principal, Nursery School (Rohini Educational Society), F-Block, Prashant Vihar, Rohini, Delhi-110085.

Conditions for the validity of Fire Safety Certificate:

- All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management/occupier.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

INSPECTION REPORT

1. Name & address of the building: Nursery School (Rohini Educational Society), F-Block, Prashant

Vihar, Rohini, Delhi-110085.

2. Type of Occupancy : Educational

: New Case (Basement + Stilt + Ground + 02 upper floors) 3. Type of Case

: NA 4. Details of Previous NOC

: F.6/DFS/MS/BP/2022/102 dated 07.03.2022 5. Fire Safety directives letter No

6. Date of inspection : 03.08.2023

: Sh. Ajay Kumar Sharma (ADO Rohini) D.B Mukherjee, DO (NW) 7. Name of Inspecting Officer

8. Name and designation of officers

: Sh. R. N. Jindal (Owner) From the building side

10. S. No.	Minimum Standards on fire prevention	NBC Requirement		Remarks MR/NMR
	and fire safety U/R 33 Access to building		12.0-	MR
	EARE DE UNITED DE LA CONTRACTOR DE LA CO	13.0m	13.0m	MR
	Road width Gate width	4.5m	5.0m NA	NA
	Width of internal road	NA	NA	
2.	Number, Width, Type & Arrangement of	Exits		
	a. Number of staircases	02	02	MR
	Upper Floors		02	MR
	Basements	02		
	b. Width of staircases	15-	2 x 1.5m	MR
	Floor	1.5m	2 x 1.5m	MR
		1.5m	2 X 1.3III	- 4.4
	c. Protection of exits	Required in basement & lift	Provided	MR
	Fire check door	lobby	NA	NA
		NA	02	MR
	Pressurization	02	Provided	MR
	d. No. of continuous staircases to terrace	Required	NA	NA
	e. Width of Corridor	NA	NA NA	
	f. Door Size			144
3.	Compartmentation Required in			
<u>. </u>	Fire check door	basement & lift	Provided	MR
		NA	NA	NA
	Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door		NA	NA
	Water Curtain	NA	ŇA	NA
	Fire Dampers	NA		
4.	Smoke Management System	10 -/- nor hou	r Exhaust fan	MR
	Basements	12 a/c per hou		i MR
	• Upper floors	12 a/c per hou	I Natural Venilla	
	Fire Extinguishers		15nos.	MR
5.	Total numbers	14nos.	ABC-15nos.	MR
	Types	ABC/CO2	Yes	MR
	IS marking	ISI marked	168	
-	First Aid Hose Reels	01	Provided	MR
6.	Total numbers on each floor		Provided	MR
	Length of hose reel hose	30mm	Provided	MR
1.0	Nla diameter	5m	Tiorided	
-	Automatic fire detection and alarming	system	NA NA	NA
7.	Type of detectors	NA	111.	

				,	
	Location of Main Panel	NA	NA	N	
	Location of Repeater Panel	NA	NA	N	
	Alternate source of power	NA	NA	N	
	Hooters' Location	NA	NA	N	
	· · · · · · · · · · · · · · · · · · ·	NA	NA	N	
8.	MOEFA Public Address System	NA	NA	N	
9.	Automatic Sprinkler System				
10.	Basement	Required	Provided	M	
	Ground & Upper Floors	NA	NA	N.	
	Sprinkler above false ceiling	NA	NA	N.	
11	Internal Hydrants	(A) A - A	and public to		
11.	Size of riser/down-comer	100mm	Provided	M	
	Number of hydrants per floor	01nos.	Provided	M	
	Hose Box	01nos.	Provided	M	
10	Yard Hydrants	The state of the state of	The second second	1	
12.	Total number of hydrants	Required	Provided	M	
	Hose Box	Required	Provided	M	
13.	Pumping Arrangements		Transfer of Victoria		
13.	Ground Level	£2.	Water State of the		
	➤ Discharge of main Pump	NA	NA	N.	
		NA	NA	N/	
	 ➢ Head of Main pump ➢ Number of main pumps 	NA	NA	N/	
		NA	NA	N/	
	> Jockey Pump out put	NA	NA	N/	
	> Jockey pump head	NA	NA	N/	
	> Standby Pump out put	NA	NA	N/	
	> Standby Pump Head	NA NA	NA	N/	
	 Auto Starting/Manual Stopping 		100000	N/	
	> Pump House Access	NA	NA	142	
	Terrace level	201	0001	M	
	Discharge of pump	90lpm	900lpm 40m	M	
	> Head of the pump	40m	Provided	M	
	> Power Supply	Required	Provided	MI	
	> Auto Starting of pump	Required	riovided	141	
14.	Captive Water Storage for fire fighting				
2): USA (SA)	Underground tank capacity	NA	NA	N/	
	> Draw-off connection	NA	NA	NA NA	
	> Fire service inlet	NA	NA NA	NA NA	
	> Access to tank	NA	NA 15 0001		
	Overhead Tank capacity	15,000ltr	15,000ltr	MI	
15.	Exit Signage.	Required	Provided	MI	
16.	Provision of Lifts.	* * *	4-9017-957		
• • •		Required	Provided	MI	
	Pressurization of Lift Shaft Pressurization of Lift labby	Required	Provided	Mi	
	 Pressurization of Lift lobby Communication In lift Car 	NA	NA	N/A	
	Fireman's Grounding SwitchLift Signage	Do militar di	Provided	MI	
		Required		MI	
17.	Standby power supply	Required	Provided	IVII	
18.	Refuge Area.		NAME OF BRIDE		
11/1	> Total Area	NÁ	NA	N/	
	> Location	NA	NA	N/	
19.	Fire Control Room	1.51			
	Detector System Panel	NA	NA	N/	
		NA	NA	N/	

NA NA	NA NA	NA NA
ŇA	NA	N/A
		5
NA	NA	NA
e of the minimum	standards on fire pro	evention a
	building were test	building were test checked and found e of the minimum standards on fire proded to grant Fire Safety Certificate und

Signature of the Inspecting Office Name: - D.B Mukherjee Designation:- DO/NW

Signature of the Inspecting Officer Name: - Ajay Kumar Sharma Designation:- ADO/Rohini

Dinectar Many

KMIL SIAL use was the ful for 4 to

Any Roby

Sparing 12

Anylong

FT letter to four ly for hind personal and Condia

Director My M

P1/8/53