

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE  
NEW DELHI-110001**

No. F.6/DFS/MS/EH/2023/SZ/264

Dated..22/08../2023

**FIRE SAFETY CERTIFICATE**

Certified that the Eating House in the Name & Style of M/s Silly located at 3<sup>rd</sup> Floor in the building comprised of 02 tire Basement, Ground plus 03 upper floors at Plot No 1 to 7, LSC, Lado Sarai, MG Road, New Delhi 110030 owned/occupied by Unit of K7 Group Hospitality Pvt Ltd was issued Fire Safety Certificate by this department vide letter no F6/DFS//MS/2011/EH/753 dated 26/04/20211 in name of Smoke House Room Restaurant. The restaurant premises was re-inspected by the officer concerned of this department on 09/08/2023 on in the presence of Mr. Rajiv Goyal and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the building/premises is fit for occupancy class **Group-D Assembly Building** (Restaurant running at 3<sup>rd</sup> Floor only) and **Validity upto 31/03/2026** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 22/08 /2023 at New Delhi by

(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE

Copy to: -

1. The Dy. Health Officer, Public Health Department, South Zone, Aurobindo Marg, Green Park, Delhi-110016 (MHA Portal ID 2023072413097 dated 25/07/2023)

**Conditions for the validity of Fire Safety Certificate: -**

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

## INSPECTION REPORT

1	Name & Address of the Building	M/s Silly (Unit of K7 Group Hospitality Pvt Ltd) located at Local Shopping Complex located at Plot No 1 to 7, Lado Sarai, MG Road, New Delhi 110030		
2	Type of Occupancy	Eating House at 3 <sup>rd</sup> Floor		
3	Building Comprised of	02 tire Basement, Ground plus 03 Upper Floor		
4	Type of Case	Renewal		
5	Details of Previous NOC	F6/DFS//MS/2011/EH/753 dated 26/04/20211 in name of Smoke House Room Restaurant.		
6	Fire Safety Directives Letter No	F6/DFS/MS/Mercantile/2023/SZ/326 dated 07/07/2023		
7	Date of Inspection	09/07/2023		
8	Name of the Inspecting Officers	DO (SD) & ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Rajiv Goyal (Manager)		
10	Year of construction	2000		
11	Applicant letter No.	MHA Portal ID 2023072413097 dated 25/07/2023		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	UBBL 2016 Requirements	Provided at Site	Remarks MR/NMR
1	Access to Building.	<b>F6/DFS/MS/Mercantile/2023/SZ/326 dated 07/07/2023 building NOC</b>		
	Road width	Required	60 mtr	MR
	Gate width	Required	06 mtr	MR
	Width of internal road	Required	06 mtr	MR
2	Number, width, type & arrangement of exits.	Fire Safety arrangement provided in the Building		
	Number of Staircase	02 Nos		Provided* MR
	Upper floors.	02 + 02 ramp		Provided* MR
	Basement floor.			
	Width of Staircase			
	Upper floors	1.50m each	Provided*	MR
	Basement floor	1.50m each & 2 mtr ramp	Provided*	MR
	Protection of exits			
	Fire check door	Required	Provided*	MR
	Pressurization	N/A	N/A	N/A
	No. of continuous staircase to terrace	02 Nos	Provided	MR
	Width of corridor	N/A	N/A	N/A
	Door size	02 Nos	1.50m x 2	MR
3	Compartmentation.	Fire Safety arrangement provided in Building		
	Fire check door.	Required	Provided*	MR
	Sealing of electrical shafts.	Required	Provided*	MR
	Fire rating of shaft door.	Required	Provided*	MR
	Water curtain	Required	Provided*	MR
	Fire dampers.	Required	Provided*	MR
4	Smoke Management system.	Fire Safety arrangement provided in Building		
	Basement	30 ACPH	Mechanical	MR
	Upper floors	12 ACPH	Natural	MR
5	Fire Extinguishers.	Fire Safety arrangement provided in Building		
	Total numbers	Required	6 Nos	MR
	Types	ABC/CO <sub>2</sub>	ABC & CO <sub>2</sub>	MR
	ISI Marking	Required	Provided	MR
6	First Aid Hose Reels.	Fire Safety arrangement provided in Building		
	Total numbers on each floor.	Required	01 at near restt.	MR
	Length of hose-reel hose.	30m	Provided*	MR
	Nozzle Diameter	5mm	Provided*	MR
7	Automatic fire detection & alarming system.	Fire Safety arrangement provided in Building		
	Type of detectors	Smoke / Heat & Beam	Provided*	MR
	Location of Main Panel	Required	Provided*	MR
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	Required	Provided*	MR

	Hooter's location	Required	Provided*	MR
8	MOEFA	Required	Provided*	MR
9	Public Address System	Required	Provided*	MR
10	Automatic Sprinkler System	Fire Safety arrangement provided in Building		
	Basement	Required	Provided*	MR
	Upper floor	Required	Provided*	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.	Fire Safety arrangement provided in Building		
	Size of Riser/Down-comer	Required	Provided*	MR
	Number of Hydrant per floor	Required	Provided*	MR
	Hose box.	Required	Provided*	MR
12	Yard Hydrants.	Fire Safety arrangement provided in Building		
	Total number of hydrants.	Required	Provided*	MR
	Hose box.	Required	Provided*	MR
13	Pumping arrangements.	Fire Safety arrangement provided in Building		
	Ground Level	Fire Safety arrangement provided in Building		
	Discharge of main pump.	2850 LPM	Provided*	MR
	Head of main pump.	70m	Provided*	MR
	Number of main pumps.	01 No	Provided*	MR
	Jockey Pump output.	180 LPM	Provided*	MR
	Jockey Pump head.	70m	Provided*	MR
	Standby Pump output.	2850 LPM	Provided*	MR
	Standby Pump head.	70m	Provided*	MR
	Auto Starting/Manual Stopping.	Required	Provided*	MR
	Pump house access.	Required	Provided*	MR
	Terrace Level	Fire Safety arrangement provided in Building		
	Discharge of pump.	450 LPM	Provided*	MR
	Head of pump.	39 m	Provided*	MR
	Power supply.	Required	Provided*	MR
	Auto starting of pump.	Required	Provided*	MR
14	Captive water storage for fire fighting.	Fire Safety arrangement provided in Building		
	Underground tank capacity.	25,000 ltr	Provided*	MR (old case)
	Draw-off connection.	Required	Provided*	MR
	Fire Service Inlet.	Required	Provided*	MR
	Access to tank.	Required	Provided*	MR
	Overhead tank capacity.	50,000 ltr	Provided*	MR
		Required	Provided*	MR
15	Exit Signage.	Fire Safety arrangement provided in Building		
16	Provision of Lifts.	Fire Safety arrangement provided in Building		
	Pressurization of lift shaft.	Required	Provided*	MR
	Pressurization of lift lobby.	Required	Provided*	MR
	Communication in lift car.	Required	Provided*	MR
	Fireman's switch.	Required	Provided*	MR
	Lift signage.	Required	Provided*	MR
17	Standby Power Supply	Required	Provided*	MR
18	Refuge Area			
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room.			
	Detector system panel.	N/A	N/A	N/A
	Flow switch panel.	N/A	N/A	N/A
	PA system panel.	N/A	N/A	N/A
	Battery backup.	N/A	N/A	N/A
	Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	Required	Provided	MR

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/2011/EH/753 dated 26/04/2011 in name of Smoke House Room Restaurant, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

*Me*

Signature of the Inspection Officer  
Name: Sh. Manoj Kumar Sharma  
Design: DO (South)

*11/8/2023*

Signature of the Inspecting Officer  
Name: Sh. Rajesh Kumar  
Design: ADO (BCP)

CFO (HQ)

*11/8/2023*

*Director*

*If less area of Rent is  
more? Please what the  
area of resturint.*

*14/8/23*

*ADY/ADP*

The area of the restaurant as mentioned in the MHA Portal is 100 sqm, and plan endorsed with Portal is 204 sqm. Earlier, there was a restaurant which was running in the name and style of M/s Smoke House Room Restaurant and issued with FSC by this deptt vide letter of even no 753 dated 26/04/2011 in the same place. Hence, the file is being forwarded & recommended for further order in the matter submitted @

*1/14  
15/08/2023*

*Director*  
*FIPB*  
*ADY/ADP*