Ve.

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/Educational/2023/SZ/24

Dated: 23/08/2023

## FIRE SAFETY CERTIFICATE

Certified that the Surajmal Memorial Education Society (Regd.), C-4, JanakPuri, New Delhi-110058 comprised of two blocks namely block D & block G (interconnected at third floor level). Both Block is comprised of stilt plus seven upper floors, owned/occupied by M/s Surajmal Memorial Education Society (Regd.). The building was inspected by the officers concerned of this department on 17/08/2023 in presence of Sh. Ajeet Singh Choudhary (Secretary) and found that the building have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi fire service Rules 2010 and that the building/premises ( D & G block only) is fit for occupancy class "Educational" w.e.f the date of issue of this certificate for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 23 08 2023 at New Delhi.

Director Delhi Fire Service

Copy to: -

1. Sh. Ajit Singh Chaudhary (Secretary), Surajmal Memorial Education Society (Regd.), C-4, JanakPuri, New Delhi-110058.

## Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.

3. Internal road of 06 m should be kept free from obstructions.

4. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

5. The trained staff should be available round the clock.

 Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

7. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

8. Basement shall be used as per the building bye laws.

9. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

10. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months

prior to its expiry.

Building is comprised of two blocks namely block D & block G (interconnected at third floor level). Both Block is comprised of stilt plus seven upper floors.

INSPECTION REPORT

	INSPECTIO	N REPORT		4 Janak Puri			
	1. Name & address of the building: Surajmal Memorial Education Society (Regd.), C-4, JanakPuri, New Delhi-110058						
	2. Type of Occupancy : Educational						
	3. Type of Case : New						
	4. Details of Previous NOC : Nil 5. Fire Safety directives letter No : F6/DFS/MS/BP/2018/161 dated 22/05/2018 6. Date of inspection : 17/08/2023						
	7. Name of Inspecting Officer : A. D.O. R.K. Yadav & DO VedpalChhikara						
	8. Name and designation of officers						
	From the building side : Sh. Ajeet Singh Choudhary (Secretary) 9. Year of Construction : 2021-2022						
		z SMES/2023/99/519 da	ated 09/08/2023				
	10. Applicant's letter No. : Ref. No.    Minimum Standards on fire prevention and	Requirement	Provided at	Remarks			
. No.		Requirement	site	MR/NMR			
	fire safety U/R 33		Site				
	• Road width	18 m	18 m	M/R			
		06 m	06 m	M/R			
	Gate width	The second secon	Provided	MR			
	Width of internal road	06 m with 9 m radius	Flovided	17.			
2.	Number, Width, Type & Arrangement of Exits						
323	a. Number of staircases	2.00		14/0			
	Upper Floors	02 no.'s each blk	Provided	M/R			
	Basements	N/A	N/A	N/A			
	b. Width of staircases		N. Salandaran				
	Hann Floor	1.50 m each blk	1.96 m each blk	MR			
	Upper Floor     Basement	N/A	N/A	N/A			
			The transfer best was				
	c. Protection of exits	Required	Provided	M/R			
	Fire check door	Required	Provided	MR			
	Pressurization						
	d. No. of continuous staircases to	Two no. each blk	Provided	M/R			
	terrace	VIVE 2740 (MATERIAL RESILENCE FOR SEXUE OF A SECTION OF A	2.50 m	M/R			
	e. Width of Corridor	1.50 m	@107/92/8/2/00/06/8/8				
	f. Door Size	1.20 m	Provided	M/R			
3.	Compartmentation	F9321					
	Fire check door	Required	Provided	M/R			
	Sealing of electrical shafts	Required	Provided	M/R			
	Fire Rating of shaft door     Wotor Contain	N/A	N/A	N/A			
	Water Curtain     Fire Dampers	N/A	N/A	N/A			
	The Dampers	N/A	N/A	N/A			
4.	Smoke Management System						
	Basements	N/A	N/A	N/A			
	Upper floors	Required	Provided	M/R			
5.	Fire Extinguishers						
	Total numbers	08 no.'s each floors	Provided	M/R			
	• Types	POLYNIA TOWN AND THE TOWN	Provided	M/R			
	IS marking	ABC/ CO₂type	Provided	M/R			
_	That king	ISI marked	Provided	IVII			

& h

	First-Aid Hose Reels	1/25		-100	
	Total numbers on each floor	01 no.'s each blk	Provided	M/R	
	<ul> <li>Total numbers on each floor</li> <li>Length of hose reel hose</li> </ul>	30 M	Provided	M/R	
	Nozzle diameter	05 MM	Provided	M/R	
	Automatic fire detection and alarming syst	em		21/4	
	Automatic fire detection and alarming sys-	N/A	Provided	N/A	
	Type of detectors     SMain Panel	N/A	N/A	N/A	
	<ul> <li>Location of Main Panel</li> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A	
	1 to the source of nower	N/A	N/A	N/A	
	Hooters' Location	N/A	N/A	N/A	
	• Hooters Became	Required	Provided	M/R	
3.	MOEFA	Required	Provided	M/R	
9.	Public Address System	- 13-1		NI/A	
10.	Automatic Sprinkler System	N/A	N/A	N/A N/A	
	Basement	N/A	N/A		
	Ground Floor     Floo cailing	N/A	N/A	N/A	
	Sprinkler above false ceiling			M/R	
11.	Internal Hydrants	01 no.'s each blk	Provided	M/R	
	Size of riser/down-comer	1 Nos.	Provided	M/R	
	<ul> <li>Number of hydrants per floor</li> </ul>	1 Nos.	Provided	IVIX	
	Hose Box			M/R	
12.	Yard Hydrants	Required	Provided	M/R M/R	
	Total number of hydrants	Paguired	Provided	MIX	
	Hose Box	umping arrangement with old building			
13.	I umpB	nping at range		M/R	
	Ground Level     Growin Bump	1620 LPM	2850 LPM	M/R	
	> Discharge of main Pump	60 m	70 m	M/R	
	> Head of Main pumps	One	Provided		
	<ul><li>Number of main pumps</li><li>Jockey Pump out put</li></ul>	180 LPM	Provided	M/R	
	<ul> <li>Jockey Pump out put</li> <li>Jockey pump head</li> </ul>	60 m	Provided	M/R	
	> Standby Pump out put	1620 LPM	2850 LPM	M/R	
	Standby Pump Head	60 m	70 m	M/R	
	> Auto Starting/Manual Stopping	Required	Provided	M/R	
5	All.	N/A	N/A	N/A	
	> Pump House Access	13/73	or out and the second	· ·	
	Terrace level	N/A	900 LPM (ou go	M/R	
	Discharge of pump	N/A	Provided	M/R	
	➤ Head of the pump	N/A N/A	Provided	M/R	
	<ul><li>Power Supply</li><li>Auto Starting of pump</li></ul>	N/A	Provided	M/R	
		1074	_0		
14.	Captive Water Storage for fire fighting	50,000 ltrs	2,00,000 Ltrs.	M/R	
14.	Linderground tank capacity		Provided	M/R	
	> Draw-off connection	Required	Provided	M/R	
	> Fire service inlet	Required	Provided	M/R	
	<ul> <li>Access to tank</li> <li>Overhead Tank capacity</li> </ul>	Required		1 11	
	Overnead 1 and capacity	5,000 ltrs	25,000 Ltrs 0	At at A	
		Required	Flovided	M/R	

1/4 W

1 /	Provision of Lifts.  Pressurization of Lift Shaft	Required	Provided	M/R	
M	Pressurization of Lift lobby Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage	Required	Provided	M/R	
		Required	Provided	M/R	
100		Required	Provided	M/R	
		Required	Provided	M/R	
	Standby power supply	Required	Provided	M/R	
	> Location	6 <sup>TH</sup> Floor	Provided	M/R	
	> Location	6 <sup>TH</sup> Floor	Provided	M/R	
$\overline{}$	Fire Control Room				
$\overline{}$	Detector System Panel	N/A	Provided	N/A	
ri i	Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel     Battery backup	Required	Provided	M/R	
	Building Floor Plans	Required	Provided	M/R	
	S S S S S S S S S S S S S S S S S S S	N/A	N/A	N/A	
	Special Fire Protection System for Protection of special Risks, if any:	Required	HT & LT Panels provided	M/R	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings issued vide letter No.F6/DFS/MS/Educational/2023/SZ/18 dated 04/05/2023 has been rectified.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under Rule 35 of the Delhi Fire Service Rule 2010.

Note:-Common pumping arrangement with old building.

Signature of Inspecting Officer

Name:-R.K.Yaday

Designation:-Asstt. Divisional Officer

Signature of Inspecting Officer

Name:- VedpalChhikara Designation:- DO(SW)

Dineda M 2023

Sn

A DO FURRORY

21/8/23