C 15

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DE LHI FIRE SERVICE, NEW DELHI-110001

No.F.6/DFS/MS/School/2023/NDZ/583

FIRE SAFETY CERTIFICATE

Certified that the Sibbal International School at F-17, Ankur Enclave, Karawal Nagar, Delhi110094, building comprised of Ground & Three upper floors only, owned / occupied by Sibbal
International School, was issued FSC vide letter No. F6/DFS/MS/NDZ/School/256 Dated
30/07/2020. The school building was re-inspected by the officer concerned of this department on
18/08/2023 in presence of Sh. Ashok Baisoya (Director) and observed that all the fire prevention and fire
safety arrangements provided in the premises found in good working condition. The premises have
therefore deemed complied with NBC (Part-IV) and that the building is fit for occupancy class
"Educational" (Group-B) with effect from .24/08. 12023. for a period of three years, in accordance
with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of
the conditions under rule 38 of the DFS rule 2010.

Issued on 24/08/2023 at New Delhi by

DIRECTOR
DELHI FIRE SERVICE

Copy to:-

1. The Director, Sibbal International School, F-17, Ankur Enclave, Karawal Nagar, Delhi-110094.

2. The Dy. Director of Education, B-Block, Yamuna Vihar, Delhi-110053.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided therein shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the Management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction, if any.
- 6. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1. Name & address of the building: Sibbal International School, F-17, Ankur Enclave

Karawal Nagar, Delhi-110094.

2. Building is comprised of : Ground & Three upper floors.

3. Type of Occupancy : Educational 4. Type of Case : Renewal 5. Details of previous NOC

: F6/DFS/MS/NDZ/School/256 Dt. 30/07/2020 6. Fire Safety directives Letter No.: NBC (Part-IV) 7. Date of inspection : 18/08/2023

8. Name of the Inspecting Officer: A.K. Jaiswal, D.O. (E.D.)

9. Name and designation of Officer

from the building side : Sh. Ashok Baisoya (Director)

10. Year of Construction

S.No.	Minimum Standards on fire	NBC NBC	4314 dated 31/07/202 Provided at Site	Remark		
	prevention and fire safety U/R 33	Paguiroment		Remark		
1	Access to building					
	Road width	06 m	06 m	M/R		
	Gate width	N/A	N/A	N/A		
	Width of internal road	N/A	N/A	N/A		
2	Number, Width, Type and Arrangement of Exits					
	a. Number of Staircases					
	Upper Floor	01	02	M/R		
	➤ Basement	N/A	N/A	N/A		
	b. Width of Staircases		The state of the s	1		
	Upper Floor	1.50 m	1.65m & 1.25m	M/R		
	Basement	N/A	N/A	N/A		
	c. Protection of exits		7 14 15			
	Fire check door	N/A	N/A	N/A		
	 Pressurization 	N/A	N/A	N/A		
1	d. No. of continuous staircases to terrace	1	1	M/R		
	e. Width of Corridor	1.50 m	1.70 m	M/R		
1	f. Door size	1.00 m	1.00 m	M/R		
3	Compartmentation					
	Fire check Door	N/A	N/A	N/A		
	 Sealing of electrical Shafts 	N/A	N/A	N/A		
	 Fire rating of Shaft Door 	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
1	Smoke Management System					
	Basement	N/A	N/A	N/A		
	Upper Floors	N/A	N/A	N/A		
5	Fire Extinguishers					
	Total Numbers	9	12	M/R/		
	• Types	ABC & Co2	ABC & Co2	M/R		
el Guis	IS Marking	ISI Marked	ISI Marked	M/R		



	First-aid-Hose Reels	1	1	M/R		
	• Total numbers of each floor	30m	30m	M/R		
	 Length of hose reel hose 	5mm	5mm	M/R		
	Nozzle diameter		17. 1			
2	Automatic fire detection and alarming	system	N/A	N/A		
	 Type of detectors 	N/A	N/A	N/A		
	 Location of main panel 	N/A	N/A	N/A		
	 Location of repeater panel 	N/A	N/A	N/A		
	 Alternate source of power 	N/A	N/A	N/A		
	 Hooter's location 	N/A		N/A		
3	MOEFA	N/A	N/A	N/A		
9	Public address System	N/A	N/A	1,7,1		
10	Automatic Sprinkler System		Tarva	N/A		
	Basement	N/A	N/A	N/A		
	Upper Floor	N/A	N/A			
	Sprinkler above false Ceiling	N/A	N/A	N/A		
11	Internal Hydrants			NI / A		
	Size of rise/down-comer	N/A	Provided	N/A		
	Number of Hydrants per Floor	N/A	Provided	N/A		
	Hose Box	N/A	Provided	N/A		
12	Yard Hydrants		WA EXPERIENCE			
	Total number of Hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements					
	• Ground Level					
	➤ Discharge of main Pump	N/A	N/A	N/A		
	➤ Head of Main Pump	N/A	N/A	N/A		
	Number of main Pumps	N/A	N/A	N/A		
	> Jockey pump output	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A		
	> Standby pump output	N/A	N/A	N/A		
	Standby pump head	N/A	N/A	N/A		
	> Auto starting/Manual stopping	N/A	N/A	N/A		
	Pump house access	N/A	N/A	N/A		
	Terrace Level					
	Discharge of pump	450LPM	450LPM	M/R		
	> head of the pump	40 m	40 m	M/R		
	> Power supply	Required	Provided	M/R		
	Auto Starting of pump	Required	Provided	M/R		
14						
14	Underground tank capacity	N/A	N/A	N/A		
	> Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
	> Access to tank	N/A	N/A	N/A		
1	overhead Tank capacity	10,000ltrs	10,000ltrs	M/R		
		LUJUUUILIS	20,0001113	1 / Ivi / IX		



16	Provision of Lifts				
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication in lift car	N/A	N/A	· N/A	
	Firemen's grounding switch	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
17	Standby power supply	N/A	N/A	N/A	
18	Refuge Area				
	Total area	N/A	N/A	N/A	
	• Location	N/A	N/A	N/A	
19	Fire Control Room				
	Detector system panel	N/A	N/A	N/A	
	Flow switch panel	N/A	N/A	N/A	
	PA system panel	N/A	N/A	N/A	
	Battery backup	N/A	N/A	N/A	
	Building floor plans	N/A	N/A	N/A	
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested, checked and found

functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required as per NBC (Part-IV), The Fire Safety Certificate issued vide letter no. F6/DFS/MS/NDZ/School/256 Dt. 30/07/2020 is recommended to be renewed.

Signature of the Inspecting Officer Name: Ashok Kumar Jaiswal Designation: D.O. (East. Div.)

2/09/20 Doftens F.T. is added for segmature pl.

Dis-ector