

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001**

No. F.6/DFS/MS/2023/SZ/ 418

Dated: 01/09/2023

FIRE SAFETY CERTIFICATE

Certified that the International Management Institute, situated at Plot No B-10, 30 & 31 Qutab Institutional Area, Tara Crescent, New Delhi-110016 having two Building Blocks-Hostel Block (comprised of Basement, Ground & 3 Upper Floors) and Residential Block (comprised of Ground & 04 Upper Floors) was issued FSC by this department vide letter No. F6/DFS/MS/SZ/2017/1261 dated 23/08/2017. These two blocks Hostel Block and Residential Block were inspected by the officer concerned of this department on 22/08/2023 in the presence of Mr. Rajender Singh (Registrar) and found that the said building blocks have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that these building blocks is deemed fit for occupancy class "Group- A (Residential)" with effect from 01/09/ /2023 for a period of five years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on O. J. J. 2023 at New Delhi by.

Copy to:-

1. The Executive Engineer (Bldg.), Building Department, South MCD, Civic Center, Minto Road, New Delhi-110002

2. The Registrar, International Management Institute, B-10, 30 & 31 Qutab Institutional Area, Tara Crescent, New Delhi-110016.

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. The basement shall be used as per the provisions of UBBL /NBC Part- IV.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first available form Service Rules 2010. The of Delhi Fire www.dfs.delhigovt.nic.in

6. This fire safety certificate may not in any way be treated as regularization of unauthorized

construction, if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

International Management Institute, B-10, 30 & 31, Quiab Institutional Area, Tara Crescent, New Delhi-110016

INSPECTION REPORT

1. Name& address of the building: International Management Institute, B-10, 30 & 31 Qutab Institutional Area, Tara Crescent, New Delhi-110016 : Class-A Residential" Type of Occupancy

[Two blocks: Hostel Block (B+G+3 UF) : Renewal 3. Type of Case & Residential Block (G + 4 UF)] : F6/DFS/MS/SZ/2017/1261 dated 23/08/2017

4. Details of Previous NOC 5. Fire Safety directives letter No: F6/DFS/MS/92/1085 dated 04/06/1992

: 22/08/2023 6. Date of inspection

: DO (South) & ADO (BCP) 7. Name of Inspecting Officer

S. No.	Mini	letter No. : num Standards on fir fety U/R 33	e prevention and	4462 dated 03/08/20 BBL/NBC Requirement	Provided at site	Remarks
1.	Access to building				12030	MR/NMR
	•	Road width		9m	7 7 11	
		Gate width		5m and	Provided 4.5m	MR
	6 .	Width of internal roa	d rov	6m	4.5m Provided	MR (old Case)
2.	Numi	er, Width, Type & A	rrangement of Ex	its	Trovided	MR
		mber of staircases			interaction of the Land	arduma 'e
- 3	VI I	2230 & 15001 (%)	Theropolit	2 Nos in Hostel	THE LETT SALE OF THE SALE OF T	
38	V .	Upper Floors		Block&1 Nos in	Provided	MR
50	V	Opper Pioors		Residential Block	Head of Main and	
- 9		Basements	Beggined	2 Nos	Provided	MR
- 6	h Wi	th of staircases			and common and all	IVIK
		Upper Floor		1.2m	Provided	MR
25	0	Basements		1.2m	Provided	311/2 (S.X-24
51	c Pro	ection of exits		mung 2 leum	2000 707 700	MR
SI		Fire check door		Required	Provided	100
-5%	4	Pressurization		-NA-	-NA-	MR
	d.	No. of continuous sta	ircases to terrace	Required	0.0000000000000000000000000000000000000	-NA-
-4	е.	Width of Corridor	-A.M-	1.5m	Provided	* MR
40	f.	Door Size			1.2111	MR (Old Case
3.	Comre	rtmentation	4/4/2	lm	1m (final exit)	MR
		and the second second	- 104		 Auto Shiring of r 	
	•	Fire check door		Required	Provided	MR
Case	0.70%	Sealing of electrical si	The second secon	Required	Provided	MR
8	F	Fire Rating of shaft do Water Curtain	Required	-NA-	-NA-	-NA-
11		Fire Dampers	7 beaugests	-NA-	-NA-	-NA-
				-NA-	-NA-	-NA-
l. "	Smoke	Management System	A CONTRACTOR OF THE PARTY OF TH	July Control	avasiness Turk cause	
8	•	Basements	Required	30 a/c per hour	Exhaust Fan	MR
	•	Upper floors	Instituted	12 a/c per hour	Natural Ventilation	MP
		tinguishers	444	0.11	(4411-11111)	mg roathir to
- A /		Total numbers	AM-	20 No's	25 No's	MR
- 2		Types		ABC/W. CO ₂ /CO ₂	10/10/05 No's	1,00,000
		IS marking	*/Vk-			IVIIC
			-AK-	ISI	Yes	MR
	. 11 21-VI	d Hose Reels				
		Total numbers	Kegumed	2 Nosin Hostel Block&1 Nos in	Provided	MR
	-	Total numbers on each	AS-0711-0801-041	Residential Block	lrea.	aguital di
		Length of hose reel hos	-AM-	30m	Provided	MR
	Nozzle diameter			5mm	Provided	MR
		tic fire detection and	alarming system		11011000	
		Type of detectors	- I Joseph	-NA-	-NA-	-NA-
- A			Alle	- 1165	(1) 1 (1) 1 (1) (1) (1) (1) (1) (1) (1)	- 40
- 4	•	Location of Main Pane		_NIA	NIA	NIA
- A		Location of Main Pane Location of Repeater P		-NA- -NA-	-NA-	-NA-

International Management Institute. B-10. 30 & 31. Outab Institutional Area. Tara Crescent. New Delhi-110016

International Management Institute, B-10, 30 & 31, Qutab Institutional Area, Tara Crescent, New Delhi-110016

	Hooters' Location	-NA-	-NA-	-NA-			
3.	MOEFA	Required	Provided	MR			
Thairt	Public Address System	-NA-	-NA-	-NA-			
0.	Automatic Sprinkler System	The same and		10 - 10			
-	Basement	Required	Provided	MR			
	CN Thur	-NA-	-NA-	-NA-			
	Upper Floors	-NA-	-NA-	-NA-			
	Sprinkler above false ceiling	and the state of the	de la	A Literature			
1.	Internal Hydrants		1 1 1 1 1				
	Size of riser/down-comer	100mm	Provided	MR			
	Number of hydrants per floor	2 Nos in Hostel Block&1 Nos in Residential Block	Provided	MR			
	Hose Box	2 Nos in Hostel Block&1 Nos in Residential Block	Provided	MR			
12.	Yard Hydrants						
	Total number of hydrants	4 Nos	6 Nos	MR			
	Hose Box	4 Nos	6 Nos	MR			
13.	Pumping Arrangements	nally has remark	2 A min 1111	2 1991 2			
	Ground Level	T.	Sup House H				
	 Discharge of main Pump 	Required	2280 & 1800 LPM	MR			
	➤ Head of Main pump	Required	60m	MR			
	> Number of main pumps	Required	Two	MR			
	Jockey Pump out put	Required	220 LPM	MR			
	Jockey pump head	Required	60m	MR			
	Standby Pump out put	Required	2280 LPM	MR			
	Standby Pump Head		60m	MR			
	Auto Starting/Manual Stopping	Required Required	Provided	MR			
	> Pump House Access	Required	Provided	1, 44, 44, 5			
	A STATE OF THE STA	Required	Flovided	MR			
	Terrace level	-NA-	-NA-	D. NIA			
	Discharge of pumpHead of the pump	-NA-	-NA-	-NA-			
	> Power Supply	-NA-	-NA-	-NA-			
	> Auto Starting of pump		10712-3053	-NA-			
14.	Captive Water Storage for fire fighting	-NA-	-NA-	-NA-			
14.	> Underground tank capacity	2.00.000 T.	1 40 000) (D (O)) (C			
	> Draw-off connection	3,00,000 Lts	1,40,000	MR (Old Cas			
	Fire service inlet	Required	Provided	MR			
	> Access to tank	Required	Provided	MR			
	Overhead Tank capacity	Required	Provided	MR			
15.	The management of the second s	Daminad	D	100			
16.	Exit Signage. Provision of Lifts.	Required	Provided	MR			
10.		-NA-	I NA I	NA			
36	Pressurization of Lift Shaft Pressurization of Lift lobby	-NA-	-NA-	-NA-			
	Communication In lift Car	-NA-	-NA-	-NA-			
	Fireman's Grounding Switch	-NA-	-NA-	-NA-			
	Lift Signage	-NA-	-NA-	-NA-			
17.	Standby power supply	Required	Provided	MR			
18.	Refuge Area.	Required	1 IOVIGG	IVIK			
10.	> Total Area	-NA-	-NA-	NIA			
	> Location	-NA-	-NA-	-NA-			
19.	Fire Control Room	-IVA-	-INA-	-NA-			
17.	Detector System Panel	-NA-	-NA-	NT A			
	Flow Switch Panel	-NA-	-NA-	-NA-			
	PA System Panel	9/8	50000 Land Land Land Land Land Land Land Land	-NA-			
	Battery backup	-NA-	-NA-	-NA-			
	Building Floor Plans	-NA-	-NA-	-NA-			
	Dundang	-NA-	-NA-	-NA-			

N/49

International Management Institute, B-10, 30 & 31, Outab Institutional Area Tara Crescent, New Delhi-110016

20.	Special Et D			
	Special Fire Protection System for Protection of special Risks, if any:	-NA-	-NA-	-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/School/2017/SZ/1542 Dt. 27/10/2017, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP)

appropried, F.T. letter in putup or your synature PI