C27 आज़ादी का अमृत महोत्सव

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

F.6/DFS/MS/EH/2023/SZ/ 270

Dated: 31 / 08 /2023

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s Anardana Hospitality Private Limited located at Unit No 151, 153 Ground Floor, DLF Avenue Mall, District Center, Saket, Delhi 110017 in the building comprised of 02 Tier Basement, Ground plus 07 Upper Floor owned/occupied by Mr. Ravi Malik (Partner) have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of this department on 24/08/2023 in the presence of Mr. Anil & Mr. Pankaj and that the premises is fit for occupancy class "Group-D Assembly Building" (Restaurant at Ground Floor) and validity upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 31 /08 /2023 at New Delhi by

ATUL GARG) DIRECTOR DELMI FIRE SERVICE

Copy to: -

1. The DHO, (Green Park), Public Health Department, MCD, Aurobindo Marg, Green Park, New Delhi-110016 (Ref. MHA Portal ID No 2023081214508 dated 19/08/2023)

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. The basement shall be used as per the provisions of BBL /NBC Part- IV.
- 4. All the staff members must know the correct method of operation of fire-fighting system.
- 5. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."



	INSPECT	TION REPORT	X3'10	10 8			
1	Name & Address of the Building						
labi	A Hambard & Manhand See Hall A	M/s Anardana Hospitality Private Limited locate at Unit No 151, 153 Ground Floor, DLF Avenu					
2	Type of Co	Mall, District Center, Saket, Delhi 110017					
3	Type of Occupancy	Eating house at Ground Floor only					
4	Building Comprised of	03 tier Basements, Ground + 07 Upper Floors					
1.63	Type of Case	New Case					
5	Details of Previous NOC						
6	Fire Safety Directives Letter No	Nil					
7	P. Parlie and D.	DLF Place Mall,- F.6/MS/DFS/BP/2005/2073 dated 04/10/2005 & F.6/MS/DFS/BP/2019/135 dated 01/04/2019					
100	Date of Inspection	24/08/2023					
8	Name of the Inspecting Officers		100 (000)				
9	Name & Designation of Officers	DO (South) & ADO (BCP)					
	from the building side	Mr. Anil & Mr. Pankaj					
10	Year of construction	and the second of the second o					
11	Applicant letter No.	2019					
S.	Minimum standards on Elian MHA Portal ID No 2023081214508 dated						
No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	Remarks MR/NMR			
1	Access to Building. (DLE Place						
W.		12 m	022/Mall/SZ/266 Dt. 15/00				
14	Gate width	7m	Provided by Mall	MR			
2	Width of internal road		N/A N/A	N/A			
	Number, width, type & arrangement of ex	its.	N/A	N/A			
1/6	Paris 1 10 25 in						
1	Upper floors.	N/A	aintained by DLF Aven				
	Basement floor.	N/A	N/A	N/A			
	b) Width of Staircase		N/A	N/A			
	Upper floors	N/A	aintained by DLF Aven				
	Basement floor	N/A	N/A N/A	N/A			
	c) Protection of exits	Provided & Maintained by DLF Avenue Mall					
	Fire check door	N/A	N/A				
	Pressurization	N/A	and against N/A or a zingu	N/A			
	d) No. of continuous staircase to terrace e) Width of corridor	N/A	N/A	N/A			
	e) Width of corridor f) Door size	N/A	N/A	N/A N/A			
3	Compartmentation.	1.50 mtr each	1.50 mtr & 1.50 mtr	MR			
101		Provided & Ma	aintained by DLF Aven	ne Moll			
	Fire check door.	Required	Provided *	MR			
	Sealing of electrical shafts.	Required	Provided *				
	Fire rating of shaft door.	N/A	N/A	MR			
	Water curtain	N/A	N/A	N/A			
1	• Fire dampers.	N/A flower	N/A	N/A N/A			
4	Smoke Management system.	Provided & Maintained by DLF Avenue Mall					
1	Basement	30 ACPH	N/A	N/A			
	Upper floors	12 ACPH	Exhaust Fans Provided	MR			
5	Fire Extinguishers.			IVIIC			
7	Total numbers Tymes	Required	08 Nos	MR			
	Types	ABC/CO ₂	ABC & CO ₂	MR			
6	ISI Marking First Aid Hose Reels.	Required	Provided	MR			
6		Provided & Ma	nintained by DLF Avenu	ue Mall			
7	Total numbers on each floor.	One near Restt	Provided *	MR			
1	Length of hose-reel hose.	30m	Provided *	MR			
	Nozzle Diameter	5mm (4)	Provided *	MR			
	Automatic fire detection & alarming system	n. (Provided & Ma	nintained by DLF Avenu	ie Mall			
DY V		D	Provided *	MR			
SY V	Type of detectors	Required		IVII			
34	Type of detectors Location of Main Panel	Required	Provided *				
31	 Type of detectors Location of Main Panel Location of Repeater Panel 	Required	Provided *	MR			
	Type of detectors Location of Main Panel						

C

W

8	MOEFA	Required	Provided *			
9	Public Address System	N/A	Provided *	MR		
10	Automatic Sprinkler System	Provided & Maintained by DLF Avenue Mal				
10	Basement	Required Provided * MR				
	Ground floor.	Required	Provided *	MR		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants.					
**	Size of Riser/Down-comer	Provided & Maintained by DLF Avenue Mall Provided * MR				
		Required	Piovided	IVII		
	Number of Hydrant per floor Hose box.	One near Restt	Provided *	MR		
	Hose dox.	One near Restt	Provided *	MR		
12	Yard Hydrants.	Provided & Maintained by DLF Avenue Mall				
	Total number of hydrants.	N/A	Provided *	N/A		
	Hose box.	N/A	Provided *	N/A		
13	Pumping arrangements.	Provided & Mai	ntained by DLF Aver	nue Mall		
	Ground Level	Common pumping arrangements for entire bldg				
	Discharge of main pump.	4500 LPM	Provided *	MR		
	➤ Head of main pump.	70m	Provided *	MR		
	Number of main pumps.	02 Nos.	Provided *	MR		
	Jockey Pump output.	180 LPM	Provided *	MR		
100	Jockey Pump head.	70m	Provided *	MR		
	Standby Pump output.	4500 LPM	Provided *	MR		
	Standby Pump head.	70m	Provided *	MR		
	> Auto Starting/Manual Stopping.	Required	Provided *	MR		
	Pump house access.	Required	Provided *	MR		
100	Terrace Level		2 Add 12	7		
	Discharge of pump.	450 LPM	Provided *	MR		
	➤ Head of pump.	40 m	Provided *	MR		
Mal	> Power supply.	Required	Provided *	MR		
:=V:::	> Auto starting of pump.	Required	Provided *	MR		
14	Captive water storage for fire fighting.	Provided & Maintained by DLF Avenue Mall				
	Underground tank capacity.	Required	3,70,000 Ltrs	MR		
	> Draw-off connection.	Required	Provided	MR		
lab4	> Fire Service Inlet.	Required	Provided	MR		
1	Access to tank.	Required	Provided	MR		
TI 1	Overhead tank capacity.	Required	30,000 Ltrs	MR		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.	Provided & Maintained by DLF Avenue Mall				
-× -	Pressurization of lift shaft.	N/A	N/A	N/A		
intvi	Pressurization of lift lobby.	N/A	N/A	N/A		
W.	Communication in lift car.	N/A	N/A	N/A		
-	Fireman's switch.	N/A	N/A	N/A		
	Lift signage.	N/A	N/A	N/A		
17	Standby Power Supply	Required	Provided	MR		
18	Refuge Area		antibility (2)	3		
Inda D	Total area	N/A	N/A	N/A		
14	Location	N/A	N/A	N/A		
19	Fire Control Room.		intained by DLF Aver	nue Mall		
	Detector system panel.	N/A	N/A	N/A		
nt f	Flow switch panel.	MA N/A	N/A	N/A		
ind .	PA system panel.	N/A	N/A	N/A		
half of	Battery backup.	N/A	N/A	N/A		
and the	Building floor plan.	N/A	N/A	N/A		
20	Special Fire Protection System for the	N/A	N/A	N/A		

5



Note: - * Provided & Maintenance by the DLF Avenue Mall, Saket, New Delhi

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

F.T. Letter in puhi