



1375
आजादी का
अमृत महोत्सव

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/EH/WZ/2023/274

Dated: 01/09/2023

FIRE SAFETY CERTIFICATE

Certified that the **Dasaprakash (A Unit of Das Kitchen)**, located at Unit No. G 04, Ground Floor, Vishal, Rajouri Garden, New Delhi – 110027, running at Ground Floor only in a building comprised of 02 Basement + Ground + 04 Upper Floor was issued FSC to mall vide this department letter no. F6/DFS/MS/2023/79 dated 14/02/2023, the building/premises was inspected by the officer concerned of this department on 24/08/2023 in the presence of Sh. Sandeep Singh and found that the said premises/building have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises/building is fit for occupancy class "Assembly" (Group - D) with effect from 01/09/2023 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010. Conditions Printed Overleaf.

Issued on 01/09/2023 at New Delhi by.

(Atul Garg)
Director

Copy to: -

1. The owner/occupier, **Dasaprakash (A Unit of Das Kitchen)**, located at Unit No. G 04, Ground Floor, Vishal, Rajouri Garden, New Delhi – 110027. **Online Application ID no. 2023081114447 dated 16/08/2023**
2. The Joint Commissioner of Police, Licensing Unit, 1st floor, Police Station, Defence Colony, New Delhi. (addlcp.lic-dl@nic.in)
3. The Dy. Health Officer, SDMC, West Zone, Vishal Enclave, Rajouri Garden, New Delhi 110027. (dhowestzone@gmail.com)

INSPECTION REPORT

1. Name & address of the building : Dasaprakash (A Unit of Das Kitchen), Located at Unit No. G 04, Ground Floor, Vishal, Rajouri Garden, New Delhi – 110027.
2. Type of Occupancy : Eating House /Assembly Occupancy
3. Type of Case : New
4. Details of previous NOC : Nil
5. Fire Safety directives letter No : Nil
6. Date of inspection : 24/08/2023
7. Name of the Inspecting Officers : Sarabjeet Singh ADO(MN)
8. Name and designation of officers from the building side : Sh. Sandeep Singh
9. Year of Construction : 2023 (As Per MHA Portal)
10. Applicant's letter No. : Online application ID No. 2023081114447 dated 16/08/2023

*** The Said Restaurant is running at Ground floor in Vishal Complex is comprised of 02 Basement + Ground + 04 Upper Floors FSC was issued vide this dept. letter no. F6/DFS/MS/2023/79 dated 14/02/2023.**

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	BBL /NBC Requirement	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	12 mts	Provided	MR
	• Gate width	4.5 mts	Provided	MR
	• Width of internal road	06 mts	Provided	MR
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	NA	Located At G.F.	NA
	• Basements	NA	NA	NA
	b. Width of staircases			
	• Upper Floors	NA	Located At G.F.	NA
	• Basements	NA	NA	NA
	c. Protection of exits			
	• Fire check door	NA	NA	NA
	• Pressurization	NA	NA	NA
	e. No. of continuous staircases to terrace	NA	NA	NA
	f. Width of Corridor	NA	NA	NA
	g. Door Size	1.5 mtr X 2	Provided	MR
3	Compartmentation.	Common With Mall		
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4	Smoke Management System.			
	• Basements	NA	NA	NA
	• Upper floors	Required	Provided	MR
5	Fire Extinguishers			
	• Total numbers	5 nos.	Provided	MR
	• Types	CO ₂ , ABC type	Provided	MR
	• IS marking	ISI marked	Provided	MR

SPP

6	First-Aid Hose Reels.	Common with Mall		
	<ul style="list-style-type: none"> Total numbers on each floor Length of hose reel hose Nozzle diameter 	01	Provided	MR
		30 mm	Provided	MR
		05 mm	Provided	MR
7	Automatic fire detection and alarming system.			
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	Smoke & Heat	Provided	MR
		Required	Provided	MR
		NA	NA	NA
		Required	Provided	MR
		Required	Provided	MR
8	MOEFA	Required	Provided	MR
9	Public Address System.	NA	NA	NA
10	Automatic Sprinkler System.			
	<ul style="list-style-type: none"> Basement Upper Floor Sprinkler above false ceiling 	NA	NA	NA
		Required	Provided	MR
		Required	Provided	MR
11	Internal Hydrants	Common With Mall		
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants per floor Hose Box 	150 mm	Provided	MR
		01	Provided	MR
		01	Provided	MR
12	Yard Hydrants.	Common With Mall		
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	NA	NA	NA
		NA	NA	NA
13	Pumping Arrangements.	Common With Mall		
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping Pump House Access Terrace level <ul style="list-style-type: none"> Discharge of pump Head of the pump Power Supply Auto Starting of pump 	2850 LPM	Common with the mall	MR
		90 m	Common with the mall	MR
		02 + 1 for water contain	Common with the mall	MR
		02 x 180 LPM	Common with the mall	MR
		90 m	Common with the mall	MR
		2850 LPM	Common with the mall	MR
		90 M	Common with the mall	MR
		Required	Common with the mall	MR
		Required	Common with the mall	MR
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
14		Captive Water Storage for fire fighting.	Common With Mall	
	<ul style="list-style-type: none"> Underground tank capacity Draw-off connection Fire service inlet Access to tank Overhead Tank capacity 	NA	02 Lakh Ltr Provided	NA
		NA	Provided	NA
		Required	Provided	MR
		NA	Provided	NA
		NA	20,000 ltr Provided	NA
15	Exit Signage.	Required	Provided	MR

16 Provision of Lifts.				
	• Pressurization of Lift Shaft	NA	NA	NA
	• Pressurization of Lift lobby	NA	NA	NA
	• Communication In lift Car	NA	NA	NA
	• Fireman's Grounding Switch	NA	NA	NA
	• Lift Signage	NA	NA	NA
17	Standby power supply	Required	Provided	MR
18 Refuge Area.				
	➤ Total Area	NA	NA	NA
	➤ Location	NA	NA	NA
19 Fire Control Room				
	• Detector System Panel	NA	NA	NA
	• Flow Switch Panel	NA	NA	NA
	• PA System Panel	NA	NA	NA
	• Batter backup	NA	NA	NA
	• Building Floor Plans	NA	NA	NA
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

ADOL/MN
18/23

~~ADOL/MN (w/2)~~

~~Signature~~
25/8/2023

Signature of the Inspecting Officer
Name: Sarabjeet Singh
Designation: ADO (MN)

~~Signature~~
28/8
M.K. CHATTOPADHYAY

~~Signature~~
29/8/2023

~~Signature~~
29/8/23

DCFW L

6/7
28/8/2023

Sir, F.T is put up for your kind personal & signature please.
Signature
30/8/2023