

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/EH/2023/SZ/272

Dated: 31/08/2023

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s **Haldiram Restaurant** located at **Ground, First Floor & Second Floor** at R-11, Block -R, Plot No 11, Main Market, Green Park, New Delhi-110016, in the building comprised of Ground plus 02 floors owner/occupied by (A Unit of Haldiram Marketing Pvt Ltd) have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 25/08/2023 in the presence of Mr. Sanjay Chauhan (Manager) and that the premise is fit for occupancy class **Group-D Assembly** and validity upto **31/03/2026** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on 31/08/2023 at New Delhi by


(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to: -

1. The DHO, (MCD), Public Health Department, Aurobindo Marg, Green Park, New Delhi-110016 (Ref. MHA Portal ID NO 2023072713387 dated 28/07/2023)
2. The Executive Engineer (Bldg Department) Green Park Zone, Aurobindo Marg, New Delhi 110016.

Conditions for the validity of Fire Safety Certificate:-

1. **The MCD Bldg department is requested to verify the height of building and a report be sent to this department, if the height of building is more than 10m to take further necessary action.**
2. All the means of escape/entry/exit shall be kept free from any obstruction.
3. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
4. All the staff members must know the correct method of operation of fire-fighting system.
5. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

M29

INSPECTION REPORT				
1	Name & Address of the Building	Haldiram Restaurant (A Unit of Haldiram Marketing Pvt Ltd) located at R-11, Block- R, Plot No 11, Main Market, Green Park, New Delhi-110016		
2	Type of Occupancy	Restaurant at Ground, First & Second Floor)		
3	Building Comprised of	Restaurant Height 9.82		
4	Type of Case	Ground + 02 upper floor		
5	Details of Previous NOC	Addition/alteration		
6	Fire Safety Directives Letter No	F6/DFS/MS/EH/2021/SZ/189 dated 19/08/2021 for GF & FF only		
7	Fire Safety Directives Letter No	Nil		
8	Date of Inspection	25/08/2023		
9	Name of the Inspecting Officers	DO (South) & ADO (BCP)		
10	Name & Designation of Officers from the building side	Mr. Sanjay Chauhan (Manager)		
11	Year of construction	2018		
11	Applicant letter No.	MHA Portal ID NO 2023072713387 dated 28/07/2023		
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	UBBL /NBC- 2016 Requirements	Provided at Site	Remarks NR/NMR
1	Access to Building.			
	• Road width	As per MPD-2021	06 m	MR
	• Gate width	4.5 m	About on road	MR
	• Width of internal road	-N/A-	-N/A-	-N/A-
2	Number, width, type & arrangement of exits.			
	a) Number of Staircase			
	➤ Upper floors.	02 Nos	Provided	MR
	➤ Basement floor.	-N/A-	-N/A-	-N/A-
	b) Width of Staircase			
	➤ Upper floors	2 m & 1.50 m	2 m & 1.50 m	MR
	➤ Basement floor	-N/A-	-N/A-	-N/A-
	c) Protection of exits			
	➤ Fire check door	Required	Provided	MR
	➤ Pressurization	-N/A-	-N/A-	-N/A-
	d) No. of continuous staircase to terrace	02 nos.	02 nos.	MR
	e) Width of corridor	-N/A-	-N/A-	-N/A-
	f) Door size	2 exits, 1.50 m x 2	Provided	MR
3	Compartmentation.			
	• Fire check door.	Required	Provided	MR
	• Sealing of electrical shafts.	Required	Provided	MR
	• Fire rating of shaft door.	Required	Provided	MR
	• Water curtain	-N/A-	-N/A-	-N/A-
	• Fire dampers.	-N/A-	-N/A-	-N/A-
4.	Smoke Management system.			
	• Basement	-N/A-	-N/A-	-N/A-
	• Upper floors	12 ACPH	Exhaust fan provided	MR
5.	Fire Extinguishers.			
	• Total numbers	15 nos.	Provided	MR
	• Types	ABC / CO ₂	ABC & CO ₂	MR
	• ISI Marking	ISI marked	Provided	MR
6.	First Aid Hose Reels.			

	<ul style="list-style-type: none"> Total numbers on each floor 	One	Provided	MR
	<ul style="list-style-type: none"> Length of hose-reel hose. 	30m	Provided	MR
	<ul style="list-style-type: none"> Nozzle Diameter 	5mm	Provided	MR
7	Automatic fire detection & alarming system.			
	<ul style="list-style-type: none"> Type of detectors 	-N/A-	Smoke type	-N/A-
	<ul style="list-style-type: none"> Location of Main Panel 	-N/A-	Ground Floor	-N/A-
	<ul style="list-style-type: none"> Location of Repeater Panel 	-N/A-	-N/A-	-N/A-
	<ul style="list-style-type: none"> Alternate source of power 	-N/A-	Provided	-N/A-
	<ul style="list-style-type: none"> Hooter's location 	-N/A-	Each floor	-N/A-
8.	MOEFA	Required	Provided	MR
9.	Public Address System	-N/A-	-N/A-	-N/A-
10.	Automatic Sprinkler System			
	<ul style="list-style-type: none"> Basement. 	-N/A-	-N/A-	-N/A-
	<ul style="list-style-type: none"> Upper floors 	-NA-	Provided	-NA-
	<ul style="list-style-type: none"> Sprinkler above false ceiling 	-NA-	-NA-	-NA-
11.	Internal Hydrants.			
	<ul style="list-style-type: none"> Size of Riser / Down-comer 	100 mm	Provided	MR
	<ul style="list-style-type: none"> Number of Hydrant per floor 	Required	01 no	MR
	<ul style="list-style-type: none"> Hose box. 	Required	01 no	MR
12.	Yard Hydrants.			
	<ul style="list-style-type: none"> Total number of hydrants. 	-N/A-	-N/A-	-N/A-
	<ul style="list-style-type: none"> Hose box. 	-N/A-	-N/A-	-N/A-
13.	Pumping arrangements.			
	<ul style="list-style-type: none"> Ground Level 			
	Discharge of main pump.	-N/A-	-N/A-	-N/A-
	➤ Head of main pump.	-N/A-	-N/A-	-N/A-
	➤ Number of main pumps.	-N/A-	-N/A-	-N/A-
	➤ Jockey Pump output.	-N/A-	-N/A-	-N/A-
	➤ Jockey Pump head.	-N/A-	-N/A-	-N/A-
	➤ Standby Pump output.	-N/A-	-N/A-	-N/A-
	➤ Standby Pump head.	-N/A-	-N/A-	-N/A-
	➤ Auto Starting/Manual stopping.	-N/A-	-N/A-	-N/A-
	➤ Pump house access.	-N/A-	-N/A-	-N/A-
	<ul style="list-style-type: none"> Terrace Level 			
	➤ Discharge of pump.	450 LPM	2 x 450 LPM	MR
	➤ Head of pump.	40 m	40 & 30 m	MR
	➤ Power supply.	Required	Provided	MR
	➤ Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for firefighting.			
	<ul style="list-style-type: none"> Underground tank capacity. 	-N/A-	-N/A-	-N/A-
	➤ Draw-off connection.	-N/A-	-N/A-	-N/A-
	➤ Fire Service Inlet.	-N/A-	-N/A-	-N/A-
	➤ Access to tank.	-N/A-	-N/A-	-N/A-
	<ul style="list-style-type: none"> Overhead tank capacity. 	20,000 ltrs	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	<ul style="list-style-type: none"> Pressurization of lift shaft. 	-N/A-	-N/A-	-N/A-
	<ul style="list-style-type: none"> Pressurization of lift lobby 	-N/A-	-N/A-	-N/A-
	<ul style="list-style-type: none"> Communication in lift car. 	-N/A-	-N/A-	-N/A-

	<ul style="list-style-type: none"> • Fireman's switch. • Lift signage. 	-N/A-	-N/A-	-N/A-
17	Standby Power Supply	Required	Provided	MR
18.	Refuge Area			
	<ul style="list-style-type: none"> • Total area • Location 	-N/A-	-N/A-	-N/A-
19.	Fire Control Room.			
	<ul style="list-style-type: none"> • Detector System Panel. • Flow Switch Panel. • PA system Panel. • Battery backup • Building floor plan 	-N/A-	-N/A-	-N/A-
20.	Special Fire Protection System for the Protection of special Risk, if any.	-N/A-	-N/A-	-N/A-

Note :- The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection. The AE (Bldg) is hereby requested to verify the height of the building upto last occupied floor as restaurant occupancy and a report be sent to this office, if the height of the building is of 10 m and above.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly DFA is put up for approval and signature please.

Mensh
Signature of the Inspecting Officer
Name: - Sh. M. K. Sharma
Designation: - DO (South)

RK 28/8/23
Signature of the Inspecting Officer
Name: Sh. Rajesh Kumar
Designation: ADO (BCP)

CFO (HO) *Thugh*
28/8/2023

Director *[Signature]*
29/8/23

FTP's
Approved *put up*
as per rule

As approved, F.T. letter is put up for your signature pl.

Director *[Signature]*
31/8/23

N *unclassified*
[Signature]
31/8/23

[Signature]
30/8