

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

No.F6/DFS/MS/Hotel/NDZ/2023/ 23

Dated: 01/09/2023

FIRE SAFETY CERTIFICATE

Certified that the Park Inn by Radisson Hotel located at Plot no. 6A, I.P Extension, Mandawali Fazalpur, Delhi-110092, comprised of 02 Basement + Ground + 09 Upper floors and Barsati, owned/occupied Park Inn by Radisson Hotel was issued FSC vide letter no. F6/DFS/MS/ Hotel/2020/NDZ/385 dated 25/09/2020. The Hotel Building was re-inspected by the officers concerned of this department on 22.08.2023 in the presence Mr. Pankaj Bali (Manager) and observed that all the Fire Prevention and Fire Safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the Fire Prevention and Fire safety requirement in accordance with the rule 33 Delhi Fire Service Rules, 2010 and observed that the building are fit for occupancy Group A-5 "Hotel Building" with effect from 01 09 2023 for a period of (Three years) in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued 0110912023 at New Delhi by.

Copy to: -

1. Park Inn by Radisson Hotel located at Plot no. 6A, I.P Extension, Mandawali Fazalpur, Delhi-110092.

2. Join Commissioner of police (Lic.), Ist Floor, P.S Defence Colony, New Delhi-24 w.r.t.-MHA portal ID - 2023080313920 dated 11/08/2023.

Condition for the validity of fire safety certificate

All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.

2 Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

The trained fire fighting staff should be available round the clock.

4 Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

This fire safety certificate may not be treated in any case for regularization of unauthorized 5 construction, if any.

6 The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

7 The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.

Basement shall be used strictly as per Building By-Laws 1983.

The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

7		PI	SPECTION REP	ORT			
E -		dress of the building	Park Inn by Ra	disson Hotel located at	Dlat - C		
1	Name & address of the building Building is comprised of		Park Inn by Radisson Hotel located at Plot no. 6A, I. Extension, Mandawali Fazalpur, Delhi-110092. 02 Basement + Ground + 09 Upper floors only.				
2	Build	of occupancy	Assembly/ Hotel Building				
	Type	of occup	Renewal				
	Type	of case	F6/DFS/MS/ Hotel/2020/NDZ/385 dated 25/09/2020.				
	Detai	ils of previous FSC	F6/DFS/MS/RP/2010/252 1 125 00 00 00 00 00 00 00 00 00 00 00 00 00				
	Fire s	afety direction retter	F6/DFS/MS/BP/2010/252 dated 27.01.2010				
-+	Date	df inspection	22.08.2023				
	Name	of the inspecting officers	A.K.Jaiswal, DO (ED) & Yashwant Singh Meena ADO (L.N)				
1	Name	of the designation of officer the building side	Mr. Pankaj Bali (Manager)				
-	Year	of construction	2010				
0			Application No.	. I.D -2023080313920 da	ted 11/08/2022		
1	Appl	cant's letter no.	Requirements	Provide at site			
. No	Mini Prev 33	mum standard of Fire ention and Fire Safety U/R	NBC-IV	1 Tovide at site	Remarks MR/NMR		
	Acce	ss to Building	1	20	1100		
	A	Road width	12 mtrs	30 mtr	MR ~		
1	В	Gate width	4.5 mtrs	6.0 mtrs	MR -		
	C	Width of internal roads	6.0 mtrs	6.0 mtrs	MR		
2	Number, Width, Type & Arrangement of Exits						
	A	No. of staircase:	Too	02	MD		
		a) Upper floor	02 nos.	02 nos.	MR -		
		b) Basements	03 nos.	02 nos. + 01 ramp	IVIK /		
	В	Width of the staircase:	14	1.5 . 0.145 .	T v m		
		a) Upper floors	1.25 mtrs	1.5 mtrs & 1.45 mtrs.	MR -		
		b) Basements	1.25 mtrs	1.5 mtrs & 1.45 mtrs.	MR /		
	C	Protection of Exits		Descrided	MR -		
		a) Fire check door	Required	Provided Provided	MR -		
		b) Pressurization	Required	02 nos.	MR -		
	D	No. of continuous staircase to terrace:	02 nos.	A 1	MR C		
	E	Width of the corridor	1.50 mtrs	1.50 mtrs	MR /		
	F	Door size	1.0 mtrs	1.0 mtrs	MIK		
	Con	npartmentation:					
3		The I	Denvised	Provided	MR		
	A	Fire check doors	Required Required	Provided	MR -		
	В	Sealing of horizontal & vertical opening		Provided	MR ~		
	C	Fire rating of shaft doors	02 hrs. N/A	N/A	N/A -		
	D E	Water curtain	Required	Provided	MR		
		Fire dampers oke management System:	Required	. 10 11000	III NU Valle ma V		
4	310	ione management system;			and the		
•	A	Basements	30 ACPH	Provided	MR /		
	В	Upper floors	12 ACPH	Provided	MR _		
		e extinguishers	-90		0		
5	Land	Barran a			MR -		
5	A	Total numbers	65 nos.	70 nos.	IVIIC		
5	A	Total numbers Types	65 nos. ABC/CO ₂	70 nos. Provided	MR _		

		st Aid Hose Reel	02 no.	02 no.	MR		
	15.00	Total no. at each floor	30 mtrs	30 mtrs	MR		
		Length of hose reel	05 mm	05 mm	MR		
	C	Nozzle diameter		05 11111	IVIIC		
_	_	omatic Fire Detection and Alarm	Smoke/Heat	Provided	MR /		
	A	Type of detectors	Reception		MR		
1	-	Location of main Panel	Reception		MR /		
	_	Location of repeater panel	Battery & DG Set		MR /		
	D	Alternate power source	Different Location		MR /		
_	~	Hooter's location		Provided			
		EFA	Required	Provided	MR /		
	11.0	lic Address System	Required	Provided	WIK /		
10		tomatic Sprinkler System	Dogwinad	Provided	MR		
	A	Basement	Required	Provided	MR		
	В	Upper floor	Required	Provided	-		
	C	Sprinklers above false ceiling	Required	Provided	MR ',		
1	A	ernal Hydrants Size of the riser/down comer	150 mm	150 mm	MR /		
			Deposit Services	CO SCHOOL STORY	N. C.		
	В	No. of hydrants per floor	02 nos.	02 nos.	MR /		
	C	Hose box	02 nos.	02 nos.	MR (
12	_	rd Hydrants	1	Tac	Tran		
	A	Total no. of hydrants	04 nos.	06 nos.	MR/		
	B	Hose box	04 nos.	06 nos.	MR'		
13		mping arrangements Ground Level	All and he was	100000000000000000000000000000000000000	7		
	A	The state of the s	2200 I DV	2200 1 771 /	1200		
		a) Discharge of main pump b) Head of Main Pump	2280 LPM	2280 LPM	MR		
			88 mtrs	88 mtrs	MR		
		c) Number of Main Pump	02 nos.	02 nos.	MR		
		d) Jockey Pump out put	450 LPM	450 LPM	MR		
		e) Jockey Pump Head	88 mtrs	88 mtrs	MR		
		f) Standby Pump out put	2280 LPM	2280 LPM	MR		
		g) Standby Pump Head	88 mtrs	88 mtrs	MR		
	-	h)Auto Stating/ Manual Stopping	Required	Provided	MR		
	B	B Terrace Level					
		a) Discharge of Pump	900 LPM	900 LPM	MR /		
		b) Head of terrace pump	88 mtrs	88 mtrs	MR		
		c) Power supply	Required	Provided	MR		
		d) Auto starting of pump	Required	Provided	MR		
14	Captive Water Storage for Fire Fighting.						
	A		2,00,000 ltrs	2,00,000 ltr	s MR		
	В		Required	Provided	MR		
	C		Required	Provided	MR		
	E)	Required	Provided /	MR		
	D		20,000 ltrs	20,000 ltrs	MR		
15		xit Signage	Required	Provided	MR		
16	Provision of lift						
	A	Of the share	Required	Provided	MR		
	B		Required	Provided	MR		
	C	and the cal	Required	Provided	MR		
	D	The state of the s	Required	Provided	MR		
11	E		Required	Provided	MR		
1'	5	tandby Power Supply	Required	Required	MR		



park Inn by Radisson localed at Plot no. 6A, I.P Extension, Mandawali Fazalpur, Delhi-110092.

18	Refuge Area						
-	٨	location		102 10 0014	MD C		
	В	Total area	61 Sqrm	183.18 SQM	MR		
19	Fire Control Room		4 th & 6 th floor	4" & 6" floor	MR /		
	A	Fire Detection System panel	D	Desided	MR C		
	В	Flow switch panel	Required	Provided	MR		
	C	P A system panel	Required	Provided			
	D	Battery backup	Required	Provided	MR /		
	E	Building G	Required	Provided	MR /		
20	_	Building floor plan	Required	Provided	MR /		
20	Special Fire Protection for special risk if any						
	A	Special Fire Protection system for Protection of Special Risk, if any: HT/LT Panels Provided	Required for		MR		

The fire protection systems provided in the building were randomly tested /checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules. The FSC issued Vide Letter no. F6/DFS/MS/ Hotel/2020/NDZ/385 dated 25/09/2020 it is recommended to renew Fire Safety Certificate Under the rules 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer

Name: A.K. Jaiswal Designation: DO (ED)

Signature of the Inspecting Officer Yashwant Singh Meena

Designation: ADO (L.N)

Dy.CFO(NDZ)

F.T. is added for signature please.

An Injurant 31/8/2013