

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELHI- 110001

ग्रिक आज़ादी न अमृत महोत्सव

No.F6/DFS/MS/Residential/SZ/2023/ 426

Dated: 05 09/2023

## FIRE SAFETY CERTIFICATE

Certified that the M/s Multistory Building, CRRI Staff Colony, Maharani Bagh, New Delhi-65, comprised of Ground + 12 upper floors was granted Fire Safety Certificate (FSC) by this department vide letter no. F6/DFS/MS/2015/SZ/2052 dated 13.11.2015. The premises was re-inspected by officers concerned of this department on 30.08.2023 in presence of Mr. Muni Raj Meena, Executive Engineer (E) and found that the building/premises has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy class Group 'A (Residential) with effect from OS. 109/2023..... for a period of five years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on ... 05 09 2023 at New Delhi by

Director

Delhi Fire Service

Copy to:-

1. Mr. Mukesh Kumar (MBSQ), CRRI- Staff Colony, Maharani Bagh, New Delhi-65.

## Conditions for the validity of Fire Safety Certificate

- All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

			PECTION REPO	RT	2.00.04 (2.0.00)		
1		Name & address of the building	M/s Multis Maharani	M/s Multistory Building, CRRI Staff Colony, Maharani Bagh, New Delhi-65.			
2		Building is comprised of	Ground + 12	Ground + 12 upper floors			
3		Type of occupancy	Residential E	Residential Building			
4		Type of case	Renewal F6/DFS/MS/2015/SZ/2052 dated 13.11.2015 DFS Act 2007 & Rules 2010				
5		Details of previous FSC					
6		Fire safety direction letter no.					
7		Date of inspection	30.08.2023				
8	-	Name of the inspecting officers	Rajesh Kumar Shukla, ADO (M. Road) Mr. Muni Raj Meena, Executive Engineer (E)				
9	$\dashv$	Name of the designation of officer					
		From the building side		Meena, Executive F	Engineer (E)		
10		Year of construction	1974				
11	1	Applicant's letter no.	Outdoor diary	Outdoor diary no. 5372 dated 24.08.2023			
s. N		Minimum standard of Fire Prevention and Fire Safety U/R 33	BBL/NBC	Provide at site	Remarks MR/NMR		
		Access to Building					
	_	A Road width	9.0 mtrs	Provided	MR		
		B Gate width	5.0 mtrs	Provided	MR		
	1000	Width of internal roads	6.0 mtrs	Provided	MR		
-	1	Number, Width, Type & Arrangen No. of staircase:	nent of Exits				
	1	TATAL DESCRIPTION OF THE PROPERTY OF THE PROPE	1-				
	1	a) Upper floor b) Basements	2 nos.	2 nos.	MR		
	1		NA	NA	NA		
	B		10	1.0			
		a) Upper floors	1.0 mtrs	1.0 mtrs	MR (Old case)		
	-	B) Basements	NA	NA	NA		
	C	PRODUCTOR OF THE PRODUC	100		Xw 101		
		a) Fire check door	NA	NA	NA		
	_	b) Pressurization	NA	NA	NA		
	D	No. of continuous staircase to terrace:	1 no.	Provided	MR		
	E	Width of the corridor	NA	NA	NA ·		
	F	Door size	NA	NA	NA		
3	Co	mpartmentation:	Jan Mar				
	A	Fire check door	NA	NA	NA		
	В	Sealing of horizontal & vertical opening	Required	Provided	MR		
	C	Fire rating of shaft doors	NA	NA	NA		
_	D	Water curtain	NA	NA	NA		
_	E	Fire dampers	NA	NA	NA		
		oke Management System:	use Ti				
1	1	Basements	NA	NA	NA		
E		Upper floors	NA	NA	NA		
F	Fire Extinguishers						
A		Total numbers	42 nos.	46 nos.	MR		
B		Types	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR		
C		ISI marking			A CONTRACTOR OF THE PARTY OF TH		
-	۱ ۱	131 marking	ISI marked	Provided	MR		

6	First Aid Hose Reel							
	A	Total no. at each floor	2 nos.	2 nos.	MR			
	B	Length of hose reel	30 mtrs	30 mtrs	MR			
	C	Nozzle diameter	5 mm	5 mm	MR			
7	Automatic Fire Detection and Alarm System (ADAS)							
	A	Type of detectors	NA NA	NA	NA			
	В	Location of main Panel	NA NA	NA NA	NA			
	_	Location of repeater panel	NA NA	NA NA	NA			
	D	Alternate power source	NA NA	NA NA	NA			
	E	Hooter's location	Each floor	Provided	MR			
8	_	OEFA		Provided	MR			
9	_	blic Address System	Required	Provided	MR			
10	Automatic Sprinkler System Required Provided  Automatic Sprinkler System							
10	A	Basement System	LNIA	NA	NA			
	_	Upper floor	NA	NA NA	NA			
		Sprinklers above false ceiling	NA	NA NA	NA			
11	In	ternal Hydrants	NA	NA NA	IVA			
11	A		1100	Provided	MR			
	_	No. of hydrants per floor	150 mm	Provided	MR			
	C	Hose box	2 no.		MR			
12	C Hose box 2 no. Provided MR  Yard Hydrants							
12	A	Total no. of hydrants	10	Provided	MR			
	B	Hose box	2 no.	Provided	MR			
13	_	mping Arrangements	2 no.	Provided	IVIIC			
	A	Ground Level		_				
		a) Discharge & head of main pump	NA	NA	NA			
		b) Number of main pump	NA NA	NA NA	NA			
		c) Discharge & head of jockey pump	135 WATER	TOTAL CONTRACTOR OF THE PARTY O	NA			
		d) Discharge & head of Standby pump	NA	NA NA	NA NA			
		e) Auto starting/ manual stopping	NA	NA NA	NA NA			
	e) Auto starting/ manual stopping NA NA  B Terrace Level							
	-		150 1 016	To 11.1	1 10			
		a) Discharge of terrace pump	450 LPM	Provided	MR			
		b) Head of terrace pump	45 mtrs	Provided	MR			
		c) Alternate power supply	Required	Provided	MR			
14	Co	d) Auto starting of pump	Required	Provided	MR			
14		ptive Water Storage for Fire Fighting	1 00 000 1'	In 11.1	Lvm			
	A B	Underground tank capacity  Draw off connection	1,00,000 litters	Provided	MR			
		Fire Service Inlet	Required	Provided	MR			
	_	Access to tank	Required Required	Provided Provided	MR MR			
		Overhead tank capacity	10,000 litters	Provided	MR			
15			Required	Provided				
16								
10	A	Pressurization of lift shaft	Required	Provided	MR			
		Pressurization of lift lobby	NA	NA ·	NA .			
	-	Communication in lift car	Required	Provided	MR			
Ì	_	Fireman switch	Required	Provided	MR			
	_	Lift signage	Required	Provided	MR			
17		ndby Power Supply	Required	Provided	MR			

M/s Multistory Building, CRRI Staff Colony, Maharani Bagh, New Delhi-65



18	Refuge Area						
	A	location	NA	NA	NA		
	В	Total area	NA	NA	NA		
19	Fire Control Room						
	A	Fire Detection System panel	NA	NA	NA		
	В	Flow switch panel	NA	NA	NA		
	C	P A system panel	NA	NA	NA		
	D	Battery backup	NA	NA	NA		
	E	Building floor plan	NA	NA	NA		
20	Special Fire Protection for special risk if any						
	A	Special Fire Protection system for Protection of Special Risk, if any:	NA	NA			

Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/2015/SZ/2052 dated 13.11.2015 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (M. Road)

20(0)

Meyl 31/2/2

Sinceter 1/5/2

97 in pur up pla

05/9/23

Director (DFG)

Im