

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

F.6/DFS/MS/Hospital/2023/SZ/ 432 No.

Dated: 12 / 09 /2023

## FIRE SAFETY CERTIFICATE

Certified that Hospital Building located at Plot No R-26, Nehru Enclave, Kalkaji, New Delhi comprised of Basement, Stilt Ground plus Three Upper Floors owned/occupied by M/s Veselka Estates Private Limited have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by officer concerned of this department on 31/08/2023 in presence of Mr. Mahesh Aggarwal and that the building is fit for occupancy class "Institutional building" Group-C (Hospital) with effect from 12/09/2023 for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Pelhi Fire Service Rules, 2010.

Issued 12 09 /2023 at New Delhi by

DELHI FIRE SERVICE

OIN

Copy to: -

1. M/s Veselka Estates Private Limited located at Plot No R-26, Nehru Enclave, Kalkaji, New Delhi- 110019

2. The Asstt. Engineer (Building)-I, Municipal Corporation of Delhi Building Department,-1, Central Zone, Lajpat Nagar, New Delhi 110024

Conditions for the validity of Fire Safety Certificate:

All the means of escape/entry/exit shall be kept free from any obstruction.

- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The basement shall be used as per the provisions of UBBL-2016/NBC Part- IV.
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL- 2016), if any.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.



6	INSPECTION	N REPORT	The state of the		
1	Name & Address of the Building	Hospital Building, at Plot No R-26, Nehru Enclave, Kalkaji, New Delhi- 110019			
34.	Type of Occupancy	Institutional building, "Group-C" (Hospital)			
2	Building Comprised of	Basement, Stilt, Ground + 03 upper floors.			
3	Type of Case	New Case			
4	Details of Previous NOC	Nil			
5	Fire Safety Directives Letter No	F6/DFS/MS/2023/BP/1187 dated 07.06.2023			
6	Date of Inspection	31/08/2023			
7	Name of the Inspecting Officers	DO (South) & ADO (BCP)			
8	Name & Designation of Officers	Mr. Mahesh Aggarwal			
9	from the building side	adments (1 increase)			
10	Year of construction	2023 Date Private Private A			
11	Applicant letter No.	Outdoor diary no 4785 dated 10/08/2023			
. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Directive requirements	Provided at Site	Remarks MR/NMF	
1	Access to Building.		36-3011 84-7	IVIIOIVIVII	
-	a Road width	9 mtr	13.71 mtr	MR	
M	Gate width	6 mtr	Provided	MR	
	Width of internal road	-NA-	-NA-	-NA-	
_	Number, width, type & arrangement of exits.	-MA-	H CALL A MINORITOR - F	-IVA-	
2		garee math	TO SCHOOL PRISE TO		
"		02 Nos	Provided	MR	
	Opper moors.	02 Nos	Provided	MR	
IIA I		UZ NOS	riovided	IVIK	
(12)	b) Width of Staircase	02 mtr each	02 mtr each	MR	
ME	> Upper floors > Basement floor	02 mtr each	02 mtr each	MR	
Nete		02 mili cacii	OZ IIILI Edicii	IVIN	
	c) Protection of exits	Required	Provided	MR	
MM.	Fire check door	-17-14	A comment of the second	The state of the s	
8/1//	Fiessurization	-NA-	-NA-	-NA-	
24.8	d) No. of continuous staircase to terrace		Provided	MR	
	e) Width of corridor	1.50 mtr	Provided	MR	
174	n Door size	2m / 1.50 mtr	Provided	MR	
3	Compartmentation.		Author to some	3.00	
176	Fire check door.	Required	Provided	MR	
AV.	<ul> <li>Sealing of electrical shafts.</li> </ul>	Required	Provided	MR	
	Fire rating of shaft door.	Required	Provided	MR	
MIK	Water curtain	-NA-	-NA-	-NA-	
2018	Fire dampers.	-NA-	-NA-	-NA-	
4.	Smoke Management system.	1		140	
	a Docement	12 ACPH	Exhaust fan provided	MR	
2DA	Upper floors	12 ACPH	Exhaust fan provided	MR	
5.	Fire Extinguishers.		81.11 132	MR	
5.	Total numbers	Required	95 Nos		
	SALES STORY PRODUCTION OF THE PROPERTY.	ISI marked	ABC & Co2	MR	
Misc	Types     ISI Marking	Required	Provided	MR	
341	ISI Marking		uttenturment ₹	1 . 25	
6.	First Aid Hose Reels.	02 Nos at each	Provided	MR	
MIN	Total numbers on each floor.	30m	Provided	MR	
TIDE	<ul> <li>Length of hose-reel hose.</li> </ul>		Provided	MR	
50345	Nozzle Diameter	5mm	1.0,100		
7	die Condition & elerming system.		Provided	MR	

V

NIE



	Location of Main Panel	Required	Ground floor	MR
	Location of Repeater Panel	-NA-	-NA-	-NA
	Alternate source of power	Required	Provided	MR
8.	Hooter's location	Required	Provided	MR
	MOEFA	Required	Provided	MR
9,	Public Address System	-NA-	-NA-	-NA
10.	Automatic Sprinkler System	4 - 4		
	Basement	Required	Provided	MR
	<ul> <li>Upper floors (except EE area)</li> </ul>	Required	Provided	MR
	Sprinkler above false ceiling	Required	Provided	MR
11.	Internal Hydrants.		Z. specifydnino	
	<ul> <li>Size of Riser/Down-comer</li> </ul>	150 mm	Provided	MR
	Number of Hydrant per floor	02 Nos	Provided	MR
	Hose box.	02 Nos	Provided	MR
12.	Yard Hydrants.		144 FIRE LEVEL 2 11 1 41151	14
	Total number of hydrants.	Required	Provided	MR
116	Hose box.	Required	Provided	MR
13.	Pumping arrangements.		Transport to Pro-P	
	Ground Level	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	we because the polimic	7   2
	Discharge of main pump.	1620 LPM	Provided	MR
	➤ Head of main pump.	60 mtr	Provided	MR
	➤ Number of main pumps.	One	Provided	MR
	> Jockey Pump output.	180 LPM	Provided	MR
	➤ Jockey Pump head.	60 mtr	Provided	MR
	➤ Standby Pump output.	1620 LPM	Provided	MR
	➤ Standby Pump head.	60 mtr	Provided	MR
M	➤ Auto Starting/Manual Stopping.	Required	Provided	MR
	> Pump house access.	Required	Provided	MR
	Farmed Bearings	Kequited	policinos in diliti. Is	
19	Terrace Level	-NA-	-NA-	-NA-
	> Discharge of pump.	-NA-	-NA-	-NA-
	<ul> <li>➤ Head of pump.</li> <li>➤ Power supply.</li> </ul>	-NA-	-NA-	-NA-
	> Auto starting of pump.	-NA-	-NA-	-NA-
	Captive water storage for fire fighting.		all the second second	MD
14.	Underground tank capacity.	75,000 Ltr	Provided	MR MR
	> Draw-off connection.	Required	Provided Provided	MR
M-	> Fire Service Inlet.	Required	Provided	MR
	> Access to tank.	Required	Provided	MR
Vi.	Overhead tank capacity.	10,000 Ltr Required	Provided	MR
5.	Exit Signage.	Required	The state of the s	
6.	Provision of Lifts.		stedium buaT *	
£ 11	SUN OL	Required	Provided	MR
	Pressurization of lift shaft.	Required	Provided	MR
A.	Pressurization of lift lobby.	Required	Provided	MR MR
	Communication in lift car.	Required	Provided	MR
1	Fireman's switch.	Required	Required	MR
	Lift signage.	Required	Provided (DG Set)	MIK
7.	Standby Power Supply			-NA-
8.	Refuge Area	-NA-	-NA-	-NA-
77	Total area	-NA-	-NA-	-INA

S





19.	Fire Control Room.			
20.	Detector system panel. Flow switch panel. PA system panel. Battery backup. Building floor plan.  Special Fire Protection System for the Protection of special Risk, if any.	-NA-	-NA-	
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		Required	LT, HT &	-NA-
			Transformers provided with Co2 flooding	MR

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly DFA is put up for approval and signature please.

Signature of the Inspection O

Name: Sh. Manoj Sharma Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)

CFO (HQ)

F-1. rettel is proto