GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001 Dated: 13 09 2023

No. F6/DFS/MS/2023/School/WZ/636

FIRE SAFETY CERTIFICATE

Certified that the M.D.Memorial Sr. Sec. Public School, Indra Jheel, G-Block, Sultan Puri, Nangloi, Delhi-86, comprised of Ground + 02 upper floors only has already been issued FSC by this department vide letter No. F.6/DFS/MS/2016/24 dated 06.01.2017. The premises was re-inspected by the officer concerned of this department on 25.08.2023 in the presence of Sh. Ved Parkash Yadav (Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Group B Educational with effect from for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ...13. 0.9. 2023.... at New Delhi by

DIRECTOR

Ph; 011-23414000

Ru

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sect. Delhi - 54.

2. The Principal, M. D. Memorial Sr. Sec. Public School, Indra Jheel, G-Block, Sultan Puri, Nangloi, Delhi-86.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building

5. This certificate cannot be treated in any case for regularizations of unauthorized

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+an http://www.delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms d+Rules/

INSPECTION REPORT

: M. D. Memorial Sr. Sec. Public School, Indra Jheel, G-Block, 1. Name & address of the building

Sultan Puri, Nangloi, Delhi-110086.

: Educational 2. Type of Occupancy

: Renewal (Ground + 02 upper floors) 3 Type of Case : F.6/DFS/MS/2016/24 dated 06.01.2017. 4 Details of previous NOC

: NBC Part 4. 5 Fire Safety directives letter No : 25.08.2023 6 Date of inspection

7 Name of the Inspecting Officers : A.K.Sharma ADO (Rohini)

8 Name and designation of officers

: Sh.. Ved Parkash Yadav/ Manager from the building side

: 2009,2014 & 2023

9. Year of Construction

10	Minim	nt's letter No. ; Onlin um Standards on fire prevention and fire safety U/R 33	Dir. Of Education/ NBC Requirement	Provided at site	Remarks MR/NMR		
\dashv	Access t	building	P. C. C.	Viet Director	MR		
-	110000		Accessible	Accessible			
	•	Road width	Accessible	4.5m	MR		
		Gate width	NA	NA	NA		
	•	Width of internal road	The state of the s				
	Number, Width, Type & Arrangement of Exits						
	a. Numl	er of staircases	02	02	MR		
	•	Upper Floors	NA NA	NA	NA		
	•	Basements	- 1,11.	3015 11 146	F		
	b. Widt	n of staircases	1.50 mtr	1.5m & 1.40 mtr	MR(Old case)		
	•	Upper Floors	NA NA	NA	NA		
	•	Basements					
	c. Prote	c. Protection of exits	NA	NA	NA		
		Fire check door	NA	NA	NA		
	•	Pressurization	01	01	MR		
	d. No.	of continuous staircases to terrace	1.50 mtr	1.50 mtr	MR		
		th of Corridor	1.0m	1.0 mtr	MR		
-	f. Doo						
3	Compartmentation. NA NA NA						
		Fire check door	NA	NA NA	NA		
		a v - Calcatrical shafts	NA	NA NA	NA		
		Fire Rating of shaft door	NA NA	NA NA	NA		
		Water Curtain	NA	NA NA	NA		
		Fire Dampers	NA	11.1			
4	Smoke Management System.						
		Basements	30 a/c per hour	NA Natural Ventilated	MR		
		Upper floors	12 a/c per hour	Natural Ventilated			
5	F	re Extinguishers	11		MR		
-		Total numbers	10nos	15nos	MR		
4		Types	ABC/Co2	ABC15	MR		
		ISI marking	Yes	Yes	MIK		
6	First Aid Hose Reels.						
0	71130	Total numbers on each floor	01	01	MR		
		Length of hose reel hose	30m	30m	MR		
		Nozzle diameter	5m	5m	IVIIC		





4/18

			NA	NA 3
T	Type of detectors	NA	NA	NA
	Location of Main Panel	NA	NA	NA
	Location of Repeater Panel	NA	NA	NA
	Alternate source of power	NA	NA	NA
×	Hooters' Location	NA	NA	NA
1	MOEFA	NA	NA	NA
	Public Address System.	NA		
0	Automatic Sprinkler System.		NA	NA
F	Basement	NA	NA	NA
	Upper Floor	NA	NA	NA
	Sprinkler above false ceiling	NA	The second second	
11	Internal Hydrants	ACCOUNTS TO	NA	NA
''	Size of riser/down-comer	NA	NA	NA
	Number of hydrants per floor	NA	NA	NA NA
	Hose Box	NA	NA	IV.
_		- mik	1 9 1 1 Aug 19 1	of t
12	Yard Hydrants.	NA	NA	NA
	Total number of hydrants	NA	NA	NA
	Hose Box		Q.b h	tal Long 1
13	Pumping Arrangements.		The second second	
İ	Ground Level	N/A	N/A	N/A
	Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	N/A
	 Jockey pump head Standby Pump out put 	N/A	N/A	N/A
	Standby Pump Out put Standby Pump Head	N/A	N/A	N/A
	> Auto Starting/ Manual stopping	N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level		to linear	100
	> Discharge of pump	450 lpm	450 lpm	MR
	> Head of the pump	40m	40m	MR
	> Power Supply	Required	Provided	MR
	> Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for fire fighting.			The state of the s
		NA	NA	NA
	Underground tank capacity Draw-off connection	NA	NA	NA
		NA	NA	NA
	> Fire service inlet > Access to tank	NA	NA	NA
	Overhead Tank capacity	10,000ltr	10,000ltr	MR
1.5		Required	Provided	MR
15	Exit Signage.			
16	Provision of Lifts. Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
11	Lift Signage	N/A	N/A	N/A
		N/A	N/A	N/A
17	Standby power supply	INA		
18	Refuge Area.	N/A	N/A	N/A
	> Total Area > Location	N/A	N/A	N/A
	➤ Location Fire Control Room			
19		N/A	N/A	N/A
	Detector System Panel	IN/A	111/73	11/7

Chy

• Flow Switch Panel	N/A	N/A	N/A
PA System Panel	N/A	N/A	N/A
Batter backup	N/A	N/A	N/A
Building Floor Plans	N/A	N/A	N/A
Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in Director of Education Circular / NBC Part 4, the FSC issued vide letter of even no F.6/DFS/MS/2016/24 dated 06.01.2017 renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Signature of the Inspecting Officer
Name Ajay Kumar Sharma
Designation ADO(Rohini)

Dy. CFO (WZ)

Cfo lught
6 (91) 2022

Dêneeta)

Anytu

for kind pensal and Signatur please.

Director My/19/2