

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2023/SZ/ 624

Dated: 12 09 2023

FIRE SAFETY CERTIFICATE

Certified that the Sunita Gyan Niketan School, Located at Village & Post Office Chhawla, New Delhi-110071, comprised of ground plus one upper floor & (One room at 2nd floor) owned/occupied by Sunita Gyan Niketan School was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/2009/1857 Dated 24/06/2009. The school building was reinspected by the officer concerned of this department on 30/08/2023 in the presence of Sh. Suresh Gaur (Owner) and found that the School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. 262 to 362 dated 17/01/2005 issued by the Director of Education and that the building/ premises (ground & first floor only) is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on 12 09 2023 at New Delhi.

DELHI FIRE SERVICE

Copy to:-

- 1. The Manager, Sunita Gyan Niketan School, Village & Post Office Chhawla, New Delhi-110071.
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-54.

Following fire safety directives must be adhered to:-

1. This NOC is valid for ground & first floor only.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

3. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.

4. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

5. The trained staff should be available round the clock.

6. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

7. The certificate may not be treated in any case for the regularization of the unauthorized

construction, if any.

8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior

to its expiry.

INSPECTION REPORT

Sunita Gyan Niketan School, Village & Post Office Chhawla, New 1. Name & address of the building :

Ground plus two upper floor but school at gr. & first floor only (One 2. Building comprised of

room at 2nd floor)

Educational 3. Type of Occupancy 4. Type of Case Renewal

F.6/DFS/MS/2009/1857 Dated 24/06/2009 5. Details of Previous NOC Circular No. 262-362 dated 17/01/2005 6. Fire Safety directives letter No :

30/08/2023 7. Date of inspection

A.D.O. R.K. Yadav 8. Name of Inspecting Officer

9. Name and designation of officers

Sh. Suresh Gaur (Owner) From the building side

11. S. No.	Applicant's letter No. : E-mail dated Minimum Standards on fire prevention and	Requirements	Provided at site	Remarks MR/NMR			
	fire safety U/R 33						
l .	Access to building			M/R			
	1.11	Accessible 06 m	10 m				
	Road width	4.5 m	Direct accessible from road	MR, old case			
	Gate width Width of internal road	N/A	N/A	N/A			
	TAN 1 WEST-SHOP GREEN HEAVING SCHOOL SHOP STORY						
2.	Number, Width, Type & Arrangement of Exits	4	Ear.				
	a. Number of staircases	20 31 1	02 No.'s	M/R			
	Upper Floors	02 No.'s	N/A	N/A			
	Basements	N/A	IVA	i Aspensa			
	b. Width of staircases	100000	1.80 & 1.25 m	MR			
	Upper Floor	1.50 &.75 m.	N/A	N/A			
	Basements	N/A	IVA				
	c. Protection of exits	27/4	N/A	N/A			
	Fire check door	N/A	N/A	N/A			
	Pressurization	N/A	IVA				
	d. No. of continuous staircases to	B :-1	Provided	M/R			
	terrace	Required	2.05 m	M/R			
	e. Width of Corridor	1.50 m		M/R			
	f. Door Size	1.0 m	Provided	IVI/K			
3.	Compartmentation						
		N/A	N/A	N/A			
	Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A	N/A	N/A			
	Fire Rating of shaft door		N/A	N/A			
	Water Curtain	N/A	N/A	N/A			
	Fire Dampers	N/A	NA				
4.	Smoke Management System	N/A	N/A	N/A			
	Basements	IN/A	1307				
		Required	Natural ventilation	M/R			
	Upper floors		provided	A Service			
,	Fire Extinguishers	A Maria	11 11 11 11 11	gazin a			
5.	Total numbers	08 no's	Provided	M/R			
	Types	ABC/CO ₂ type	Provided	M/R			
	IS marking	ISI marked	Provided	M/R			
6.	First-Aid Hose Reels		IVA.	1915			
0.	Total numbers on each floor	One	Provided	M/R			
	* * * * * * * * * * * * * * * * * * *	30 m	Provided	M/R			

			The state of the s	
	 Length of hose reel hose 	5 mm	Provided	M/R
0.5	Nozzle diameter			
7.	Automatic fire detection and alarming system		21/4	21/4
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location		N/A	N/A
8.	MOEFA	N/A	N/A N/A	N/A N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System Basement	N/A	N/A	N/A
		N/A N/A	N/A	N/A
		N/A	N/A	N/A
11.	Sprinkler above false ceiling Internal Hydrants	IN/A	19/74	10/74
11.	Size of riser/down-comer	N/A	N/A	N/A
- 1	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants	IVA	IN/A	1071
14.	Total number of hydrants	N/A	N/A	N/A
13	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements	1074		
13.	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	> Head of Main pump	N/A	N/A	N/A
	> Number of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	N/A
- 1	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
-		N/A	N/A	N/A
	Pump House Access	1071	N/A	INA
	Terrace level	450 LPM	Provided	NA/D
1	Discharge of pump	430 LPM 40 m	USANSAZZ SWAQ3QX	M/R
	Head of the pump		Provided	M/R
- 4	> Power Supply	Required Required	Provided .	M/R
3.5	Auto Starting of pump	Required	Provided	M/R
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	NI/A	N1/A	NU
14	> Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
15.	Exit Signage.	5,000 ltrs	Provided	M/R
	88	Required	Provided	M/R
6.	Provision of Lifts.	1 2	107	
	Pressurization of Lift Shaft	N/A	No Lift	SIL
	Pressurization of Lift lobby		N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
		N/A	N/A	N/A
17		N/A	NIA	Secure 1
17.	Standby power supply	IN/A	N/A	N/A

18.	Refuge					
	0.00	Total Area	N/A	N/A	N/A	
	>	Location	N/A	N/A	N/A	
19.	Fire Control Room					
	•	Detector System Panel	N/A	N/A	N/A	
	•	Flow Switch Panel	N/A	N/A	N/A	
	•	PA System Panel	N/A	N/A	N/A	
	Battery backup Building Floor Plans	N/A	N/A	N/A		
		N/A	N/A	N/A		
20.		Fire Protection System for Protection of Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number <u>F.6/DFS/MS/2009/1857 Dated 24/06/2009</u> renewal in accordance with the Circular No. 262 to 362 dated 17/01/2005 issued by the Director of Education is recommended.

Note: School building is comprised of ground plus one upper floor & one room at second floor uses as storage purpose.

Signature of Inspecting Office

Name:- R.K.Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

9/2

Directar

M