

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001

No.F6/DFS/MS/EH/NDZ/2023/ 296

Dated: 15/09/2023

FIRE SAFETY CERTIFICATE

Issued on 15/89/2023 at New Delhi by

Director
Delhi Fire Service

Tel: 011-23414000

Copy to:-

 The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi: - Ref. MHA Portal ID. No. 2023082315089 dated 23.08.2023.

 The Medical Officer of Health, Health Department, MCD, Civic Centre, Minto Road, New Delhi- 02.

3. The Licensee, M/s Al-Gulzar Restaurant at 4092-93, Urdu Bazar, Jama Masjid, Delhi -06.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.
- 8. Any changes in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

INSPECTION REPORT

1. Name & address of the building

: M/s Al-Gulzar Restaurant (ground floor & mezzanine

floor) 4092-93, Urdu Bazar, Jama Masjid, Delhi-06.

2. Building is comprised of

: Ground + Mezzanine + 03 upper floors

3. Type of Occupancy

: Assembly (Restaurant at ground & mezzanine floor

completely segregated)

4. Type of Case

: Renewal

5. Details of Previous FSC

: F6/DFS/MS/EH/NDZ/2020/138 dated 30.09.2020

6. Fire Safety direction letter No

: NBC Part-IV 2005

7. Date of Inspection

: 01.09.2023

8. Name of the Inspecting Officers: : Rajinder Atwal, DO(CD) & Sumit Kumar, ADO (SPM)

9. Name of the designation of Officer

from the building side

: Mr. Pawan Kumar (Manager)

10. Year of Construction

: 2015

11. Applicant's letter No

: Online ID no. 2023082315089 dated 23.08.2023

5.N 0	Minimum Standards on fire prevention and fire safety U/R 33	Requirements as per NBC 2005	Provided at Site	Remarks MR/NMR		
1	Access to building		with a second			
10.0	Road width	06 m	12 m	MR		
	Gate width	NA	NA	NA		
	Width of internal road	N/A	N/A	N/A		
2	Number, Width, Type and Arrangement of	Exits.				
_	A. Number of Staircases	The second				
	upper floor	2 no.	2 no.	MR		
	Basement	NA	NA	NA		
	No. of Exits/door at Ground floor	2 no.	2 no.	MR		
	No. of Exits/door from mezzanine to Ground floor	2 no.	2 no.	MR		
	B. Width of Staircases	•	Maria Cara Cara Cara Cara Cara Cara Cara			
	Upper floor	1.5 m, 1.35 m	1.52 m & 1.37 m	MR		
	Basement	NA ·	NA	NA		
	width of Exits/door at ground floor	2 m	2.1 m & 1.5 m	MR		
	Width of Exits/door from mezzanine to Ground floor	1.5 m	1.52 m & 1.37 m	MR		
	C. Protection of exits	NA	NA	NA		
	Fire check door	NA	NA	NA		
	Pressurization	NA	NA	NA		
	D. No. of continuous staircases to terrace	01 no.	01 no.	MR		
	E. Width of Corridor	NA	NA	NA		
3	Compartmentation					
_	Fire check door	Required	Provided	MR		
	Sealing of electrical shafts	N.A.	NA	NA		
100	Fire rating of shaft door	N.A.	N.A.	NA		
	Water curtain	N.A.	N.A.	NA		
	Fire Dampers	N.A.	N.A	NA		
4	Smoke Management System.	30h				

	Fire Extinguisher Total numbers	06 no.	06 no.	MR		
	1 1 Table 1 Table 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ABC +CO ₂	ABC +CO ₂	MR		
	types IS marking	Required	Provided	MR		
<u> </u>	IS marking First-aid-Hose Reels.					
6	Total numbers of ground floor	01 no.	01 no.	MR		
	Length of hose reel hose	30 m	30 m	MR		
	Nozzle diameter	5 mm	5 mm	MR		
7	Automatic fire detection and alarming system.					
	Type of detectors	NA	N.A	NA		
	Location of main panel	NA	NA	NA		
	Location of repeater panel	NA	NA	NA		
	Alternate source of power	NA .	NA	NA -		
	Hooters	NA	NA	NA		
•	MOEFA	Required	Provided	MR		
9	Public address System.	NA	NA	NA	-0	
30716	Automatic Sprinkler System.		Be Museum to	March 1		
10	Ground floor	NA	Provided	NA		
	Mezzanine floor	NA	Provided	NA	T	
	sprinkler above false ceiling	NA	NA	NA		
••	Internal Hydrants	PARTIES NO.				
11	Size of down-comer	100 mm	100 mm	MF	<u> </u>	
	Number of hydrants each floor	1 no	1 no.	MF	1	
	Hose box each floor	1 no.	1 no.	M	3	
12	Yard Hydrants.	77- Sept. Se				
12	Total number of hydrants	NA	NA	N/	1	
	Hose Box	NA	NA .	N/	4	
	Pumping Arrangements.					
13		NA	NA	N	Α	
	Ground Level Discharge of main Pump	NA	NA	N	Α	
	> Head of Main Pump	NA	NA	N	A	
	> Number of main pumps	NA .	NA	N	IA	
	> Jockey pump out put	NA	NA	1	IA	
	> Jockey pump head	NA	NA	1	AA	
	> Standby pump out put	NA	NA	n min	NA	
	> Standby pump Head	NA	NA	11	NA	
	> Auto Starting /Manual stopping	1.00000	NA		NA	
	> Pump House Access	NA	NA	y	NA	
	T unip node node		W	Actor (No. 2)		
	Terrace Level					
	> Discharge of pump	450 LPM	900 LPM	al Dodge	MR	
	> Head of the Pump	40m	40 m	coord for	MR	
	> Power supply	Required		a0 - a1	MR	
	> Auto Starting of pump	Required	Provided		MF	



4	Captive Water Storage for Fire Fighting.					
0	Underground tank capacity	NA	NA	NA		
	Draw-off connection	NA	NA .	NA		
	Fire service inlet	NA	NA .	NA		
	Access to tank	NA -	NA	NA		
	Overhead Tank capacity	10,000 Liters	20,000 Liters	MR		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					
	Pressurization of Lift Shaft	NA	NA	NA		
	Pressurization of Lift lobby	NA .	NA	NA		
	Communication in lift car	NA	NA	NA		
	Firemen's grounding switch	NA	NA	NA		
	Lift Signage	NA	NA	NA		
17	Standby power supply	Required	Provided	MR		
18	Refuge Area.					
. 7.5	Total area	NA	NA .	NA		
	Location	NA	NA	NA		
19	Fire Control Room					
	Detector system panel	NA	NA	NA		
	Flow switch panel	NA	NA	NA		
	PA system panel	NA	NA	NA		
	Battery backup	NA	NA	NA		
•	Building Floor Plans	NA	NA	NA		
20	Special Fire Protection systems for protection of special Risks, if any:	LPG Bank	Protected by Co2 extinguisher	MR		

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

Shortcomings communicated vide letter No.F6/DFS/MS/EH/NDZ/2023/419 dated 31/07/2023 have been rectified.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/EH/NDZ/2020/138 dated 30.09.2020 is recommended to be renewed (restaurant running at ground & mezzanine floor only), under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name

Rajinder Atwal

Designation

DO (CD)

Signature of the Inspecting Officer

Name

Sumit Kumar

Designation A

ADO (SPM)

2. f. 0. Nul 2. f. 0. Nul Dinectar My 9/73

Anyson