

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F6/DFS/MS/2023/WZ/EH/ 287

Dated: 18/09/2023

FIRE SAFETY CERTIFICATE

Certified that the Nine-11 (N-11), Anushka Shopping Mall, GF, Block-02, Garg Trade Centre, Sector-11, Rohini, Delhi-110085, is running at ground floor in building comprised of Basement + Ground + 07 upper floors was inspected by the officer concerned of this department on 22.08.2023 in the presence of Miss. Mona Tiwari and found that the said premises have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010. and that the premise is fit for occupancy Group D 'Assembly' (Eating House) for Ground floor (Nine-11 (N-11) Restaurant) with effect from 18/09/2023 for a period of 03 (Three) years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ...18/09/2023... at New Delhi by


 (Atul Garg)
 DIRECTOR
 Ph; 011-23414000

Copy to:

MHA Id- 2023081114433 dated 14.08.2023

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management/occupier.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules
 / http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

INSPECTION REPORT

1. Name & address of the building : Nine-11, (N-11), Anushka Shopping Mall, GF, Block-02, Garg Trade Centre, Sector-11, Rohini, Delhi-110085.
2. Type of Occupancy : Assembly (Eating House)
3. Type of Case : New Case (Restaurant Nine-11, N-11 is running at Gr. Floor only)
4. Details of Previous NOC : NA
5. Fire Safety directives letter No : NBC Part IV
6. Date of inspection : 22.08.2023
7. Name of Inspecting Officer : A.K.Sharma ADO (Rohini)
8. Name and designation of officers
From the building side : Miss. Mona Tiwari
9. Year of Construction : 2023
10. Applicant's letter No. : Online application no. 2023081114433 dated 14.08.2023.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	UBBL/NBC Requirement	Provided at site	Remarks MR/NMR
1.	Access to building [Anushka Tower, Garg Trade Center, Plot No.2, issued FSC vide letter No.F.6/DFS/MS/WZ/487 dated 01.11.2022]			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	Restaurant within Mall	As Above	MR
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	Restaurant within NA	NA	MR
		Restaurant within NA	As Above	MR
	b. Width of staircases			
	<ul style="list-style-type: none"> • Upper Floor • Basements 	Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
	c. Protection of exits			
	Fire check door			
	<ul style="list-style-type: none"> • Pressurization 	Restaurant within NA	As Above	MR
		Restaurant within NA	As Above	MR
	d. No. of continuous staircases to terrace			
		Restaurant within NA	As Above	MR
	e. Width of Corridor			
		Restaurant within NA	As Above	MR
	f. Door Size	1.50m	2m & 1.5m	MR
3.	Compartmentation			
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	Required	Provided	MR
		Restaurant within NA	As Above	MR
		Restaurant within NA	As Above	MR
		Restaurant within NA	As Above	MR
		Restaurant within NA	As Above	MR
4.	Smoke Management System			
	<ul style="list-style-type: none"> • Basements • Upper floors 	Restaurant within mall	As Above	MR
		Restaurant within mall	As Above	MR
5.	Fire Extinguishers			
	<ul style="list-style-type: none"> • Total numbers • Types • IS marking 	03nos.	08nos.	MR
		ABC/CO2	ABC/CO2	MR
		ISI marked	Yes	MR
6.	First-Aid Hose Reels			
	<ul style="list-style-type: none"> • Total numbers on each floor • Length of hose reel hose • Nozzle diameter 	01 near to restaurant	As Above	MR
		30mm	As Above	MR
		5m	As Above	MR
7.	Automatic fire detection and alarming system			
	<ul style="list-style-type: none"> • Type of detectors • Location of Main Panel 	Required	Provided	MR
		NA	As Above	NA

Am

	<ul style="list-style-type: none"> Location of Repeater Panel Alternate source of power Hooters' Location 	NA	As Above	NA
		NA	As Above	NA
		NA	As Above	NA
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System[Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> Basement 	NA	As Above	NA
	<ul style="list-style-type: none"> Ground & Upper Floors 	NA	As Above	NA
	<ul style="list-style-type: none"> Sprinkler above false ceiling 	NA	As Above	NA
11.	Internal Hydrants[Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> Size of riser/down-comer 	100mm	As Above	MR
	<ul style="list-style-type: none"> Number of hydrants per floor 	One(near to Restaurant)	As Above	MR
	<ul style="list-style-type: none"> Hose Box 	One(near to Restaurant)	As Above	MR
12.	Yard Hydrants[Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> Total number of hydrants 	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> Hose Box 	Restaurant within mall	As Above	MR
13.	Pumping Arrangements[Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> Ground Level 	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> ➤ Discharge of main Pump 	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> ➤ Head of Main pump 	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> ➤ Number of main pumps 	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> ➤ Jockey Pump out put 	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> ➤ Jockey pump head 	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> ➤ Standby Pump out put 	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> ➤ Standby Pump Head 	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> ➤ Auto Starting/Manual Stopping 	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> ➤ Pump House Access 	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> Terrace level 	[Provided & Maintained by Mall management]		
	<ul style="list-style-type: none"> ➤ Discharge of pump 	NA	As Above	MR
	<ul style="list-style-type: none"> ➤ Head of the pump 	NA	As Above	MR
	<ul style="list-style-type: none"> ➤ Power Supply 	Required	As Above	MR
	<ul style="list-style-type: none"> ➤ Auto Starting of pump 	Required	As Above	MR
14.	Captive Water Storage for fire fighting [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> Underground tank capacity 	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> ➤ Draw-off connection 	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> ➤ Fire service inlet 	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> ➤ Access to tank 	Restaurant within mall	As Above	MR
	<ul style="list-style-type: none"> Overhead Tank capacity 	Restaurant within mall	As Above	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts. [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> Pressurization of Lift Shaft 	NA	NA	NA
	<ul style="list-style-type: none"> Pressurization of Lift lobby 	NA	NA	NA
	<ul style="list-style-type: none"> Communication In lift Car 	NA	NA	NA
	<ul style="list-style-type: none"> Fireman's Grounding Switch 	NA	NA	NA
	<ul style="list-style-type: none"> Lift Signage 	NA	NA	NA
17.	Standby power supply	NA	NA	NA
18.	Refuge Area. [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> ➤ Total Area 	NA	NA	NA
	<ul style="list-style-type: none"> ➤ Location 	NA	NA	NA
19.	Fire Control Room[Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> Detector System Panel 	NA	NA	NA

N/S

• Flow Switch Panel	NA	NA	NA
• PA System Panel	NA	NA	NA
• Battery backup	NA	NA	NA
• Building Floor Plans	NA	NA	NA
Special Fire Protection System for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

[Handwritten Signature]
28/8/23

Signature of the Inspecting Officer
Name Ajay Kumar Sharma
Designation ADO(Rohini)

Dy. CFO (WZ)

[Handwritten Signature]
24/8
M.K. CHATTOPADHYAY

[Handwritten Signature]
24/8/23

[Handwritten Signature]
25/8/2023
Director
[Handwritten Signature]
24/8/23

[Handwritten Signature]
DLF/WZ

put up F.T.

[Handwritten Signature]
ADO(Rohini)

[Handwritten Signature]
28/8

FT letter is put up for kind
perusal and Signature please

[Handwritten Signature]
15/9/23
Director

[Handwritten Signature]
28/8/23

Deemed approval on
12/9/23