



No F 6 / DFS / MS/ 2023/WZ/

1441

Dated:

8 09 2023

FIRE SAFETY CERTIFICATE

Certified that the Bristal Farm located at Palla Bakhtawarpur Road, Alipur, Delhi110036 comprised of Basement & Ground floor owned/occupied by Bristal Farm was issued
Fire Safety Certificate vide letter no. F6/DFS/MS/2020/283 dated 31/07/2020. The premise was
re-inspected by the officer concerned of this department on 30/08/2023 in the presence of Sh.
Anshum and found that the said farm house building have deemed complied with the fire
prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service
Rules, 2010 and that the building premise is fit for occupancy under "Class D 'Assembly
Building' (Farm House)" with effect from 12.39.25... for a period of three years in
accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and
subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010,

Issued on 18 99 2023 at New Delhi by

Ph 011-23414000

Conditions for the validity of Fire Safety Certificate:

 Means of escape shall not be kept locked or bolted from outside and shall be easily open able at the time of emergency.

All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

 Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

4. The trained fire fighting staff should be available round the clock.

5. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

6. This certificate cannot be treated in any case for regularizations of unauthorized construction.

- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>WWW.dfs.Delhigovt.nic.in</u>

Copy to:-

- 1. The Assistant Engineer (Bldg.), Delhi Municipal Corporation, Narela Zone, Delhi.
- 2. M/s Bristal Farm located at Palla Bakhtawarpur Road, Alipur, Delhi-110036.

1

INSPECTION REPORT

Name & address of the building: Katyal Garden located at Palla Bakhtawarpur Road, Alipur

Delhi-110036.

: Assembly

2. Type of Occupancy

3. Building Comprised : Basement & Ground Floor.

4. Type of Case : Renewal

5. Details of Previous NOC : F6/DFS/MS/2020/283 dated 31/07/2020

6. Fire Safety directives letter No : NBC Part-IV
7. Date of inspection : 30.08.2023
8. Name of Inspecting Officer : ADO R.K. Sinha

9. Name and designation of officers

From the building side : Sh. Anshum 10. Year of Construction : 2000

11. Applicant's letter No. : E mail id Dated 24.08.2023

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/BBL Requirements	Provided at site	Remarks MR/NMR			
1.	Access to building	Acquirements	Site	MINIMIK			
	Road width	9 m	Provided	MR			
	Gate width	4.5 m	4.5 m	MR			
	Width of internal road	6 m	6 m	MR			
2.	Number, Width, Type & Arrangement of	Exits	UII	IVIK			
	a. Number of staircases						
	Upper Floors	NA	NA	NIA			
	Basements	01		NA			
	b. Width of staircases	UI_	01	MR(old case)			
	Upper Floor		The state of the s				
	The same of payments	NA	NA	NA			
	Basements	1.25 m	3 m	MR			
	c. Protection of exits	1/4	function is the	Alteria E			
		NA	NA	NA			
	Fire check door Pressurization	NA	NA	NA NA			
			HILL SHOW	INA			
	d. No. of continuous staircases to	NIA	A C LEAVE CO. III.	N. C. W. C. C.			
	terrace	NA	NA	NA			
	e. Width of Corridor	NA	The real of the later	tronder -			
	c. Width of Corridor	INA	NA	NA			
	f. Door Size		1.60 (2.)	3 1 mm m			
		1 m	Provided	MR			
3.	Commont	The state of the s	Quality project	Total Control			
э.	Compartmentation	70148	C. Jenn				
	Fire check door	NA	NA	NA			
	Sealing of electrical shafts Fire Rating of shaft door	NA	NA				
		NA		NA			
	Water Curtain	- 15	NA	NA			
	Fire Dampers	NA	NA	NA			
4.	Smoke Management System	49		TE K			
	Basements	Required	Exhaust Fan	MR			
			Provided	IVIK			
	Upper floors	Required	Natural	MD			
_		CONCESSOR LAND	Ventilated	MR			
5.	The Extinguishers						
	 Total numbers 	1@300 SQM	Description	and I so Dienous			
	Types		Provided	MR			
	IS marking	ABC & Co2	Provided	MR			
6.	First-Aid Hose Reels	Yes	Yes	MR			
	Total numbers on each floor						
	Length of hose reel hose	01	01	MR			
	Nozzle diameter	30 m	30 m	MR			
	Trocate diameter	5 mm	5 mm	50.5000000			
			1 - 411111	MR			

M

7.	T	N-23			
<i>/</i> .	Automatic fire detection and alarming s		7	N/A	
	Type of detectorsLocation of Main Panel	NA	NA	NA	
		NA	NA	NA	
	Location of Repeater PanelAlternate source of power	NA	NA	NA	
	Alternate source of power	NA	NA	. NA	
	Hooters' Location	NA	NA	NA	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System	NA	NA	NA	
10.	Automatic Sprinkler System		ax Lepter		
	Basement	Required	Provided	MR	
	Ground Floor	NA	NA	NA	
	Sprinkler above false ceiling	NA	NA	NA	
11.	Internal Hydrants				
	Size of riser/down-comer	100 mm	Provided	MR	
	Number of hydrants per floor	01	01	MR	
	Hose Box	01	01	MR	
12.	Yard Hydrants		3.00		
	Total number of hydrants	NA NA	NA NA	NA	
	Hose Box	NA NA	NA NA	NA	
13.	Pumping Arrangements	1	- 77.4		
_	Ground Level	_			
	> Discharge of main Pump	NA	NA	NA	
	> Head of Main pump	NA NA	NA NA	NA	
	Number of main pumps			NA NA	
	> Jockey Pump out put	NA	NA NA		
	> Jockey pump head	NA	NA	NA	
	Standby Pump out putStandby Pump Head	NA	NA	NA	
	> Auto Starting/Manual Stopping	NA	NA	NA	
	17.8	NA	NA	NA	
	> Pump house Access	NA	NA	NA	
	Terrace level		-	Self Amend	
	Discharge of pump	450 lpm	Provided	MR	
	> Head of the pump	40 m	Provided	MR	
	> Power supply	Required	Provided	MR	
	Auto starting of pump	Required	Provided	MR	
14.	Captive Water Storage for fire fighting	7.7	Torner 18		
_ 1.	 Underground tank capacity 	NA	NA	NA	
	> Draw-off connection	NA	NA	NA	
	> Fire service inlet	NA	NA	NA NA	
	> Access to tank	NA	NA NA	NA NA	
	Overhead Tank capacity	10,000 ltrs	Provided		
15.	Exit Signage.	Required	Provided	MR MR	
6.	Provision of Lifts.			1000	
	• Procounication of Lie Cl. C			11 1121 4	
	Pressurization of Lift Shaft Pressurization of Lift lobby	NA	NA	NA	
	Communication In lift Car	NA	NA	NA	
	Fireman's Grounding Switch	NA	NA	NA	
	Lift Signage	NA	NA	NA	
		NA	NA		
	Standby power supply	Required		NA	
7.	- man by power suppris	Required	Provided, 125	MR	

n

_	Refuge Area. > Total Area	NA	NA	NA
	> Location	NA	NA	NA
_	Fire Control Room			
-	Detector System Panel	NA	NA	NA
	Fow Switch Panel	NA	NA	NA
•	PA System Panel	NA	NA	NA
	Battery backup	NA	NA	NA
	Building Floor Plans	NA	NA	NA
	Special Fire Protection System for	NA	NA	NA

The fire protection system provided in the building were tested/checked and found

functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew the Fire Safety Certificate issued vide letter number F6/DFS/MS/2020/283 dated 31/07/2020 under rule 35 of the Delhi Fire Service Rules 2010.

> Signature of the Inspecting officer Name: Rajeev Kumar Sinha Designation: ADO/BW

Morton 8hr. F-1 lette v. Puty for syn. pla