

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001**

No. F.6/DFS/MS/GH/2023/SZ/153

Dated: 19.09.2023

FIRE SAFETY CERTIFICATE

Certified that the **Hotel Stanley** located at A-192, NH-8, Road No 4, Mahipalpur Extn. New Delhi-110037 comprised of Basement, (locked) Ground (Rec.) 1st Floor (12 G/Rooms) 2nd Floor (12 G/Room) 3rd Floor (12 G/Rooms) & 4th Floor Sealed with brick Wall by the management owned/occupied by Mr. Omveer Singh have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of this department on 13/09/2023 on in the presence of Mr. Omveer Singh and that the premise is fit for occupancy class **Group-A "Residential"** (Guest House with 36 G/Rooms) and **validity upto 31/03/2026** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 19/09/2023 at New Delhi by

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049 (Ref. MHA Portal ID 2023082815313 dated 28/08/2023)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. The basement shall be used as per the provisions of UBBL /NBC Part- IV.
4. All the staff members must know the correct method of operation of fire fighting system.
5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."
8. The MCD Bldg department is requested to verify the height of building and a report be sent to this department, if the height of building is more than 15m and above to take further necessary action

N/116

INSPECTION REPORT				
1	Name & Address of the Building	M/s Hotel Stanley located at A-192, NH-8, Road No 4, Mahipalpur Extn. New Delhi-110037		
2	Type of Occupancy	Residential, "Group-A" (Guest House)		
3	Building Comprised of	Basement (found locked), Ground + 04 upper floors. (4 th floor Sealed with brick wall)		
4	Type of Case	New case		
5	Details of Previous NOC	Nil		
6	Fire Safety Directives Letter No	UBBL- 2016		
7	Date of Inspection	13/09/2023		
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Omveer Singh		
10	Year of construction	2000	Ground floor - reception, 1 st to 3 rd floor, - 12 G/Room each total 36 G/Rooms	
11	Applicant letter No.	MHA Portal ID 2023082815313 dated 28/08/2023		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	UBBL-2016 requirements	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	• Road width	Required	06 mtr	MR
	• Gate width	-NA-	-NA-	-NA-
	• Width of internal road	-NA-	-NA-	-NA-
2	Number, width, type & arrangement of exits.			
	a) Number of Staircase			
	➤ Upper floors.	02 Nos	02 Nos	MR
	➤ Basement floor.	-NA-	Found locked	-NA-
	b) Width of Staircase			
	➤ Upper floors	1.50 m each	1.50 mtr each	MR
	➤ Basement floor	-NA-	-NA-	-NA-
	c) Protection of exits	As per clause 7.31 in UBBL-2016		
	➤ Fire check door	Required	Provided	MR
	➤ Pressurization	-NA-	-NA-	-NA-
	d) No. of continuous staircase to terrace	One	Provided	MR
	e) Width of corridor	1.8 m	Provided	MR
	f) Door size	1.5 m	Provided	MR
3	Compartmentation.			
	• Fire check door.	-NA-	-NA-	-NA-
	• Sealing of electrical shafts.	-NA-	-NA-	-NA-
	• Fire rating of shaft door.	-NA-	-NA-	-NA-
	• Water curtain	-NA-	-NA-	-NA-
	• Fire dampers.	-NA-	-NA-	-NA-
4	Smoke Management system.	As per clause 7.31 in UBBL 2016		
	• Basement	12 ACPH	-NA-	-NA-
	• Upper floors	12 ACPH	Exhaust fan Provided	MR
5	Fire Extinguishers.			
	• Total numbers	10 Nos	Provided	MR
	• Types	ABC / CO2	ABC & CO2	MR
	• ISI Marking	ISI marked	Provided	MR
6	First Aid Hose Reels.			
	• Total numbers on each floor.	One	Provided	MR
	• Length of hose-reel hose.	30 mtr	Provided	MR
	• Nozzle Diameter	5 mm	Provided	MR

N

~

7 Automatic fire detection & alarming system.		As per clause 7.31 in UBBL 2016		
<ul style="list-style-type: none"> • Type of detectors • Location of Main Panel • Location of Repeater Panel • Alternate source of power • Hooter's location 	Co/Mo/det.	Provided	MR	
	Required	Provided	MR	
	-NA-	-NA-	-NA-	
	Required	Provided	MR	
	Required	Provided	MR	
8 MOEFA	Required	Provided	MR	
9 Public Address System	-NA-	NA	-NA-	
10 Automatic Sprinkler System				
<ul style="list-style-type: none"> • Basement • Upper floors. • Sprinkler above false ceiling 	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
11 Internal Hydrants.				
<ul style="list-style-type: none"> • Size of Riser/Down-comer • Number of Hydrant per floor • Hose box. 	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
12 Yard Hydrants.				
<ul style="list-style-type: none"> • Total number of hydrants. • Hose box. 	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
13 Pumping arrangements.				
<ul style="list-style-type: none"> • Ground Level <ul style="list-style-type: none"> ➤ Discharge of main pump. ➤ Head of main pump. ➤ Number of main pumps. ➤ Jockey Pump output. ➤ Jockey Pump head. ➤ Standby Pump output. ➤ Standby Pump head. ➤ Auto Starting/Manual Stopping. ➤ Pump house access. • Terrace Level <ul style="list-style-type: none"> ➤ Discharge of pump. ➤ Head of pump. ➤ Power supply. ➤ Auto starting of pump. 	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
	450 LPM	Provided	MR	
	40m	Provided	MR	
	Required	Provided	MR	
	Required	Provided	MR	
	14 Captive water storage for fire fighting.			
<ul style="list-style-type: none"> • Underground tank capacity. <ul style="list-style-type: none"> ➤ Draw-off connection. ➤ Fire Service Inlet. ➤ Access to tank. • Overhead tank capacity. 	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
	20,000 ltrs	Provided	MR	
15 Exit Signage.	Required	Provided	MR	
16 Provision of Lifts.				
<ul style="list-style-type: none"> • Pressurization of lift shaft. • Pressurization of lift lobby. • Communication in lift car. • Fireman's switch. • Lift signage. 	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
	Required	Provided	MR	
	Required	Provided	MR	
	Required	Provided	MR	
17 Standby Power Supply	Required	Provided	MR	
18 Refuge Area				
<ul style="list-style-type: none"> • Total area • Location 	-NA-	-NA-	-NA-	
	-NA-	-NA-	-NA-	
19 Fire Control Room.				
<ul style="list-style-type: none"> • Detector system panel. 	-NA-	-NA-	-NA-	

2

3

M118

	• Flow switch panel.	-NA-	-NA-	-NA-
	• PA system panel.	-NA-	-NA-	-NA-
	• Battery backup.	-NA-	-NA-	-NA-
	• Building floor plan.	-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any.			-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection and 4th floor sealed with brick wall by the management.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 450 dated 30/08/2023.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010.

Accordingly, DFA is put up for approval and signature please.

Handwritten signature

Signature of the Inspection Officer
Name: Sh. Manoj Kumar Sharma
Design: DO (South)

Handwritten signature and date
13/9/2023

Signature of the Inspecting Officer
Name: Sh. Rajesh Kumar
Design: ADO (BCP)

CFO (HQ)

Handwritten signature and date
14/9/2023

Handwritten signature and date
Director 13/9/23

Handwritten signature
ADU/BCP

As approved, F.S. letter is put up for your signature P1

Handwritten signature and date
14/9/2023

Handwritten signature and date
Director 13/9/23

Handwritten signature
om

uploaded
19/9/23

Handwritten signature