

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/GH/SZ/2023/155

FIRE SAFETY CERTIFICATE

Certified that the M/s Karon Hotel (Guest House) located at 61, Ring Road, Lajpat Nagar-III, New Delhi, comprised of Basement + Ground + 03 upper floors: Basement - Office Space + Store + Services, Ground floor- Others Property (Mega Store), 1st floor - 09 Guest rooms + Pantry + Dining room (for inhouse guest only), 2nd floor- 11 Guest rooms, 3rd floor - 11 Guest rooms total 31 Guest rooms was granted Fire Safety Certificate (FSC) by this department vide letter no. F6/DFS/MS/GH/2019/SZ/2296 dated 10.12.2019. The premises was re-inspected by the officer concerned of this department on 22.09.2023 in presence of Mr. Deepak Bakshi (Manager) and found that the building /premises has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of Group 'A (Residential) sub division A-1, having 31 guest rooms (1st floor - 09 Guest rooms + Pantry + Dining room (for inhouse guest only), 2nd floor- 11 Guest rooms, 3rd floor - 11 Guest rooms) and valid upto 31.03.2026 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on27 0.9. 22.3.....at New Delhi by

Reference: MHA Portal Online application no. 2023081414587 dated 18.09.2023

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- Basement shall be used as per NBC/UBBL.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.
- 9. This FSC is valid for 1st to 3rd floor only.

1	N	ame a	& address of the building					
2	Building is comprised of			Ring Road, Lajpat Nagar-III, New Delhi. Basement + Ground + 03 upper floors Basement- Office Space + Store + Services				
					ners Property (Mega S			
					t rooms + Pantry + D			
				room (fo	or inhouse guest only)		
				2 nd floor - 11 Gues	st rooms			
3	T	pe o	f occupancy	3 rd floor - 11 Guest rooms Residential, 'Group-A''(Guest House)				
4	_		f case	Renewal				
5	-	-	of Previous FSC	A TOTAL CONTROL OF THE PARTY OF	019/SZ/2296 dated 1	0 12 2010		
6	-		fety directive letter no.	Nil	019/32/2290 dated 1	0.12.2019		
7	Date of inspection			22.09.2023				
8			of the inspecting officers	Rajesh Kumar Shukla ADO (M. Road)				
9			of the designation of		HT. TT 1			
	officer from the building side Year of construction			Mr. Deepak Bakshi (Manager) Nil				
10								
11	Applicant's letter no.		ant's letter no.	Online application no. 2023081414587 dated				
	0.5			18.09.2023	110. 202300141	Jor daled		
S.No	M	inim	um Standards on fire					
			tion and fire safety	per Rule 35 (6)	at bite	MR/NMR		
	re	quire	ements U/R 33		1.4-4-4	- TANKININ		
	A	cess	to building					
1	A			6.0 mtrs	Provided	MR		
	В	G	ate width	NA	NA	NA		
	C		idth of internal road	NA	NA	NA		
2		ımbe	er, Width, Type and Arran	gement of Exits				
	A Number of staircases			A Property of				
		a	Upper floor	2 nos.	2 nos.	MR		
	_	b	Basement	2 nos.	2 nos.	MR		
-31	В	1000	Width of staircases					
		a	Upper floor	1.30 m & 0.80 m	1.30 m & 0.80 m	MR (Old		
		Ь	Basement	1 20 0 0 00		Case)		
		-	Suscincin	1.30 m & 0.80 m	1.30 m & 0.80 m	MR (Old		
	C	Pr	otection of exits (Required	as per clause 7.21	(v) HDDI acco	Case)		
			THE CHOCK GOOD	Required Required	(x) UBBL 2016 (am			
		b	Pressurization	NA	Provided NA	MR		
	D	- Continuous staircases		NA	NA	NA		
	to terrace					NA		
	E	_	dth of corridor	NA	NA	NA		
-	F	Do	or size	1.0 m	1.0 mtrs (final	MR		
	Co	Compartmentation			exits)	IVII		
	A							
	B	1110011 4001		NA	NA	NA		
	C	Fire	rating of checking shatts	NA	NA	NA		
			rating of shaft door er curtain	NA	NA	NA		
+				NA	NA	NA		
	E Fire dampers Smoke Management System. ((amended)			NA		NΔ		
	(an	end.	Management System. (Required as per	clause 7.31 (x)	URRI 20		
	A	Page	ement		(a)	2DDL 20		
	A	Dase	ment	Natural/	Exhaust fans	MD		
	В	B Upper floor		Mechanical	and Idiis	MR		
100	_	- bb	- 1100I	Natural/	Exhaust fans			
				Mechanical	Exilaust fanc	MR		

M/s	Karon I	Hotel quest	house.61.	Lainat Nagar	-III. New Delhi
-----	---------	-------------	-----------	--------------	-----------------

5.	Fire Extinguisher						
	A	Total numbe		10 nos.	10 nos.	MR	
	В	Types		CO ₂ & ABC	ABC type	MR	
	C	ISI marking	THE STATE OF THE S	ISI marked	Provided	MR	
6	First-Aid-Hose Reels						
•	A			01 no.	Provided	MR	
	B			30 mtrs.	Provided	MR	
				5 mm	Provided	MR	
	C Nozzle diameter						
7	Automatic Fire Detection And Alarming System (required as per clause 7.31. UBBL 2016).						
	A	Type of det	ectors	CO detectors	Provided	MR	
	В	Location of	main panel	At 1st floor	Provided	MR	
	C	Location of	repeater panel	NA	NA	NA	
	D		ource of power	NA	NA	NA	
	E	Hooters	Desired thought	Audible in entire building	Provided	MR	
8	Me	DEFA	SERVINGER WHEN	Required	Provided	MR	
9	Pu	blic Address	System.	Required	Provided	MR	
10	_		nkler System.		-V		
10	A	Basement	OF THE PARTY	Required	Provided	MR	
	В	Upper floor	`	NA ·	NA	NA	
	C		ove false ceiling	NA	NA	NA	
11							
11	Internal Hydrants					NIA	
	A			NA NA	100 mm	NA	
	В			NA	1 no.	NA	
	C	Hose box	D1	NA	1 no.	NA	
12	+	rd Hydrants					
	A	Contraction	r of hydrants	NA	NA	NA	
	B Hose box		NA	NA	NA		
13	Pumping Arrangements.						
	A	Ground	Level				
		a Discha	rge of main Pump	NA .	NA	NA	
		b Head o	f Main Pump	NA	NA	NA	
		c Numbe	r of main pumps	NA	NA	NA	
			pump out put	NA	NA	NA	
	20		pump head	NA	NA	NA	
			y pump out put	NA	NA	NA	
	h.		y pump Head	NA	NA	NA	
		h Auto S	tarting /Manual	NA	NA	NA	
		stoppin					
	-		iouse access	NA	NA	NA	
	В	Terrace Le					
		a Discha	rge of pump	Boosting Arrangement	450 LPM + 180 LPM	MR	
		b Head o	f the Pump	NA	35 mtrs	MR	
		c Power	supply	Required	Provided	MR	
		d Auto st					



14	M/s Karon Hotel guest house, 61, Lajpat Nagar-III, New Delhi Captive Water Storage for Fire Fighting.							
	A Underground tank canacity	15.17						
	B Draw-off connection	NA	NA	NA				
	C Fire service inlet	NA	NA	NA				
	D Access to tank	NA	NA	NA				
	E Overhead tank capacity	NA 5 000 1	NA	NA				
15	Exit Signage.	5,000 ltrs	7,000 ltrs	MR				
16	Provision of Lifts.	Required	Provided	MR				
	A Pressurization of lift shaft	NA	NA	NA				
	B Pressurization of lift lobby	NA	NA	NA				
	C Communication in lift car	Required	Provided	MR				
	D Firemen's grounding switch	Required	Provided	MR				
	E Lift signage	Required	Provided	MR				
17	Standby Power Supply	Required	Provided	MR				
18	Refuge Area.							
	A Total area	NA	NA	NA				
	B Location	NA	NA	NA				
19	Fire Control Room							
	A Detector system panel	NA	NA	NA				
	B Flow switch panel	NA	NA	NA				
	C PA system panel	NA	NA	NA				
	D Battery backup	NA	NA	NA				
	E Building floor plans	NA	NA	NA				
20	Special Fire Protection Systems For Protection Of Special Risks, If Any:	NA	NA	NA				

Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

The shortcomings issued to the building vide letter no. F6/DFS/MS/GH/SZ/2022/565 dated 12.07.2022 has been rectified by the management.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/2019/SZ/2296 dated 10.12.2019 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (M. Road)

DO (SD)

23/9/2

Director / 19 19 19

or Jaks