

chig





## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001 No.F6/DFS/MS/NDZ/2023/NDZ/ Sch 675 Dated: 26 / 09 /2023

## FIRE SAFETY CERTIFICATE

Certified that the Nav Jeevan Adarsh Public School, located at Maan Singh Nagar, Mustafabad, Delhi-110094, comprised of Ground plus Three upper floors, owned / occupied by Nav Jeevan Adarsh Public School, was issued FSC vide letter No. F6/DFS/MS/School/2019/NDZ/2339 Dt. 18/12/2019. The School building was re-inspected by the officer concerned of this department on 15/09/2023 in presence of Mr. Mohit Bansal and observed that all the Fire Prevention and Fire Safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with rule 33 of the Delhi Fire Service Rule, 2010 and that the building is fit for occupancy class "Educational" (Group-B) with effect from \$\frac{1}{2}6 \frac{1}{2}09 \frac{1}{2}023\$ for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 26/09/2023 at New Delhi by.

DELHI FIRE SERVICE.

Copy to:-

1. The Principal, Nav Jeevan Adarsh Public School, Maan Singh Nagar, Mustafabad, Delhi-110094.

2. The Dy. Director of Education, B-Block, Yamuna Vihar, Delhi-110053.

## Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided therein shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the Management.
- 3. The trained firefighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc. shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction, if any.
- 6. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

**INSPECTION REPORT** 

1. Name & address of the building: Nav Jeevan Adarsh Public School,

Maan Singh Nagar, Mustafabad, Delhi-110094.

2. Building is comprised of : Ground Plus Three upper floors. (3rd floor only one room)

3. Type of Occupancy : Educational 4. Type of Case : Renewal

5. Details of previous NOC : F6/DFS/MS/School/2019/NDZ/2339 Dt. 18/12/2019

6. Fire Safety directives Letter No.: NBC (Part-IV) 7. Date of inspection : 15/09/2023

8. Name of the Inspecting Officer: A.K. Jaiswal, D.O. (E.D.)

9. Name and designation of Officer

from the building side : Mr. Mohit Bansal 10. Year of Construction

: 2007

S.No.	olicant's letter No. : Nil dt. : Minimum Standards on fire	21/08/2023		-			
0	prevention and fire safety U/R 33	NBC (Part-IV)	Provided at Site	Remar			
1	Access to building	Requirement					
	Road width	6.0 m	6.0 m	M/D			
	• Gate width	N/A		M/R			
	Width of internal road	N/A	N/A N/A	N/A N/A			
2	Number, Width, Type and Arrange		N/A	IN/A			
2 1	a. Number of Staircases	Inche of Exits		1			
	• Upper Floor	01 Nos.	02 Nos.	MR			
	Basement	N/A	N/A	N/A			
	b. Width of Staircases		1111	11/11			
	• Upper Floor	1.50 M	1.12 m & 0.82 m /	MR (old accepted)			
	Basement	N/A	N/A	N/A			
	c. Protection of exits		PARTY PARTY NAMED IN THE PARTY N				
	• Fire check door	N/A	N/A	N/A			
	Pressurization	N/A	N/A	N/A			
	d. No. of continuous staircases to terrace	01 Nos.	01 Nos.	MR			
	e. Width of Corridor	1.50 M	2.00 M	MR /			
ilu.	f. Door size	1.0 M	1.0 M	MR -			
3	Compartmentation						
	Fire check Door	N/A	N/A	N/A			
	Sealing of electrical Shafts	N/A	N/A	N/A			
	Fire rating of Shaft Door	N/A	N/A	N/A			
	Water Curtain	N/A	N/A	N/A			
	Fire Dampers	N/A	N/A	N/A			
4	Smoke Management System						
	Basement	N/A	N/A	N/A			
1	Upper Floors	N/A	N/A	N/A			
5	Fire Extinguishers						
	Total Numbers	10 Nos.	12 Nos.	MR /			
	• Types	ABC & Co2	ABC & Co2	MR			
	IS Marking	ISI Marked	ISI Marked	MR			



5	First-aid-Hose Reels						
	Total numbers of each floor	01 Nos.	01 Nos.	MR /			
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	30 m	MR			
	Nozzle diameter	05 mm	05 mm	MR			
7	Automatic fire detection and alarming system						
	Type of detectors	N/A	N/A	N/A			
	Location of main panel	N/A	N/A	N/A			
	Location of repeater panel	N/A	N/A	N/A			
3	Alternate source of power	N/A	N/A	N/A			
	MOEFA	N/A	N/A	N/A			
	Public address System	N/A	N/A	N/A			
0	Automatic Sprinkler System						
	Basement	N/A	N/A	N/A			
	Upper Floor	N/A	N/A	N/A			
	Sprinkler above false Ceiling	N/A	N/A	N/A			
1	Internal Hydrants	1	W-11.6	Landing			
	Size of rise/down-comer	N/A	N/A	N/A			
	Number of Hydrants per Floor	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
2	Yard Hydrants						
	Total number of Hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
3	Pumping Arrangements	V		- 4			
	Ground Level	The District		201			
	Discharge of main Pump	N/A	N/A	N/A			
	Head of Main Pump	N/A	N/A	N/A			
	Number of main Pumps	N/A	N/A	N/A			
	Jockey pump output	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	> Standby pump output	N/A	N/A	N/A			
	Standby pump head	N/A	N/A	N/A			
	Auto starting/Manual stopping	N/A	N/A	N/A			
	> Pump house access	N/A	N/A	N/A			
	Terrace Level	The second		2 41 14			
	> Discharge of pump	450 LPM	450 LPM	MR			
	> head of the pump	40 M	40 M	MR			
	> Power supply	Required	Provided '	MR			
	Auto Starting of pump	Required	Provided	MR			
4	Captive Water Storage for Fire Fighti		AND PROPERTY OF	real field			
•	Underground tank capacity	N/A	N/A	N/A			
	> Draw-off connection	N/A	N/A	N/A			
	> Fire service inlet	N/A	N/A	N/A			
	> Access to tank	N/A	N/A	N/A			
	• overhead Tank capacity	10,000 Ltrs.	10,000 Ltrs.	MR			
	Exit Signage	Required	Provided	MR			



16	Provision of Lifts	-	150.44	Lervi		
	Pressurization of Lift Shaft     Pressurization of Lift lobby     Communication in lift car     Firemen's grounding switch	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
17	Standby power supply					
18	Refuge Area  Total area Location	N/A	N/A	N/A		
		N/A	N/A	N/A		
	- tual Poom					
19	Detector system panel     Flow switch panel     PA system panel     Battery backup	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
100	Building floor plans		N/A	N/A		
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	ilding were tested.			

The fire protection systems provided in the building were tested, checked and found

functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, The Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/2019/NDZ/2339 Dt. 18/12/2019 renewa under NBC (Part-IV) is recommended.

> Signature of the Inspecting Office Name: Ashok Kumar Jaiswal Designation: D.O. (East. Div.)

Broyed, F.T. Letter is