

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**



No. F6/DFS/MS/2023/School/632

Dated: 14 /09/2023

## FIRE SAFETY CERTIFICATE

Certified that the Pragati Memorial Public School located at 16, Gali No. 17, A-Block, Bangali Colony, Sant Nagar, Burari, Delhi-110084 comprised of Ground & 02 upper floors but school is running at ground & first floor only owned / occupied by Pragati Memorial Public School was issued Fire Safety Certificated vide this office letter no.F6/DFS/MS/2018/School/WZ/1543 dated 03.07.2018. The premises was re-inspected by the officer concerned of this department on 01.09.2023 in the presence of Mr. Narendra Bishal (Owner) and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011and the building/ premise is fit for occupancy "Group B Educational" for ground & first floor only with effect from 14. 6.9. 2223.... for a period of Valid up to 31.03.2026, subject to compliance of the conditions mentioned below:

Issued on .14 09. 2.2.3..... at New Delhi

Ph:-011-23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.

2. The Principal, Pragati Memorial Public School located at 16, Gali No. 17, A-Block, Bangali Colony, Sant Nagar, Burari, Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first Service Rules http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms. 2010. The form is

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-

2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its

## NA

## INSPECTION REPORT

1. Name & address of the building : Pragati Memorial Public School, 16, Gali No. 17, A-Block,

Bangali Colony, Sant Nagar, Burari, Delhi-110084.

2. Type of Occupancy : Educational

3. Composition of building : Ground & 02 upper floors but school is running at ground

& first floor only

4. Type of Case : Renewal

5. Details of previous NOC : F6/DFS/MS/2018/School/WZ/1543 Dated: 03.07.2018

6. Fire Safety directives letter No : Nil

7. Date of inspection : 01.09.2023

8. Name of the Inspecting Officers : ADO (RN)

9. Name and designation of officers

from the building side : Sh. Narendra Bishal (Owner)

10. Year of Construction : 2009

	Area-360 m2 Covered area450 m2, Minimum Standards on fire prevention and	No of student—	Provided at site	Remarks		
	fire safety U/R 33	Requirement as per Rule 35 (6)	Provided at site	MR/NMR		
	Access to building					
	Road width	06m	5.10m	MR(old case)		
	Gate width	4.5m	3.0m	MR(old case)		
	Width of internal road	NA	NA	NA		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases		91			
	Upper Floors	02	02	MR		
	Basements     Wide Gasiness	NA	NA .	NA		
	b. Width of staircases					
	Upper Floors     Basements	1.50 m	1.10m & 1.00m(iron staircase)	MR(old case		
	c. Protection of exits	NA	NA	NA		
	Fire check door	NA	NA	NA		
	Pressurization	NA NA	NA NA	NA NA		
	d. No. of continuous staircases to terrace	NA	Olno	NA		
	e. Width of Corridor	NA	NA	NA		
	f. Door Size	1.0m	1.0m	MR		
}	Compartmentation.					
	Fire check door	NA	NA	NA		
	Sealing of electrical shafts	NA	NA	NA		
	Fire Rating of shaft door	NA	NA	NA		
	Water Curtain	NA	NA	NΛ		
	Fire Dampers	NΛ	NA	NA		
4	Smoke Management System.					
	Basements	NA	NA	NA		
	Upper floors	Required	Natural Ventilation	MR		
5	Fire Extinguishers					
	Total numbers	05nos	06nos	MR		

N	15

	• Types	ABC/Co2	ABC-06	MR		
	ISI marking	Yes	Yes	MR		
6	First-Aid Hose Reels.					
1	Total numbers on each floor	NA	NA	NA		
	Length of hose reel hose	NA	NA	NA		
	Nozzle diameter	NA	NA	NA		
7	Automatic fire detection and alarming system					
	Type of detectors	NA	NA	NA		
	Location of Main Panel	NA	NA	NA		
	Location of Repeater Panel	NA	NA	NA		
	Alternate source of power	NA	NA	NA		
	Hooters' Location	NA	NA	NA		
8	MOEFA	NA	NA	NA		
9	Public Address System.	NA	NA	NA		
10	Automatic Sprinkler System.					
V:35	Basement	NA	NA	NA		
	Upper Floor	NA	NA	NA		
	Sprinkler above false ceiling	NA	NA	NA		
11	Internal Hydrants	×				
	Size of riser/down-comer	NA	NA	NA		
	<ul> <li>Number of hydrants per floor</li> </ul>	NA	NA	NA		
	Hose Box	NA	NA	NA		
12	Yard Hydrants.					
	Total number of hydrants	NA	NA	NA		
	Hose Box	NA	· NA	NA		
13	Pumping Arrangements.					
	Ground Level		2020	200000		
	<ul> <li>Discharge of main Pump</li> </ul>	N/A	N/A	N/A		
	> Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A .	N/A		
	> Standby Pump out put		N/A	N/A		
	> Standby Pump Head	N/A				
	<ul> <li>Auto Starting/ Manual stopping</li> <li>Pump House Access</li> </ul>	N/A	N/A	N/A		
	Terrace level	N/A	N/A	N/A		
	> Discharge of pump			1		
	> Head of the pump	NA	NA	NA		
	> Power Supply	NA	NA	NA		
	> Auto Starting of pump	NA	NA	NA		
	runo otarring or pump	NΛ	NA	NA		
14	Captive Water Storage for fire fighting.		The second secon			
	Underground tank capacity	NA	NA	NA		
	Draw-off connection	NA	NA	NA		
	Fire service inlet	NA	NA	NΛ		
	> Access to tank	NA	NA	ÑΑ		
	Overhead Tank capacity	NΛ	NA	NA		
		INA	INA /	14/4		

- 44	1000	-
-	OSF BETTER	
2014	D	
N/I		207

MR	Exit Signage.	Required	Provided	MR	
1	payising of Lifts.				
16	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication In lift Car	N/A	N/A	N/A	
	• Fireman's Grounding Switch	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
7	Standby power supply	N/A	N/A	N/A	
8	Refuge Area.				
	> Total Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
9	Fire Control Room				
	Detector System Panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel	N/A	N/A	N/A	
	Batter backup	N/A	N/A	N/A	
	Building Floor Plans	N/A	N/A	N/A	
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested/ checked randomly and found in

good working condition, at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to vide this department letter of even no. renewal of fire safety certificate issued F6/DFS/MS/2018/School/WZ/1543 dated 03.07.2018.

Signature of the Inspecting Office Name :-C.L. Meena

Designation:- ADO/RN

M.K. Chattopadhyay Dy. Chief Fire Officer (NWD)