

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2023/SZ/ 298

Dated: 37/09/2023

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s Reliance Brand Limited located at Ground floor, Select City Walk Mall, A-3, District Centre, Saket, New Delhi-110017 in the building comprised of 03 Tier Basement, Ground plus 07 Upper Floors owned/occupied by Unit of Reliance Brand Limited have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 18/09/2023 in the presence of Ms Parul and that the premise is fit for occupancy class Group—D Assembly (Restaurant at Ground Floor only) and valid upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on $\frac{97}{09}$ /2023 at New Delhi by

DIRECTOR

DELHI FIRE SERVICE

Copy to: -

 The Dy. Health Officer, Public Health Department, MCD, Aurobindo Marg, Green Park, New Delhi 110016. (Ref. MHA Portal ID 2023083015441 dated 01/09/2023)

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The basement shall be used as per the provisions of UBBL 2016/NBC Part- IV.
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."
- The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in





1 1	Name & Address S.	TON REPORT		out of the same	
	Name & Address of the Building	TON REPORT	builtinb(Inmaxa)		
		M/s Reliance Br	rand Limited located at (Ground floo	
2	Type of Occupancy	Sciect City Wall	Mall A-3 District C	entre, Sake	
3	Building Comprised of	110017			
4	Type of Case	Assembly Building. (Restaurant at Ground floor only)			
5	Details on	03 tier Basements, Ground + 07 Upper Floors			
	Details of Previous NOC	New case		H	
	Fire Safety Directives Letter No	Nil			
B 2.8 (*)	lougar a	F.6/MS/DFS/BP/2006/1141 dated 15/05/2006 & F.6/MS/DFS/BP/2016/299 dated 23/11/2017,			
7	Date of Inspection	f6/DFS/MS/BP/2010	6/299 dated 23/11/2017, /431 dated 05/10/2021 for Mail		
8	Name of the Y	18/09/2023	431 dated 05/10/2021 for Mal		
9	Name of the Inspecting Officers		20 (DCD)	-	
	The Control of Control	DO (South) & AI			
10	Tom the building side	Ms Parul	acing sand-old constraint	2	
10	Year of construction	2007 1-	1-19-11	1	
11	Applicant letter No.	2007 Restt at	Ground floor of Mall b	dg	
S.	Minimum standards on Fire Deve		023083015441 dated 01/0	9/2023	
No.	and Fire Safety U/R 33	UBBL/NBC	Provided at Site	Remark	
1	Access to Building	Requirements	on large than pales of	MR/NM	
81	Road width (Select City	Walk Mall - F.6/DFS	/MS/Mall/202/SZ/335 Dt. 2	27/07/2022)	
	Gate width	9m	Provided by Mall	MR	
100	Width of internal road	5m	Provided by Mall	MR	
2		6m	Provided by Mall	MR	
2	Number, width, type & arrangement of exits.		fuggire cares a sample	IVIIC	
The s	Number of Staircase Provided 8 Miles 11 Cl. Co.				
2017	Upper floors.	02 Nos	12 Nos Provided*		
377.5	Basement floor.	N/A		MR	
91.1	Width of Staircase	N/A N/A N/A Provided & Maintained by Select City Walk, Saket			
1	Upper floors	1.50 mtr each			
	Basement floor	N/A	Provided*	MR	
817	Protection of exits	The state of the s	N/A	N/A	
77 to	Fire check door	Provided & Maintained by Select City Walk, Saket			
1910	Pressurization	Required	Provided*	MR	
	No. of continuous staircase to terrace	Required	Provided*	MR	
	Width of corridor	Restt within Mall	-NA-	MR	
A.HIE		Required	Provided	MR	
2	Door size	02 x 1.50 mtr	1.50 m each	MR	
3	Compartmentation.	Provided & Main	ntained by Select City Wa	lk, Saket	
217	Fire check door.	Required	Provided*	MR	
MHs	Sealing of electrical shafts.	Required	Provided*	MR	
MA	Fire rating of shaft door.	N/A	N/A	N/A	
No.	Water curtain	N/A	N/A	N/A	
alle !	Fire dampers.	N/A	N/A	N/A	
4	Smoke Management system.	Provided & Mai	ntained by Select City Wa	dlk Sub-u	
411	Basement	30 ACPII	N/A	N/A	
387	Upper floors	12 ACPH	Exhaust Fans Provided		
5	Fire Extinguishers.		Tovideo	IVIK	
170	Total numbers	Required	06 Nos	MD	
5110	Types	ABC/CO ₂	ABC & CO ₂	MR	
	ISI Marking	Required	Provided	MR	
6	First Aid Hose Reels.		ntained by Calast C's are	MR	
0	Total numbers on each floor.	One near Restt	ntained by Select City W		
	Length of hose-reel hose.	30m	Provided*	MR	
100	Nozzle Diameter	5mm	Provided*	MR	
_	Automatic fire detection & alarming system		Provided*	MR	
7			aintained by Select City V	Valk, Saket	
	Type of detectors	Required	Provided*	MR	



	Location of Main Panel	Required	Provided*	MR	
	Location of Repeater Panel	Required	Provided*	MR	
	Alternate source of power	Required	Provided*	MR	
	Hooter's location	Required	Provided*	MR	
8	MOEFA	Required		300000	
9	Public Address System	N/A	Provided*	MR	
10	Automatic Sprinkler System	111.000.000	NA NA	NA NA	
-	Basement	Provided & Maintained by Select City Walk, Saket			
	Upper floor	Required	Provided*	MR	
	Sprinkler above false ceiling	Required	Provided*	MR	
11	Internal Hydrants.	Required	Provided*	MR	
•	Size of Riser/Down-comer	Provided & Maintained by Select City Walk, Saket			
	Number of Hydrant per floor	Required	Provided*	MR	
	Hose box.	Required	Provided*	MR	
12		Required	Provided*	MR	
12	Yard Hydrants.		intained by Select City W	alk, Sake	
100	Total number of hydrants.	Required	Provided*	MR	
10	Hose box.	Required	Provided*	MR	
13	Pumping arrangements.		intained by Select City W		
	Ground Level	Common pumping arrangements for entire bldg			
	Discharge of main pump.	4500 LPM	Provided*	MR	
	Head of main pump.	88m	Provided*	MR	
TD ₂	Number of main pumps.	02 Nos.	Provided*	MR	
i	Jockey Pump output.	180 LPM	Provided*	MR	
	Jockey Pump head.	88m	Provided*	MR	
100	Standby Pump output.	4500 LPM	Provided*	MR	
	Standby Pump head.	88m	Provided*	MR	
4	Auto Starting/Manual Stopping.	Required	Provided*	MR	
i	Pump house access.	Required	Provided*	MR	
	Terrace Level				
-	Discharge of pump.	450 LPM	Provided*	MR	
3.6	Head of pump.	40 m	Provided*	MR	
20.	Power supply.	Required	Provided*	MR	
	Auto starting of pump.	Required	Provided*	MR	
14	Captive water storage for fire fighting.		intained by Select City Wa		
	Underground tank capacity.	5,00, 000 ltr	Provided*	MR	
	Draw-off connection.	Required	Provided*	MR	
	Fire Service Inlet.	Required	Provided*	MR	
	Access to tank.	Required	Provided*	MR	
İ	Overhead tank capacity.	20,000 ltr	30,000 ltr	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.		intained by Select City Wa		
10	Pressurization of lift shaft.		Provided*		
	Pressurization of lift lobby.	Required		MR	
	Communication in lift car.	Required	Provided*	MR	
200	Fireman's switch.	Required	Provided*	MR	
		Required	Provided*	MR	
	Lift signage.	Required	Provided*	MR	
17	Standby Power Supply	Required	Provided*	MR	
18	Refuge Area		1	1	
	Total area	N/A	N/A	N/A	
9 🖟	Location	N/A	N/A	N/A	
19	Fire Control Room.	Provided & Maintained by Select City Walk, Saket			
	Detector system panel.	Required	Provided*	MR	
	Flow switch panel.	Required	Provided* Provided*	MR	
	PA system panel.				



	Battery backup. Building floor plan.	Required	Provided*	MR
	Special Fire Protection System for the Protection of special Risk, if any.	Required	Provided*	MR
20		Required	Provided*	MR

M/s Reliance Brand Limited located at Ground floor, Select City Walk Mall, A-3, District Centre, Saket, New Delhi- 110017

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly DFA is put up for approval and signature please.

Signature of the Inspection Officer

Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CFO (HQ) As approved, f.t. teller is probably your synature PI