

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELHI- 110001

गाजादी न अमृत महोत्सव

No. F6/DFS/MS/GH/SZ/2023/157

Dated: 29 09 2023

FIRE SAFETY CERTIFICATE

Certified that the M/s Rosemallow Hotel (Guest House) located at C-18, Friends Colony East, New Delhi-110065, comprised of Basement + Stilt + Upper ground + 3 upper floors: Basement - lying vacant + pump room, Upper ground - 12 guest rooms + Pantry, 1st floor - 15 Guest rooms, 2nd floor - 15 Guest rooms, 3rd floor - 15 Guest rooms, was granted Fire Safety Certificate (FSC) by this department vide letter no. F6/DFS/MS/GH/2016/SZ/969 dated 08.06.2016. The premises was re-inspected by the officer concerned of this department on 22.09.2023 in presence of Mr. Ranjeet (Owner) and found that the building /premises has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of Group 'A (Residential) sub division A-1, (Upper ground - 12 guest rooms + Pantry 1st floor - 15 Guest rooms, 2nd floor- 15 Guest rooms, 3rd floor - 15 Guest rooms) and valid upto 31.03.2026 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on ... 29 6.9 2.2.3at New Delhi by

Director Delhi Fire Service

Reference: MHA Portal Online application no. 2023091516013 dated 15.09.2023 Copy to:-

Q11/23 D

 The Commissioner, Delhi Municipal Corporation, 9th Floor, Dr. SPM Civic Centre, Minto Road, New Delhi–110002- To ensure the use of Basement & Stilt as per approved plan.

Conditions for the validity of Fire Safety Certificate

- All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. Basement shall be used as per NBC/UBBL.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.
- 9. This FSC is valid for Upper ground to 3rd floor only.

		INSPE	CTION REPORT				
1	N	Name & address of the building M/s Rosemallow Hotel (Guest House) located C-18, Friends Colony East, New Delhi-110065.					
2	В	uilding is comprised of	Basement + Stilt + upper ground + 3 upper floors Basement - lying vacant + pump room + service Upper ground - 12 guest rooms + Pantry 1 st floor- 15 guest rooms 2 nd floor- 15 guest rooms 3 rd floor- 15 guest rooms				
3	T	ype of occupancy	Residential Group				
4	T	ype of case	Renewal		The second		
5	D	etails of Previous FSC	F6/DFS/MS/GH/20	016/SZ/969 dated	08.06.2016		
6	Fi	re Safety direction letter no.	Nil	-			
7		ate of inspection	22.09.2023				
8		Name of the inspecting officers Rajesh Kumar Shukla ADO (M. Road)					
9	N	ame of the designation of officer	Mr. Ranjeet (Owner)				
10		ear of construction	2009				
11	A	Applicant's letter no. Online application no. 2023091516013 date 15.09.2023					
S.No	Pı	linimum Standards on fire revention and fire safety quirements U/R 33	Requirement as per Rule 35 (6)	Provided at Site	Remarks MR/NMR		
1	A	ccess to building					
	A	Road width	6.0 mtrs	6.10 mtrs	MR		
	B	Gate width	NA	NA	NA		
	C	Width of internal road	NA SErita	NA	NA		
2	-	Imber, Width, Type and Arrangen Number of staircases	nent of Exits				
	A		02 nos.	02 nos.	MR		
		a Upper floor b Basement	02 nos.	02 nos.	MR		
	В	Width of staircases	02 1100.	02 H00.	-		
	Б	a Upper floor	1.25 mtrs & 0.92 mtrs	Provided	MR		
		b Basement	1.25 mtrs & 0.92 mtrs	Provided	MR		
	C	Protection of exits (Required a	as per clause 7.31. p		L 2016)		
		a Fire check door	Required	Provided	MR		
	D	b Pressurization No. of continuous staircases to	NA 01 no.	NA 01 no.	MR		
	E	Width of corridor	NA	NA	NA		
	F	Door size	NA	NA	NA		
3		mpartmentation	1	L PARTIE			
	A	Fire check door	NA	NA	NA		
	В	Sealing of electrical shafts	NA	NA	NA		
	C	Fire rating of shaft door	NA	NA	NA		
	D	Water curtain	NA	NA	NA		
	E	Fire dampers	NA	NA	NA		
		oke Management System.	14 1 14	Euhaust fan	MR		
2	A	Basement	Mechanical/ Natural Mechanical/	Exhaust fan Exhaust fan	MR		
	В	Upper floor	Natural	Dillium tuli			

5.	Fire Extinguisher							
	A	To	tal numbers	25 nos.	Provided	MR		
	B		pes	ABC	ABC	MR		
	C	-	marking			MR		
6	Fi	rst-A	Aid-Hose Reels	ISI marked	Provided	MK		
	A	To	tal numbers of each floor					
	В	Le	ngth of hose reel hose	1 no.	Provided	MR		
	C	No	ezzle diameter	30 mtrs	Provided	MR		
7				5 mm	Provided	MR		
	Automatic Fire Detection And Alarming System: (Required as per clause7.31.viii							
	A	T	ype of detectors	COdu	I	1.00		
	B	L	ocation of main panel	CO detectors	Provided	MR		
	-		12	At lower	Provided	MR		
	C	L	ocation of repeater panel	ground NA	NA	- N.		
	D E	A	iternate source of nouser	NA NA	NA NA	NA NA		
	L	H	ooters	Audible in	Provided	NA MR		
8	M	OEF	? A	Entire building	Tiovided	MIK		
9	Public Address System.			Required	Provided	MR		
10	An	itom	natic Springs	Required	Provided	MR		
- produce	A	Re	natic Sprinkler System.			·······		
	В		per floor	Required	Provided	MR		
	C			Required	Provided	MR		
11	Printer above false celling			NA	NA	NA NA		
11	In	tern	al Hydrants			INA		
	A	Siz	e of riser/down-comer	100 mm	Provided	100		
	B	Nu	mber of hydrants per floor	01 nos.	Provided	MR		
	C	Ho	se box	01 nos.	Provided	MR		
12		rd I	Hydrants.		riovided	MR		
	A Total number of hydrants			NA	NA	155.		
	В	Ho	se box	NA	Control of the contro	NA		
13	Pu	mpi	ng Arrangements.		NA	NA		
	A		Ground Level					
		a	Discharge of main Pump	450 LPM	Decrit 1			
		b	Head of Main Pump	40 mtrs	Provided	MR		
		С	Number of main pumps	01 no	Provided	MR		
		d	Jockey pump out put	180 LPM	Provided	MR		
		e	Jockey pump head	40 mtrs	Provided	MR		
		f	Standby pump out put	NA NA	Provided	MR		
		g	Standby pump Head	NA NA	NA	NA		
		h	Auto Starting /Manual	Required	NA Provided	NA		
			stopping	- Augunou	riovided	MR		
	_	i	Pump house access	NA	NA	NA		
	В		errace Level					
		a	Discharge of pump	900 LPM	Provided	MR		
		b	Head of the Pump	40 mtrs	Provided	MR		
		С	Power supply	Required	Provided	MR		
		d	Auto starting of pump	Required	Provided	MR		

M/s Rosemallow Hotel (Guest House) located at C-18, Friends Colony East, New Delhi-110065.



M/s Rosemallow Hotel (Guest House) located at C-18, Friends Colony East, New Delhi-110065.

4	semallow Hotel (Guest House) located at C-18, Frie Captive Water Storage for Fire Fightin	g	Provided	MR		
	A Underground tank capacity	33,000 Eus	Provided	MR		
	B Draw-off connection	Required	Provided	MR		
	1 114	Required		NA		
		NA	NA Provided	MR		
	D Access to tank	10,000 Ltrs	Provided	MR		
	E Overhead tank capacity	Required	Provided			
15	Exit Signage.					
16	Provision of Lifts.	NA	NA	NA NA		
	A Pressurization of lift shaft	NA NA	NA	NA		
	Description of lift lobby	NA NA	NA	NA		
	C Communication in lift car	NA NA	NA	NA		
	D Firemen's grounding switch	NA NA	Provided (02 nos.	MR		
	F Lift signage	Required	D.G set-200KVA,			
17	Standby Power Supply		62.5KVA)			
17	Standoy					
	NA					
18	Refuge Area.	NA NA	NA	NA		
	A Total area NA					
	B Location	7	NA	NA NA		
19	Fire Control Room	NA	NA	NA		
	A Detector system panel	NA	NA	-		
	p Flow switch panel	NA	NA	NA		
	C PA system panel	NA	NΔ	NA		
	D Battery backup	NA	Two Co2 type fire	MR		
	E Building floor plans Special Fire Protection Systems For Of Special Risks, If Any:	Required	evtinouishers			
20	Special Fire Protection Systems Protection Of Special Risks, If Any:		found provided of Applicable (NA)			

Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

During inspection, the Owner informed that the guest house name has been changed from 'Tavisha Guest House' to 'Rosemallow Hotel (Guest House)'.

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

The shortcomings issued to the building vide letter no. F6/DFS/MS/GH/SZ/2023/48 dated30.01.2023 has been rectified by the management. Use of Basement & stilt shall be ensured by

In view of the deemed compliance of minimum standards of fire prevention and fire safety MCD as per the approved plan. measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/2016/SZ/969 dated 08.06.2016 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010.

بعلياً

Signature of the Inspecting Officer Rajesh Kumar Shukla Name ADO (M. Road) Designation