

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELIII-110 001

No.F.6/DFS/MS/School/2023/SZ/ 681

Dated: 27/09/2023

FIRE SAFETY CERTIFICATE

Certified that the St. Charles School, Samaspur Khalsa-Ujwa, New Delhi-110073 comprised of ground floor plus two upper floors, owned/occupied by St. Charles School was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/School/2019/SZ/453 dated 28/02/2019. The School building was re-inspected by the officer concerned of this department on 20/09/2023 in the presence of Sh. Kulbhusan (Admin) and found that School building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class educational w.e.f. the date of issue of this certificate for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on ... 27 09 2023

Director Delhi Fire Service

Copy to:-

- 1. The Principal, St. Charles School. Samaspur Khalsa-Ujwa, New Delhi-110073.
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi - 110054

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency. 6. The certificate may not be treated in any case for the regularization of the unauthorized

7. There shall not be more than 45 children in the classrooms having single door.

- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its

N127

INSPECTION REPORT

. Name & address of the building : St. Charles School, Samaspur Khalsa-Ujwa, New Delhi-110073

Building comprised of : Ground plus two upper floors.

3. Type of Occupancy : Educational4. Type of Case : Renewal

5. Details of Previous NOC : F.6/DFS/MS/School/2019/SZ/453 dated 28/02/2019

6. Fire Safety directives letter No : N/A
7. Date of inspection : 20/09/2023

8. Name of Inspecting Officer : A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side : Sh. Kulbhusan (Admin)

10. Year of Construction : 2007 & 2015

11. Applicant's letter No : Nil dated 18/09/2023

S. No.		num Standards on fire prevention and fety U/R 33	Requirements as per FSC dt.28/02/2019	Provided at site	Remarks MR/NMR			
1.	Access	to building						
	:	Road width Gate width Width of internal road	Accessible 4.5 m N/A	Provided Directly accessible from road N/A	M/R M/R N/A			
2.	Number, Width, Type & Arrangement of Exits							
	a. Nui	mber of staircases			10.4			
		Upper Floors	02 No.'s	Provided	M/R			
	•	Basements	N/A	N/A	N/A			
	h Wie	dth of staircases			M/D being ald			
	•	Upper Floor	1.50 m	1.68 & 1.40 m	M/R, being old case			
	•	Basements	N/A	N/A	N/A			
	c. Pro	tection of exits						
	•	Fire check door	N/A	N/A	N/A			
	•	Pressurization	N/A	N/A	N/A			
	100 073 171 Ct 130 215	of continuous staircases to	Required	Provided	M/R			
	terrace e. Width of Corridor		1.50 m	2.40 m	M/R			
		ass Room Door Size	1.0 m	1.13 m	M/R			
3.	Compartmentation							
		Fire check door	N/A	N/A	N/A			
	:	Sealing of electrical shafts	N/A	N/A	N/A			
		Fire Rating of shaft door	N/A	N/A	N/A			
	•	Water Curtain	N/A	N/A	N/A			
	•	Fire Dampers	N/A	N/A	N/A			
	Smoke	Management System			F 1			
	•	Basements	N/A	N/A	N/A			
	•	Upper floors	Required	Natural ventilation provided	M/R			
	Fire Ex	tinguishers		-010	CHARLES I			
	•	Total numbers	07 no's	Provided	MR			
	•	Types	ABC/CO ₂ type	Provided	MR			
	•	IS marking	ISI marked	Provided	MR			



h

8	First-Aid Hose Reels			
	Total numbers on each floor	Two	Provided	MR
		30 m	Provided	MR
		5 mm	Provided	MR
	Nozzle diameter Automatic fire detection and alarming system			
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants			
	 Total number of hydrants 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	Ground Level		Mari III pro-	
	 Discharge of main Pump Head of Main pump 	N/A	N/A	N/A
	> Number of main pumps	N/A	N/A	N/A
	➤ Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head Auto Starting/Manual Stopping	N/A	N/A	N/A
	> Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	
	➤ Pump House Access	N/A	N/A	N/A N/A
	Terrace level			IN/A
	Discharge of pump	450 LPM	Provided	MR
	➤ Head of the pump	30 m	Provided	MR
	> Power Supply	Required	Provided	MR
	> Auto Starting of pump	Required	Provided	MR
14.	Cantive Water Storage for 5 5-1			
	Captive Water Storage for fire fighting	1.		
	 Underground tank capacity Draw-off connection 	N/A	N/A	N/A
×	> Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
15	A VE	10000 ltrs	Provided	MR
15.	Exit Signage.	Required	Provided	MR

1c W

Pro	vision of Lifts.	ion of Lifts. No I				
6.	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car Fireman's Grounding Switch	N/A	N/A	N/A		
		N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
17. Stan	dby power supply	N/A	N/A	N/A		
18. Refu	Refuge Area.					
	Total Area	N/A	N/A	N/A		
	Location	N/A	N/A	N/A		
19. Fire	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel Battery backup Building Floor Plans	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
	cial Fire Protection System for Protection of cial Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/checked at the time of inspection. The shortcomings was issued vide letter no. F6/DFS/MS/School/2022/SZ/145 dated 29/03/2022 has been complied.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2019/SZ/453 dated 28/02/2019 renewal under the Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Note:-As per undertaking submitted by principal of the school at placed (C-32) New building block is under construction which is separate from the old building.

Signature of Inspecting Officer

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

reeta) M

Anofoxi