

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/School/WZ/2023/ 671

Dated: 22/09/2023

FIRE SAFETY CERTIFICATE

Certified that the Surya Public Sec. School Located at 586, Mandir Marg, Nangloi, Delhi110041, comprised of Ground + 02 Upper Floors only owned / occupied by Surya Public Sec.
School, was issued Fire Safety Certificate by this department Vide Letter No.
F.6/MS/DFS/2007/312 dated 02.02.2007. The said premise was re-inspected by the officer concerned of this department on 12.09.2023 in the presence of Sh. Suresh Gahlot and found that the premises/building have deemed complied with the fire prevention and fire safety requirements in accordance D.O.E. Cr. No. 262-362 dated 17.01.2005 and that the premises/building is fit for occupancy class "Educational Building" Group B with effect from 22.09.203 for a period of three years, subject to compliance of the conditions, printed below.

Issued on 22/09/2023 at New Delhi by.

Tel. No. 011-234140

Copy to: -

1. The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi - 110054.

2. The Principal, Surya Public Sec. School, 586 Mandir Marg, Nangloi, Delhi-110041.

Following fire safety directives must be adhered to:-

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
- Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing Department shall always be permitted and followed.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name and address of the building: Surya Public Sec. School, Located at 586,

Mandir Marg, Nangloi, Delhi-110041

: Educational, (Ground+02 Upper Floors) 2. Type of Occupancy

: Renewal 3. Type of Case

: F.6/MS/DFS/2007/312 Dated 02.02.2007 4. Details of previous NOC

: D.O.E. Cr. No. 262-362 dated 17.01.2005 5. Fire Safety directives Letter No.

: 12.09.2023 6. Date of inspection

: Aman Kumar Lathar, ADO (JWP) 7. Name of the Inspecting Officer

8. Name and designation of Officer

: Sh. Suresh Gahlot from the building side

: 2006 9. Year of Construction

: SPS/2023-24/254 dated 18.08.2023 10. Applicant's letter No.

d	10. Applicant's letter No. Minimum standards on fire prevention and fire safety U/R 33	362 dated	r. No. 262- 1 17.01.2005 nents/ as per ed 02.02.2007	Provided at site	Rema MR/N	rks IMR
	Access of building	- PUT		Provided	M	R
1.	Road width Gate width	4.5 m Dire		irect accessible from road	ect accessible MR	
	Width of internal road			NA		
_	Toma & Arrangements of exits					
2.	a. Number of staircases			03	MR	
	Upper floors	02		NA	NA	
	Basements	1	NA	INA	•	
	b. Width of staircasesUpper floors	1.5 m	2) 1 v 0 84	to 1.07 m (G to 2 ^r to 0.97 m (G to T to 1.25 m (G to I	errace) st floor)	MR (Old Case)
			NA	NA		NA
	Basements Societa			No.		1
	c. Protection of exits	NA		NA	NA	
	Fire check door Pressurization No of continuous staircase to terrace Width Of Corridor		NA ·	NA		NA
		(S) (S)	01	Provided		MR
			NA	NA		NA
	f. Door Size		1 m	Provided		MR
-	. Compartmentation		NA	NA		NA
	Fire check door Sealing of electrical		NA	NA		NA
	shafts • Fire Rating of shaft do	or —	NA	NA		NA
	Water Curtain	-	NA	NA		NA
	Water Curtain Fire Dampers		NA	NA		NA
+	Smoke managements System		112			NIA
1	Basements		NA	NA		NA
	Upper floors		NA N	NA		NA

Fi	ire Extinguishers	06	Provided	MR
1	Total numbers	06 nos.	Provided	MR
	• Types	ABC & CO₂	Provided	MR
	IS marking	ISI marked	Flovided	I
F	irst - Aid Hose Reels		Provided	MR
1	 Total numbers on each floor 	01	Provided	MR
	 Length of hose reel hose 	30 m	Provided	MR
	 Nozzle diameter 	5 mm	Flovided	
A	Automatic fire detection and alarm	ing system	NA	NA
	 Type of detectors 	NA	NA NA	NA NA
	 Location of Main Panel 	NA	NA NA	NA
	 Location of Repeater Panel 	NA	NA NA	NA
	 Alternate source of power 	NA	NA NA	NA
	 Hooters' Location 	NA	2000000	
. 1	MOEFA	NA	NA	NA
	Public Address System	NA	NA	NA
0. 7	Automatic Sprinkler System		***	NIA
+	Basements	NA	NA	NA NA
	Upper Floor	NA	NA	NA NA
	 Sprinkler above false ceiling 	ng NA	NA	NA
1.	Internal Hydrants:			T 100
	Size of riser/down-comer	100 mm	Provided	MR
	Number of hydrants per	01	Provided	MR
	floor	01	Provided	MR
	Hose Box			
12.	Yard Hydrants	317		
	Total number of hydrants	NA	NA	NA
	Hose Box	NA	NA	NA
13.	Pumping Arrangements:	E-L-		
	Ground Level			
	Discharge of main pump	NA	NA	NA
	> Head of main pump	NA	NA	NA
	Number of main pumps	NA	NA	NA
	Jockey pump out put	NA	NA	NA
	Jockey pump head	NA	NA	NA
	Standby Pump out put	NA	NA	NA
	> Standby Pump Head	NA	NA	NA
	> Auto Staring/Manual	NA	NA	NA
	stopping			
	> Pump House Access	NA	NA	NA
	Terrace level		1 2222	
	Discharge of pump	220 lpm		MR
	N 11-1-64		225 lpm	
	> Head of the pump	40 m	Provided	MR
	Power supplyAuto starting of pump	Require		MR
		Require	d Provided	MR
14.			1 274	1 374
	Under ground tank capacitation		NA NA	NA NA
	> Draw off connection	NA	NA Provided	NA MP
	Fire service inlet	Require		MR
	Access to tank	NA 2500 ltm	NA 5000 ltm	NA MP
	Overhead Tank capacity Description:			MR
15	Exit Signage	Require	ed Provided	MR
16.		-0 1	NYA .	NIA
	> Pressurization of Lift Sh		NA NA	NA NA
	> Pressurization of lift lob		NA NA	NA NA
	Communication in lift C		NA NA	NA NA
	Fireman's Grounding SLift Signage	witch NA NA	NA NA	NA NA
19.	L LITT SIGNOGE	I NA	NA	I NA
1	Lift Signage	LIVA.	INA	IMI

4	-	
L	35/	
1		

17.	Standby power supply	NA	NA	NA
18.	Refuge Area			
	> Total area	NA	NA	NA
	> Location	NA	NA	NA
19.	Fire control room			
	> Detector system panel	NA	NA	NA
	> Flow Switch Panel	NA	NA	NA
	> PA System Panel	NA	NA	NA
	> Battery backup	NA	NA	NA
	➤ Building Floor Plans	NA	NA	NA
20.	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA	NA

Fire protection systems provided in the building were checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety requirements as per D.O.E Cr. No. 262-362 dated 17.01.2005, renewal of Fire Safety Certificate issued vide letter no.: F.6/MS/DFS/2007/312 Dated 02.02.2007 is recommended.

Accordingly DFA is prepared & put up for approval please.

Sir, Fis. With is put-up for your signature M.

Aman Kumar Lathar ADO (JWP)