



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/Resdl./SZ/2023/ 459

Dated: 03/10 /2023

FIRE SAFETY CERTIFICATE

Certified that the Residential Block No. 9 Type-II Quarters, Kidwai Nagar (East), for GPRA, New Delhi-110023, comprises of three tier Basement, Ground & Fourteen Upper floors, was issued FSC by this department vide letter No. F.6/DFS/MS/Residential/SZ/2018/2553 dated 26/11/2018 & F.6/DFS/MS/Resd1./2020/SZ/925 dated 27/03/2020. The premises was re-inspected by the officer concerned of this department on 16/09/2023 in the presence of Sh. R.P. Singh, (GM-Engg.), NBCC and found that the said building block have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Group A (Residential)" with effect from 03/10 /2023 for a period of five years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 03/10 /2023 at New Delhi by

ire Service

Copy to: -

1. The Executive Engineer (Bldg.), New Delhi Municipal Council, Palika Kendra, New Delhi-110002

2. Sh. R. P. Singh, General Manager (Engg.), Ground Floor, Tower No. 4, Office Block, Along Ring Road, East Kidwai Nagar, New Delhi-110023

Conditions for the validity of Fire Safety Certificate

1. All the means of escape/entry/exit shall be kept free from any obstruction.

- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The basement shall be used strictly in accordance with Building Bye-Laws.
- 5. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

1	Name & Address of the Building	FION REPORT Residential Block	No. 9. Type_II Quart	ers.	
•		Residential Block No. 9, Type-II Quarters, Kidwai Nagar (East) for GPRA, New Delhi-23			
2	Type of Occupancy	Group-A "Residential"			
3	Building Comprised of	3 Tier Basement, Ground + 14 Upper Floors.			
5	Type of Case	Renewal	TO SECURE THE SEC.		
2	Details of Previous NOC		al/SZ/2018/2553 dated		
6	Fire Safety Directives Letter No	F.6/DFS/MS/Resdl./2020/SZ/925 dated 27/03/2020 F.6/DFS/MS/BP/2013/01 dated 02/01/2014			
7	Date of Inspection	16.09.2023	And the second	111-24-	
8	Name of the Inspecting Officers	ADO (SJ) Santosh Kumar			
9	Name & Designation of Officers from the building side	Sh. R. P. Singh (GM-Engg.)			
10	Year of construction	2019	and Arest		
11	Applicant letter No.	Outdoor Diary No. 4421 dated 02/08/2023			
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirement/ Provided at Remarks Existing Fire Site MR/NMR Protection System			
1	Access to Building.	was be a series of	WITH THE PERSON.	7 700	
- N.,	Road width	12m	12m	MR	
	Gate width	NA	NA	NA	
1	 Width of internal road 	6m (two side)	Provided	MR	
2	Number, width, type & arrangem	ent of exits.	Supplied to the supplied to	<u> </u>	
	a) Number of Staircase	1 - Valle College	Spin'ting at 10 1	1.0	
	> Upper floors.	2 Nos	Provided	MR	
	> Basement floor.	27 + 2 ramp	Provided	MR	
	b) Width of Staircase	125 +	1146	LVD	
	> Upper floors	1.35m*	1.46m to 1.45m	MR	
	➤ Basement floor	1.35m*	1.40m to 1.50m & ramp 4.5m each	MR	
	c) Protection of exits	WE SPAR	rump 4.5m cach		
	> Fire check door	Required	Provided	MR	
	> Pressurization	Required	Natural Ventilation	3760000000	
	d) No. of continuous staircase to terrac		Provided	MR	
		NA NA	NA	NA	
	e) Width of corridor	- Marcany	Tables years	-	
	f) Door size	1.0m	1.0m (final exit)	MR	
3	Compartmentation.	1 104	Estable per en a		
	Fire check door.	Required	Provided	MR	
	 Sealing of electrical shafts. 	Required	Provided	MR	
- 4	 Fire rating of shaft door. 	Required	Provided	MR	
	Water curtain	NA	NA I	NA	
	Fire dampers.	NA	NA	NA	
4	Smoke Management system.		1 89 4	1	
•		20 ACDU	MV Sustan	MR	
	Basement	30 ACPH	M.V. System		
	Upper floors	12 ACPH	Natural Ventilatio	n MR	
5	Fire Extinguishers.		The same of the	PULL	
	 Total numbers 	39 Nos	39 Nos.	MR	
	• Types	ABC/CO ₂ /WCO ₂	ABC & WCO ₂	MR	
	ISI Marking	ISI marked	Provided	MR	
6	First Aid Hose Reels.	42. 63.65	The state of the state of	1 20	
-33	Total numbers on each floor	r. One (each)	Provided	MR	
	• Length of hose-reel hose.	30m	30m	MR	

	Automatic fire detection & alarm Type of detectors	Required	Heat & Smoke	MR	
	Location of Main Panel	Required		MR	
	Location of Repeater Panel		The training of the total of th	NA	
	Alternate source of power	Required	7/27/7	MR	
	Hooter's location	Required		MR	
8	MOEFA	Required		MR	
9	Public Address System	Required		MR	
0	Automatic Sprinkler System	Required	Tiovided	IVIIC	
	Basement	Required	Provided	MR	
	Upper floors	NA		NA	
	 Sprinkler above false ceilir 	ng NA	NA	NA	
11	Internal Hydrants.	Tolk =	(Area (1979)	PERSONAL.	
	 Size of Riser/Down-comer 		100 mm	MR	
	Number of Hydrant per floor			MR	
12	Hose box.	Required	Provided	MR	
12	Yard Hydrants.		than 5-min		
	Total number of hydrants.			MR	
	Hose box.	Required	One	MR	
13	Pumping arrangements.	W College	VE REPORTE PROTECTION	2000	
	Ground Level Discharge of main pump.	Common Pump R Hyd. & Sprinkler	oom at B-2 level for typ	e-II & III	
	Discharge of main pump.	2850 LPM (each) Water Curtain (WC): 2 of 2280 LPM	2850 LPM (Each) Water Curtain (WC): 2 of 2280 LPM	MR	
	Head of main pump.	(H&S): 90m (each) (WC): 45m (each)	Provided	MR	
	Number of main pumps.Jockey Pump output.	4 Nos	Provided	MR	
	> Jockey Pump head.	2 of 280 LPM	2 of 450 LPM	MR	
	Standby Pump output.	90m & 60m 2850 LPM	Provided Provided	MR MR	
	 Standby Pump head. Auto Starting/Manual Stopp 	00	Provided	MR	
	> Pump house access.	Required	Provided	MR	
	Towns of I such	Provided	Provided	MR	
	 Terrace Level Discharge of pump. 	NA	NA	NA	
	> Head of pump.	NA	NA NA	NA	
	> Power supply.	NA	NA	NA	
	> Auto starting of pump.	\$100074500	NA	NA	
14	Captive water storage for fire fighting.				
14	Underground tank capaci		Provided	MR	
	Draw-off connection.		Provided	MR	
		- A Secretary Company of the Company	Provided	A DESCRIPTION	
		Required		MR	
	Access to tank.	Required	Provided	MR	
	Overhead tank capacity.	10,000 Ltrs	Provided	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.		pour de l'agre		
	Pressurization of lift shaft	1	Provided	MR	
	Pressurization of lift lobb		Natural ventilation	The second second	
	Communication in lift ca		Provided	MR	
	Fireman's switch.	Required	Provided	MR	
	Lift signage.	Required	Provided	MR	
17	Standby Power Supply	Required	Provided	MR	
01H-0	Programme and State of Court Indiana, and Court Ind	Required	Tiovided	IVIK	
18	Refuge Area		J.v.	154	
	Total area	NA	NA	NA	
	Location	NA	NA	NA	
_		1/4		4	

19	Fire Control Room.			LAD
	 Detector system panel. Flow switch panel. PA system panel. Battery backup. Building floor plan. 	Required	Provided	MR
		NA	NA	NA
		Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
100000		Aerosol suppression system provided		MR
20	Special Fire Protection System for the Protection of Special Risk, if any.	for HT/ LT Panel & Transformer		

Note: - As per order No. F.6/DFS/MS/2019/6020 dated 10/10/2019 issued by the worthy Director/DFS (copy enclosed), the requirement of width of staircase for the Residential Towers including basements stands modified and shall be taken as 1.35m as per the provision of prevailing UBBL-2016.

The Fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/Residential/SZ/2018/2553 dated 26/11/2018 and F.6/DFS/MS/Resdl./2020/SZ/925 dated 27/03/2020, renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)

MIR MIR 28 Tail 2022 Director MI 21/9/27

sir, frugger is prohipfor your singulature Pl

Director / 19/m