

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



No F 6 / DFS / MS / 2023 /School/WZ/ 697

FIRE SAFETY CERTIFICATE

Certified that the Sarvodaya Kanya Vidyalaya (ID No. 1411034) located at J.J. Colony, Wazirpur, Delhi-110052 comprised of Ground and Three upper floors owned/occupied by Sarvodaya Kanya Vidyalaya was issued FSC by this department vide letter No F-6/DFS/MS/School/WZ/2020/332 dated 01.09.2020. The building was inspected by the officer concerned of this department on 20.09.2023 in the presence of Smt. Kalpana Basumatatari (HOS), and observed that all the fire prevention and fire safety arrangements as provided in the building found in good working condition. The premises have deemed complied with the requirements in accordance with DOE Circular No. 3298-3398 dated 01/03/2011 and that the building/ premise is fit for occupancy Group B Educational with effect from .29.09 20.2.3 for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on .. 29. 09. 2023. at New Delhi, by

Delhi Fire Service

Copy to : -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat ,Delhi-54.

2. The Principal, Sarvodaya Kanya Vidyalaya, J.J. Colony, Wazirpur, Delhi-52.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned

5. This certificate cannot be treated in any case for regularizations of unauthorized

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: Sarvodaya Kanya Vidyalaya, New Block (School ID- 1411034)

located at J.J.Colony, Wazirpur, Delhi-110052

2. Type of Occupancy : Educational

3. Building Comprised : Ground + Three Upper Floors

4. Type of Case : Renewal

Details of Previous NOC : F6/DFS/MS/School/WZ/2020/332 Dated- 09/09/2020
 Fire Safety directives letter No : DOE Circular No. 3298-3398 Dated 01/03/2011

Date of inspection
 20 /09/2023
 Name of inspecting Officer
 ADO, R.K.Sinha

9. Name and designation of officers

From the building side : Smt. Kalpana Basumatari (H.O.S)

10. Year of Construction : 2017

11. Applicant's letter No. : Form 'J' via outdoor diary no. 5882, Dated-11/09/2023

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR			
1.	Access to building	1 (0	6.0 m	MR			
	Road width	6.0 m		MR			
	Gate width	4.5 m	Provided	NA NA			
	Width of internal road	NA	NA	INA			
2.	Number, Width, Type & Arrangement of Exits			7			
	a. Number of staircases) AM			
	Upper Floors	03	Provided	MR			
	Basements	NA	NA	NA			
	b. Width of staircases	1.5 m in each	Provided	MR			
	Upper Floor	NA	NA	NA			
	Basements	14					
	c. Protection of exits	NA	NA	NA			
	• Fire check door	NA NA	NA	NA			
	Pressurization	INA	IIA				
	d. No. of continuous staircases to		D 1 1 1	MR			
	terrace	Required	Provided	MIK			
	e. Width of Corridor	1.50 m	Provided	MR			
	NEX 11 CTOT CHARLESTEE .			200,000,000			
	f. Door Size	1 m	Provided	MR			
				141 0			
3.	Compartmentation			4.8			
	Fire check door	NA	NA	NA			
	Sealing of electrical shafts	NA	NA	NA			
	Fire Rating of shaft door	NA	NA	NA			
	Water Curtain						
		NA	NA	NA			
	Fire Dampers	NA	NA	NA			
4.	Smoke Management System						
32-20.	Basements	NA	NA	NA			
	Upper floors	Required	Natural	MR			
	• Opper moors	- Acquired	Ventilated	11074			
5.	Fire Extinguishers						
٥.	Total numbers	01@300 SQM	Provided	MR			
	Types	ABC/CO2	ABC/Co2	MR			
	IS marking	Yes	Yes				
		ies	ies	MR			
6.	Total numbers on each floor	03	Provided	MD			
			Provided	MR			
	Length of hose reel hose	30 m		MR			
	Nøzzle diameter	5 mm	Provided	MR			
7.	Automatic fire detection and alarming system	T					
	Type of detectors	NA	NA	NA			
10	Location of Main Panel	NA	NA	NA			
	 Location of Repeater Panel 	NA	NA	NA			

=

10-32

	• Alternation	32			
	Alternate source of power	NA	NA NA	NA NA	
	Hooters' Location		NA	NA	
M	OEFA	NA	I INA	147	
Pu	Iblic Address System	NA	NA	NA	
· Ai	utomatic Sprinkler System	NA	NA	NA NA	
		10	IVA	I NA	
1	Basement				
	Ground Floor	NA	NA	NA	
	Sprinkler above false ceiling	NA	NA	NA	
. In	iternal Hydrants	NA	NA	NA	
	Size of riser/down-comer	NA			
	Number of hydrants per floor Hose Box	NA NA	NA	NA	
2. V	ard Hydrants	NA NA	NA	NA	
•	ard Hydrants	NA	NA	NA	
	Total number of				
	 Total number of hydrants Hose Box 	NIA		5.00	
3. P	umping Arrangements	NA NA	NA	NA	
	Arrangements	NA	NA	NA	
	Ground Level		7.61		
	Discharge of	_			
	> Head of Main Pump	NA			
	Number of me!	NA	NA	NA	
		NA	NA		
	Jockey Dillimn head	NA	NA	NA	
	Standov Pump out	NA	NA	· NA	
	Standby Pump Head	NA		NA	
		NA	NA	NA	
	Auto Starting/Manual Stopping	NA	NA	NA	
	> Pump House Access	NA	NA	NA	
	Trouse Access	NA NA	NA	NA	
	Terrace level	INA	NA	NA	
	• Discharge of pump	- 1		IVA	
	• Head of the pump	450 lpm			
	Power Supply	40 m	Provided	MR	
		Required	40 m	MR	
	 Auto Starting of pump 	-	Provided	MR	
		Required	Drow! 1	-	
14.	Cantive West Co.		Provided	MR	
	Captive Water Storage for fire fighting • Underground tank				
	> Draw-off capacity	N:		- 1	
	Fire service int	NA NA	NA		
	> Access to tank	NA	NA	NA	
		NA	NA	NA	
15.	Overhead Tank capacity Exit Signage.	NA	NA	NA	
	Bunge,	10,000 ltrs	Provided	NA	
		Required	Provided	MR	
16.	D		Daniver	MR	
- 0.	Provision of Lifts.				
	• Pressurization of the	×10			
		NA	111		
	Communication In lift Car	NA	NA	NA	
	Somman's Grounding Switch	NA	NA	NA	
	 Lift Signage 	NA	NA	NA	
	- 0-	NA	NA	NA	
17.	Standby	MA	NA		
	Standby power supply	NA	77.1	NA	
18.			NA		

			N- 33			
1	\ \ \ \ \ \	Total Area				
6	>	Location	NA	NA	NA	
-			NΛ	NA	NA	
19.	Fire Control Room					
	•	Detector System Panel				
	•	flow Switch Panel	NA	NΛ	NA	
	•	PA System Panel	NA	NA	NA	
	Battery backup	NA	NA	NA		
		исту васкир	NA	NA	NA	
	•	Building Floor Plans	NA	NA	NA	
20.	Special special	Fire Protection System for Protection of Risks, if any:	NA	NA	NA	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures required under DOE Circular No. 3298-3398 dated 01/03/2011. It is recommended to renew the Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/WZ/2020/332 dated 09/09/2020, under rule 35 of the Delhi Fire Service Rules 2010.

ADOUR 19/2

Signature of Inspecting Officer

Name: Rajeev Kumar Sinha

Designation: ADO/B.W.

DOFOH LOS PLANS

Jan 1

21 9/ 2022 Dineta / 19/2

HAN AN

f T letter proto from a

A308W 15/9/27

treator (PT) // 19/2