

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/2023/EH/300

Dated 04/10/2023

## **FIRE SAFETY CERTIFICATE**

Certified that the M/s Barbeque Nation (A Unit of Ms Barbeque Nation Hospitality Ltd.) located at Third Floor, Property No-B2, Gujrawala Town Part-I, Delhi-110009 in a building comprised of basement, ground and 03 upper floors owned/occupied by M/s Barbeque Nation (A Unit of Ms Barbeque Nation Hospitality Ltd.) have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 23.09.2023 in the presence of Sh. Bijender (Manager) and that the building/ premise is fit for occupancy Class Assembly (Restaurant) at third floor only with effect from (Manager) and that the building/ premise is fit for occupancy Class Assembly (Restaurant) at third floor only with effect from (Manager) and that the building/ premise is fit for occupancy Class Assembly (Restaurant) at third floor only with effect from (Manager) and that the building/ premise is fit for occupancy Class Assembly (Restaurant) at third floor only with effect from (Manager) and that the building/ premise is fit for occupancy Class Assembly (Restaurant) at third floor only with effect from (Manager) and that the building/ premise is fit for occupancy Class Assembly (Restaurant) at third floor only with effect from (Manager) and that the building/ premise is fit for occupancy Class Assembly (Restaurant) at third floor only with effect from (Manager) and that the building/ premise is fit for occupancy Class Assembly (Restaurant) at third floor only with effect from (Manager) and that the building/ premise is fit for occupancy Class Assembly (Restaurant) at third floor only with effect from (Manager) and that the building/ premise is fit for occupancy Class Assembly (Restaurant) at third floor only with effect from (Manager) and that the building/ premise is fit for occupancy Class Assembly (Restaurant) at third floor only with effect from (Manager) and the floor only with effect from (Manager) and the floor only with effect from (Manager) a

Director Ph/011-23414000

Copy to:-

 M/s Barbeque Nation (A Unit of Ms Barbeque Nation Hospitality Ltd.) located at Third Floor, Property No-B2, Gujrawala Town Part-I, Delhi-110009.

## Conditions for the validity of Fire Safety Certificate:

- 1. This Fire Safety Certificate is valid only for restaurant at third floor for assembly occupancy only. In case of any violation, this FSC will be treated as null & void.
- 2. All the means of escape/entry/exit shall be kept free from any obstruction.
- 3. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 4. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 5. All the staff members must know the correct method of operation of firefighting system.
- The owner / occupier shall submit a declaration every year in Form "K" provided in the
  first schedule of Delhi Fire Service Rules 2010. The form is available on
  <a href="http://delhi.gov.in./wps/wcm/connect/doit">http://delhi.gov.in./wps/wcm/connect/doit</a> fire/FIRE/Home/Forms.
- 7. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 8. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

## INSPECTION REPORT

1. Name& address of the building : M/s Barbeque Nation (A Unit of Ms Barbeque Nation Hospitality Ltd.), at

3<sup>rd</sup> Floor, B-2, Gujrawala Town, Part-1, Delhi-110009.

2. Type of Occupancy : Assembly (Restaurant)

3. Composition of building : Basement, Ground & 03 Upper Floors, basement-vacant, ground & first floor

4. Haldiram restaurant, second floor-vacant but Restaurant is purposed at 3<sup>rd</sup>

Floor only

5. Type of Case : New Case

6. Details of previous NOC : Nil7. Fire Safety directives letter No : Nil

8. Date of inspection : 23.09.2023

9. Name of the Inspecting Officers : ADO/RN, Chutanla Meena

10. Name and designation of officers

from the building side : Mr. Bijender (Manager)

11. Year of Construction : 2018

12. Applicant's letter No. : Online MHA Portal I. D. No- 2023091415928 dated 18.09.2023

	Minimum Standards on fire prevention and fire safety U/R 33	UBBL/NBC requirement	Provided at site	Remarks MR/NMR		
1	Access to building					
	Road width	09m	12m approx	MR		
	Gate width	NA	NA	NA		
	Width of internal road	NA	NA	NA		
!	Number, Width, Type & Arrangement of Exits	Restaurant third f	loor only			
	a. Number of staircases		95	140		
	Upper Floors	02	02	MR		
	Basements	02	02	MR		
	b. Width of staircases					
	Upper Floors	02m &1.5m	02m each	MR		
3	Basements	02m &1.5m	02m each	MR		
	c. Protection of exits		Q1 - 4m )	Pari ve		
	Fire check door	Required	Provided	MR		
	Pressurization	NA	NA	NA		
	d. No. of continuous staircases to terrace		918	NA NA		
	e. Width of Corridor	NA NA	lm NA	NA NA		
	The state of the s			3774315-0		
	f. Door Size	2m & 1.50m	Provided	MR		
	Compartmentation.	Alexander Control				
	Fire check door	NA	NA	NA		
	<ul> <li>Sealing of electrical shafts</li> </ul>	NA	NA	NA		
	Fire Rating of shaft door	NA	NA	NA		
	Water Curtain	NA	NA	NA		
	Fire Dampers	NA	NA	NA		
	Smoke Management System.					
	Basements	NA	NA	NA		
	Upper floors	Required	Provided	MR		
i -	Fire Extinguishers					
	Total numbers	06nos	08nos	MR		

	• Types	ABC/Co2	ABC-5 Co2-3	MR	
	ISI marking	Yes	Yes	MR	
	First-Aid Hose Reels.	returned by			
ı	Total numbers on each floor	01	01	MR	
	Length of hose reel hose	30m	30m	MR	
	Nozzle diameter	5mm	5mm	MR	
	Automatic fire detection and alarming system.		J	I WIK	
	Type of detectors	Smoke/Heat	Provided	MR	
	Location of Main Panel	Third floor	Provided	MR	
	Location of Repeater Panel	NA	NA	NA	
		Required	Provided	MR	
		Third floor	Provided	MR	
	Hooters' Location			200000	
8	MOEFA	Required	Provided	MR	
9	Public Address System.	Required	Provided	MR	
10	Automatic Sprinkler System.		7 0 0	-	
	Basement	Required	Provided	MR	
	Upper Floor	Required	Provided	MR	
	Sprinkler above false ceiling	NA NA	NA	NA	
		10.7	- 31		
11	Internal Hydrants		w		
	Size of riser/down-comer	100mm 01	Provided Provided	MR MR	
	Number of hydrants per floor     Uses Box	01	Provided	MR	
	• Hose Box				
12	Yard Hydrants.	NA	NA	NA	
	Total number of hydrants	NA	5000 5 2550	NA NA	
	Hose Box	NA	NA	NA	
13	Pumping Arrangements.				
	Ground Level	had a	n	MR	
	<ul> <li>Discharge of main Pump</li> </ul>	2280 LPM	Provided	433,50	
	> Head of Main pump	50m	50m	MR MR	
	> Number of main pumps	02	02	MR	
	> Jockey Pump out put	180 LPM	Provided	Attende	
	> Jockey pump head	50m 2280lpm	Provided Provided	MR MR	
	> Standby Pump out put	(Diesel operative)	Fr		
	> Standby Pump Head	50m	Provided	MR	
	> Auto Starting/ Manual stopping	Required	Provided	MR	
	> Pump House Access	Required	Provided	MR	
	Terrace level		and ask and a		
	> Discharge of pump	450lpm	Provided	MR	
	> Head of the pump	40m	Provided	MR	
		Required	Provided	MR	
	> Power Supply	Required	Provided	MR	
	> Auto Starting of pump	Required	11011000	2,000	
14	Captive Water Storage for fire fighting.				
4-7	Underground tank capacity (Overhead)	100,000 LTR	Provided at terrace	If agreed MR	
			level		

1	18
---	----

	> Fire service inlet > Access to tank	NA NA	NA L	NA	
		NA	NA	NA	
	Overhead Tank capacity	10,000 LTR	Provided	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.				
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication In lift Car	Required	Provided	MR	
	Freman's Grounding Switch	Required	Provided	MR	
	Lift Signage	Required	Provided	MR	
17	Standby power supply	Required	Not Provided	NMR	
18	Refuge Area.				
	> Total Area	N/A	N/A	N/A	
	➤ Location	N/A	N/A	N/A	
19	Fire Control Room				
	Detector System Panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel	N/A	N/A	N/A	
	Batter backup	N/A	N/A	N/A	
	Building Floor Plans	N/A	N/A	N/A	
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA	

Note:-

It was observed that there is no space to construct underground tank at ground level. Therefore applicant has provided 1 lakh liters water tank for firefighting at terrace level. If agreed than point no.14 may be taken as meeting requirement.

- The total covered area of the third floor Restaurant is 327.76sqm (Approx) including kitchen area seating area, counter area, & store area.
- As per the NBC Part IV, the number of occupants comes out to be approx 182 person's (b) i.e. (327.76/1.8=182)

The fire protection systems provided in the building were tested/ checked and found in working order at the time of inspection. The observations/ shortcomings issued and communicated vide this department letter of even no. F6/DFS/MS/2023/EH/328 dated: 23.06.2023 have been compiled by the management.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

M.K. Chattopadhyay

Signature of the Inspecting Officer

Name :- C.L. Meena

Designation:- Asst. Div. Officer (RN)

Dy. Chief Fire Officer (NV)