

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE

No.F.6/DFS/MS/School/2023/SZ | NEW DELHI-110 001.

Dated: 04/10/2023

FIRE SAFETY CERTIFICATE

Certified that the Hari Krishna Public School, A-114-118, Mansa Ram Park, Uttam Nagar, New Delhi-110059, comprised of ground plus three upper floors, owned/occupied by Hari Krishna Public School was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/2018/SZ/250 dated 15/02/2018 (For GF & FF Only). The building was re-inspected by the officer concerned of this department on 21/09/2023 in the presence of Sh. Ashok Sharma (Manager) and found that the School building have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on...... at New Delhi.

Copy to:-

1. The Manager, Hari Krishna Public School, A-114-118, Mansa Ram Park, Uttam Nagar, New Delhi-110059.

2. Director of Education. Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building: Hari Krishna Public School, A-114-118, Mansa Ram Park, Uttam Nagar,

New Delhi-110059.

2. Building comprised of G+3 upper floors Type of Occupancy Educational Type of Case Addition/New

Details of Previous NOC F.6/DFS/MS/2018/SZ/250 dated 15/02/2018 (For GF & FF Only)

Fire Safety directives letter No N/A Date of inspection 21/09/2023 8. Name of Inspecting Officer A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side Sh. Ashok Sharma (Manager)

10. Year of Construction Before 2006 (GF & FF) & 2016 (SF & TF)

11. Applicant's letter No. H/K/P/S dated 15/09/2023

S. No.		num Standards on fire prevention and fety U/R 33	Requirements	Provided at site	Remarks MR/NMR
1.		s to building			
		Road width Gate width Width of internal road	Accessible 06 mtrs 4.5 mtrs N/A	'06 mtrs Directly accessible from road N/A	M/R M/R N/A
2.	Numb	er, Width, Type & Arrangement of Exits	•		
-	a. Nun	nber of staircases			
	•	Upper Floors .	02 No.'s	02 No.'s	· M/R
	•	Basements	N/A	N/A	. N/A
			1 8		
	b. Wid	th of staircases	1.5 m each	1.5 m each	MR
	1/25	Upper Floor Basements	N/A	N/A	N/A
	1.5				
	D.	ation of ovita	N/A	N/A	N/A
	c. Prote	ection of exits Fire check door	N/A	N/A	N/A
		Pressurization		5.00.0	1.33.F(3)
		1 ressurzation	N/A	N/A	N/A
	d. No.	of continuous staircases to	1.5 M	1.65 M	M/R
	terra			(4.5.4.5)	
		th of Corridor	- 1.0 M	.98 M (double door)	M/R, being old case
1.0	5 C.	r Size			•
	Compar	tmentation			
-	•	Fire check door	N/A	. N/A	· , N/A
		Sealing of electrical shafts	N/A	N/A	· N/A
* 1	• 1	ire Rating of shaft door	N/A	N/A	N/A
		Vater Curtain	N/A	.N/A	N/A
	• F	ire Dampers	N/A	N/A	N/A
	Smalra N	Janagement System	IVA .		ž.
- 4			N/A .	N/A	N/A
	• B	asements	IN/A		XXXXXXXX
	• U	Ipper floors	Required	Natural ventilation provided	M/R
F	ire Exti	nguishers			. 7
		otal numbers	06 no's	Provided	M/R
		ypes ·	ABC/CO ₂ type	Provided	M/R
	• 18	marking	ISI marked	Provided '	, M/R
F	irst-Aid	Hose Reels			10 mag 1
	• T	otal numbers on each floor	l No.	· Provided	· · M/R
	• L	ength of hose reel hose	30 m	Provided	· M/R
		ozzle diameter	5 mm	Provided	M/R
	- 1	c fire detection and alarming system	200000000000000000000000000000000000000	The supplied of the supplied o	

Krishna Public School, A-114-118, Mansa Ram Park, Uttam Nagar, New Delhi-110059)

01/12

Location of Main Panel N/A N/A		75.4				
Location of Repeater Panel N/A		Type of detectors Location of Main Panel	N/A .	N/A		N/A
Alternate source of power N/A			53.535.54			
Hooters' Location				1,000,000		
8. MOEFA						
9. Public Address System	0		H1 100 100 100 100 100 100 100 100 100 1			
10. Automatic Sprinkler System						
Basement N/A N/A N/A N/A Ground Floor N/A N/A N/A Stree of riser/down-comer N/A N/A N/A N/A N/A N/A N/A N/A			N/A	. N/A		N/A
• Ground Floor N/A	10.		N/A	N/A		NI/A
Sprinkler above false ceiling					-	
11. Internal Hydrants		1930 MACABARAN SANDAN (1930 MACABARAN 1930 MACABARA	1.00000000	9000097007		
Size of riser/down-comer N/A N	11.		IV/A	IN/A		IN/A
Number of hydrants per floor N/A N/A			N/A	N/A		N/A
Hose Box		그리아 하나 있는 맛들이 보는 맛이 되었다면 없는 것이 없어				
12. Yard Hydrants			74 CO. Co. Co.	-		1700000000
Total number of hydrants	12.	Yard Hydrants				
Hose Box			N/A	. N/A		N/A
Pumping Arrangements Pumping Arrangements		Hose Box				
Discharge of main Pump	13.	Pumping Arrangements				1
Head of Main pump		Ground Level				
Head of Main pump		Discharge of main Pump	N/A	N/A	-	N/A
Number of main pumps		➤ Head of Main pump			-	
Sockey pump head N/A N/A		Number of main pumps				
Standby Pump Out put Standby Pump Head Standby Pump Head N/A	96		The second secon		-	
Standby Pump Head Auto Starting/Manual Stopping N/A Pump House Access Terrace level Discharge of pump Head of the pump Head of the pump Head of the pump Auto Starting of pump Underground tank capacity Draw-off connection Fire service inlet Access to tank Overhead Tank capacity Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift Signage N/A Standby power supply N/A N/A N/A N/A N/A N/A N/A N/			42 OF SEC.			
Auto Starting/Manual Stopping N/A N/A N/A N/A N/A N/A N/A N/A N/A N/			N/A	N/A		N/A
N/A N/A N/A N/A		Standby Fump Head	N/A	N/A	4.1	N/A
N/A N/A N/A N/A		Auto Starting/Manual Stopping	N/A	.N/A		N/A
Pump House Access Terrace level Discharge of pump Head of the pump Auto Starting of pump Underground tank capacity Fire service inlet Access to tank Overhead Tank capacity Exit Signage: Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift Shaft Pressurization of Lift Shaft Fireman's Grounding Switch Lift Signage N/A N/A N/A N/A N/A N/A N/A N/A N/A N/		7 Time Starting Mandan Stopping	N/A ·	N/A		N/A
> Discharge of pump > Head of the pump > Head of the pump > Power Supply Auto Starting of pump ■ Underground tank capacity > Draw-off connection > Fire service inlet > Access to tank ■ Overhead Tank capacity ■ Provided ■ N/A ■	-5-1		N/A		103	
> Head of the pump > Power Supply > Auto Starting of pump • Underground tank capacity > Fire service inlet > Access to tank • Overhead Tank capacity • Provision of Lifts. • Pressurization of Lift Shaft • Pressurization of Lift Shaft • Pressurization of Lift Shaft • Fireman's Grounding Switch • Lift Signage Refuge Area. > Total Area > Total Area > Location				1500-150	17.7	
Power Supply Required Provided M/R						
Auto Starting of pump Required Required Provided M/R Captive Water Storage for fire fighting Underground tank capacity Draw-off connection Fire service inlet Access to tank Overhead Tank capacity Exit Signage: Provision of Lifts. Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Required Provided M/R N/A N/A N/A N/A N/A N/A N/A N/A N/A N/						
I. Captive Water Storage for fire fighting • Underground tank capacity > Draw-off connection > Fire service inlet > Access to tank • Overhead Tank capacity I. Exit Signage. Exit Signage. Provision of Lifts. • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car • Fireman's Grounding Switch • Lift Signage Standby power supply Refuge Arca. > Total Area > Location	1 100 1					
Underground tank capacity Draw-off connection Fire service inlet Access to tank Overhead Tank capacity Exit Signage. Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Required N/A N/A N/A N/A N/A N/A N/A N/		Auto Starting of pump	Required	Provided		M/R
Draw-off connection Fire service inlet Access to tank Overhead Tank capacity Exit Signage. Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Refuge Area. Polymer Survive inlet N/A	١.	Captive Water Storage for fire fighting				
Draw-off connection Fire service inlet Access to tank Overhead Tank capacity Exit Signage. Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Refuge Area. Possion of Lift Area Location N/A N/A N/A N/A N/A N/A N/A N/A N/A N/		Underground tank capacity	N/A	N/A		N/A
Fire service inlet Access to tank Overhead Tank capacity N/A N/A N/A N/A N/A N/A N/A N/A N/A N/			I SPERIOR VICE			
Overhead Tank capacity N/A N/A N/A N/A N/A N/A N/A N/				The state of the s	,	
Discrete and Tank capacity 10,000 ltrs Provided M/R	1 .			312,033,147		PERSONAL PROPERTY.
Required Provided M/R		Overhead Tank capacity				2500855
Provision of Lifts. No Lift • Pressurization of Lift Shaft N/A N/A N/A • Pressurization of Lift lobby N/A N/A N/A • Communication In lift Car N/A N/A N/A • Fireman's Grounding Switch N/A N/A N/A • Lift Signage N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A Refuge Area. N/A N/A N/A ➤ Total Area N/A N/A N/A ➤ Location N/A N/A N/A		Evit Cianaga				
• Pressurization of Lift Shaft N/A N/A N/A • Pressurization of Lift lobby N/A N/A N/A • Communication In lift Car N/A N/A N/A • Fireman's Grounding Switch N/A N/A N/A • Lift Signage N/A N/A N/A N/A N/A N/A N/A		Exit Signage.	Required .	Provided	1	M/R
• Pressurization of Lift lobby N/A N/A N/A • Communication In lift Car N/A N/A N/A • Fireman's Grounding Switch N/A N/A N/A • Lift Signage N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A			1		ift	ustron's
• Communication In lift Car N/A N/A N/A • Fireman's Grounding Switch N/A N/A N/A • Lift Signage N/A N/A N/A N/A N/A N/A N/A		The state of the s	N/A	. N/A		N/A
• Communication In lift Car N/A N/A N/A • Fireman's Grounding Switch N/A N/A N/A • Lift Signage N/A N/A N/A N/A N/A N/A N/A			N/A	N/A		N/A
• Lift Signage			N/A			
N/A N/A N/A N/A			N/A	N/A		N/A
Standby power supply N/A N/A N/A N/A Refuge Area. > Total Area > Location N/A N/A N/A N/A		- Litt Signage	480 (480)	1 2 2		
Refuge Area. N/A N		Standby power supply	200110.7476			
Refuge Area. ✓ ➤ Total Area N/A N/A ➤ Location N/A N/A	XX		2.864.86	. INIA		IV/A
> Total Area > Location N/A N/A N/A		Refuge Area.	*			
		> Total Area	N/A	N/A		N/A
		Location	N/A	N/A		N/A

(Hari Krishna Public School, A-114-118, Mansa Ram Park, Uttam Nagar, New Delhi-110059)

0. Spe	cial Fire Protection System for Protection of cial Risks, if any:	N/A	N/A	N/A
	Building 1 test 1 time	N/A	N/A	N/A
	Battery backup Building Floor Plans	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
1	Flow Switch Panel	N/A	N/A	N/A
	Detector System Panel	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at issued letter The shortcoming inspection. time of

F6/DFS/MS/School/2022/SZ/161 dated 07/04/2023 has been complied.

Keeping in view of the compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/2018/SZ/250 dated 15/02/2018 (For GF & FF Only) renewal under the Rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

(South West) Divisional Office 26/9/2 Holley is put up for sign