

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2023/SZ/ 7/7

Dated: 09 10 2023

FIRE SAFETY CERTIFICATE

Certified that the Parkash Model School Located at Mahavir Enclave Part-III, C-Block, New Delhi, comprised of Ground plus one upper floor owned/occupied by Parkash Model School was issued Fire Safety Certificate by this department vide letter No F.6/DFS/Ms/School/2019/SZ/1013 Dated 14/05/2019. The school building was re-inspected by the officer concerned of this department on 03/10/2023 in the presence of Sh. Bhoop Singh (Manager) and found that the School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. 262 to 362 dated 17/01/2005 issued by the Director of Education and that the building/ premises is fit for occupancy class 'Educational' w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on 09 10 223 at New Delhi.

DIRECTOR DELIM FIRE SERVICE

Copy to:-

1. The Manager, Parkash Model School, Mahavir Enclave Part-III, New Delhi.

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-54.

Following fire safety directives must be adhered to:-

 All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.

 Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

 The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

 The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry. 1. Name & address of the building

: Parkash Model School Located at Mahavir Enclave Part-

III, C-Block, New Delhi.

2. Building is comprised of

: Ground plus one upper floor.

3. Type of Occupancy

: Educational

4. Type of Case

: Renewal

5. Details of Previous FSC letter

: F.6/DFS/MS/School/2019/SZ/1013 Dated 14/05/2019

6. Fire Safety direction letter No

: Circular No. 262-362 dated 17/01/2005

7. Date of Inspection

: 03/10/2023

8. Name of the Inspecting officers

: ADO R.K. Yadav

9. Name and designation of Officer:

From the building side

: Sh. Bhoop Singh (Manager)

10. Year of Construction

: 2008

11. Applicant's letter No

: Form 'J'Dated- 14/09/2023

S. N	Minimum Standards on fire prevention and fire safety U/R33	Requirement	Provided at Site	Remarks MR/NMR				
1	Access to building							
	Road width	06 m.	Provided	MR				
	Gate width Width of internal road	4.5 m	Directly accessible from road	MR				
		N/A	N/A	N/A				
2	Number, Width, Type and Arrangement of Exits							
	a. Number of Staircases							
	Upper Floor Basements	02 Nos.	2 Nos.	MR				
		N/A	N/A	N/A				
	B. Width of Staircases							
	Upper Floor	1.25 & 1.0 m	Provided	MR				
	Basements	N/A	N/A	N/A				
	c. Protection of exits							
	Fire check door	N/A	N/A	N/A				
	Pressurization	N/A	N/A	N/A				
	d. No. of continuous staircases	N/A	N/A	N/A				
	to terrace	N/A	Provided	N/A				
	e. Width of Corridor f. Door Size	1.0 m	Old case	MR, being old case				
3	Compartmentation.			•				
_	Fire check door	N/A	N/A	N/A				
	Sealing of electrical shafts	N/A	N/A	N/A				
	Fire rating of shaft door	N/A	N/A	N/A				
	Water curtain	N/A	N/A	N/A				
	1 ASSA 1	N/A	N/A	N/A				
_	• Fire Dampers N/A N/A Smoke Management System.							
4		N/A	N/A	N/A				
	Basement	N/A	N/A	N/A				
	Upper floor							
5.	Fire Extinguishers	04 nos.	Provided	MR				
	Total numbers	ABC /CO ₂	ABC /CO ₂	MR				
	Types	IS I marked	ISI marked	MR				
	IS marking	15 I marked	131 markeu	1,,,,				

k

h

6	First-aid-Hose Reels.					
	Total numbers of each floor	01 No	Provided	MR		
	Length of hose reel hose	30 m	Provided	MR		
	Nozzle diameter	05 mm	Provided	MR		
,	Automatic fire detection and alarming system.					
	Type of detectors	N/A	N/A	N/A		
	 Location of main panel 	N/A	N/A	N/A		
	 Location of repeater panel 	N/A	N/A	N/A		
	 Alternate source of power 	N/A	N/A	N/A		
	 Hooter's location 	N/A	N/A	N/A		
3	MOEFA	N/A	N/A	N/A		
)	Public Address System.	Required	Provided	MR		
0	Automatic Sprinkler System.					
	Basement	N/A	N/A	N/A		
	upper floor	N/A	N/A	N/A		
	sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants					
-	size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
_						
2	Yard Hydrants.	N/A	N/A	N/A		
_	Total number of hydrants	N/A	N/A	N/A		
_	Hose Box					
3	Pumping Arrangements.					
	Ground Level	NI/A	N/A	N/A		
	 Discharge of main Pump 	N/A				
_	> Head of Main Pump	N/A	N/A	N/A		
	> Number of main pumps	N/A	N/A	N/A		
	> Jockey pump out put	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A		
_	> Standby pump out put	N/A	N/A	N/A		
	> Standby pump Head	N/A	N/A	N/A		
	Auto Starting /Manual stopping	N/A	N/A	N/A		
	> Pump House Access	N/A	N/A	N/A		
	Terrace Level					
	> Discharge of pump	220 LPM	Provided	MR		
_	> Head of the Pump	40 M	Provided	MR		
	> Power supply	Required	Provided	MR		
14	> Auto Starting of pump	N/A	N/A	N/A		
		IN/A	18/73	INIA		
14	Captive Water Storage for Fire Fighting.			V		
	Underground tank capacity	N/A	N/A	N/A		
	Draw-off connection	N/A	N/A	N/A		
	> Fire service inlet	N/A	N/A	N/A		
	> Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	2500 ltrs	Provided	MR		





16	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication in lift car	N/A	N/A	N/A		
	Firemen's grounding switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
17	Standby power supply	N/A	N/A	N/A		
18	Refuge Area. Not Required					
	Total area	N/A	N/A	N/A		
	Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector system panel	N/A	N/A	N/A		
	 Flow switch panel 	N/A	N/A	N/A		
	PA system panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2019/SZ/1013 Dated 14/05/2019 renewal in accordance with the Circular No. 262 to 362 dated 17/01/2005 issued by the Director of Education is recommended.

Signature of the Inspecting Officer

Name- R.K. Yadav

Designation- A.D.O (JKP)

DO (South West)

6/10/23

The state of the s

M