





## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F.6/DFS/MS/Petrol/SZ/2023/ 489

Dated: /3 //0 /2023

## FIRE SAFETY CERTIFICATE

Certified that the M/s Engineers Service Station, Retail Outlet (Petrol, Diesel Pump & Service Station), Dealers for Indian Oil Corporation Ltd., Sri Aurobindo Marg, Opposite Jorbagh, New Delhi-110003, comprised of Ground Floor only, owned / occupied by M/s Engineers Service Station, was issued Fire Safety Certificate vide letter No. F.6/DFS/MS/Petrol/202/SZ/449 dated 03/11/2020. The premises was re-inspected by the officer concerned of Fire Service on 18.09.2023 in the presence of Sh. Rajender Singh (Manager) of the said filling station and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that said premises is fit for occupancy class "Group-J Hazardous Building as above with effect from 12/10/202 for a period of 3 (three) years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 13/10/2023 at New Delhi by

DIRECTOR DELHI FIRE SERVICE

Copy to: -

- 1. Addl. Commissioner of Police (Lic.), 1st Floor, PS Defence Colony, New Delhi-110049
- Manager, M/s Engineers Service Station, Retail Outlet (Petrol, Diesel Pump & Service Station), Sri Aurobindo Marg, Opposite Jorbagh, New Delhi-110003

## Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- Any deviation with regard to construction ventilation occupancy, electric installation etc. may be got verified from the concerned authorities
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".
- The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on www.dfs.delhigovt.nic.in

## **INSPECTION REPORT**

1. Name & address of the building: M/s Engineers Service Station, Retail Outlet (Petrol, Diesel Pump & Service Station), Dealers for Indian Oil Corporation Ltd., Sri Aurobindo Marg, Opposite Jorbagh, New Delhi-110013.

: Hazardous Building (Group -J) 2. Type of Occupancy

: Ground floor only. 3. Building Comprised of

: Renewal 4. Type of Case

: F6/DFS/MS/Petrol/2020/SZ/449 dated 03/11/2020 5. Details of previous NOC

6. Fire Safety directives Letter No.: NIL

: 18/09/2023 7. Date of inspection

8. Name of the Inspecting Officer: Santosh Kumar A.D.O. (S.J.)

9. Name and designation of Officer

: Sh. Rajendar Singh (Manager) From the building side

: Running since 1970 10. Year of construction

S. No	pplicant's letter revived through Minimum standards on fire prevention and fire safety U/R 33	Old NOC Requirements	11011400	Remarks MR/NMR
1.	Access of building		1.4	MR
	Road width    Gate width	Accessible	18m	III III III III III III III III III II
		NA	NA	NA
	Width of internal road	NA	NA	NA
2.	Number, width, Type & Arran	gements of exi	ts	
2.	a. Number of staircases	200	-	114
	> Upper floors > Basements	NA	NA	NA
		NA	NA	NA
	b. Width of staircases		1	NA
	> Upper floors	NA	NA	NA
	Basements	NA	NA	IVA
	c. Protection of exits	NA	INA	NA
	> Fire check door	NA	NA NA	NA NA
	> Pressurization	NA	NA NA	NA NA
	d. No of continuous	NA	ant ut   Image codes	147.
	staircase to terrace	NA	NA	NA
	e. Width Of Corridor	1m	Provided	MR
	f. Door Size	Att		
3.	Compartmentation  • Fire check door	NA	NA	NA
	<ul> <li>Sealing of electrical shafts</li> <li>Fire Rating of shaft door</li> <li>Water Curtain</li> </ul>	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
,		NA	NA	NA
	Fire Dampers			1
4.	Smoke managements System	30 ACPH NA		NA
	Basements	30 ACPH 12 ACPH	NA	NA
	Upper floors	12 ACFII	100	
5.	Fire Extinguishers  • Total numbers	10 nos.	17 nos. (10kg=10.4. 5kg=4 & Foam=03 no.	MR
	Thurse	CO <sub>2</sub> / DCP	ABC, DCP & CO2	MR
	Types     ISI marking  MA	ISI Marked	Provided	MR



. 1	First – Aid Hose Reels			NA				
1	<ul> <li>Total numbers on each floor</li> </ul>	NA	NA	NA NA				
	<ul> <li>Length of hose reel hose</li> </ul>	NA	NA	NA NA				
	Nozzle diameter	NA	NA	NA				
.	Automatic fire detection and alarming system							
	Type of detector	NA	NA	NA				
	Location of Main Panel	NA	NA	NA				
	Location of Repeater Panel	NA	NA	NA				
	Alternate source of power	NA	NA	NA				
	Hooters' Location	NA	NA	NA				
3.	MOEFA	NA	NA	NA				
).	Public Address System	N/A	N/A	N/A				
$\rightarrow$	Automatic Sprinkler System	3.32.5.5.	ormillo de la colo	7 2 - 0				
10.	· · · · · · · · · · · · · · · · · · ·	NA	NA	NA				
-	Basements	NA NA	NA NA	NA NA				
	Upper Floor	17827030	NA NA	NA				
	<ul> <li>Sprinkler above false ceiling</li> </ul>	NA	INA					
11.	Internal Hydrants		lava .	NA				
	<ul> <li>Size of riser/down- comer</li> </ul>	NA	NA					
	<ul> <li>Number of hydrants</li> </ul>	NA	NA	NA				
	per floor	HTps://pdl	ard a serificial	NA				
*	Hose Box.	NA	NA	IVA				
12.	Yard Hydrants NA NA NA							
	Total number of hydrants	NA	NA					
	Hose Box	NA	NA	NA				
13.	Pumping Arrangements	111		4				
13.	Cround Level	alt	7 19 20 1 1191	12.2				
	Discharge of main pump	NA	NA	NA NA				
	▶ Head of main pump	NA	NA	NA NA				
	Number of main pumps	NA	NA	NA NA				
6	Jockey pump out put	NA	NA NA	NA NA				
	> Jockey pump head	NA	NA NA	NA NA				
	Standby Pump out put	NA	NA NA	NA NA				
	<ul><li>Standby Pump Head</li><li>Auto Staring/Manual</li></ul>	NA	NA NA	NA NA				
	> Auto Staring/Manual stopping	NA	NA NA	NA NA				
	> Pump House Access	NA	NA					
	Terrace level		NIA	NA				
	> Discharge of pump	NA	NA NA	NA NA				
	> Head of the pump	NA	NA	NA				
	> Power supply	NA	NA	NA NA				
1	> Auto starting of pump	NA	NA	147				
	tor Storage for fire fig	hting		NA				
14.	Underground tank capacity	NA	NA	IVA				
	> Draw of connection	NA	NA	NA				
	n: somice inlet	NA	NA	NA				
1			NA	ı NA				
	> Access to tank	NA	10.5	NA				

M

15	No Smoking Signage	Required Prov	rided	MR		
16.	Provision of Lifts	Required Prov	nueu	IVIK		
ho	Pressurization of Lift Sha	oft NA	NA A	NA		
	Pressurization of lift lobb	y NA	NA	NA		
	Communication in lift Ca	r NA	NA NA	NA		
	<ul> <li>Fireman's Grounding</li> <li>Switch</li> </ul>	NA	NA	NA		
	Lift Signage	NA	NA	NA		
17.	Standby power supply	Required	Provided	MR		
18.	Refuge Area	NA.	NA	1		
	> Total area	NA	NA DE	NA		
	> Location	NA	NA NA	NA NA		
19.	Fire control room					
	Detector system panel	NA	NA	NA		
	Flow Switch Panel	NA ·	NA	NA		
	PA System Panel	NA	NA	NA		
	Battery backup	NA .	NA	NA		
	Building Floor Plans	NA	NA	NA NA		
20.	Special Fire Protection Systems for Protection of special Risks, if any;	Fire buckets filled with dry sand & no loose electric wiring seen in the premises.		MR		

The fire protection systems provided in the building were tested checked at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules renewal of the FSC issued vide letter No. F6/DFS/MS/Petrol/2020/SZ/449 dated 03/11/2020 renewal under rule 37 of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer

Name: Santosh Kumar

Designation : A.D.O (SJ)

We are not entertaining the quest houses cares Tesned. In the same line abouted cases

stand also not the entertained by AFS. regardless earlier FSE issued or not, as it does not incarifumly with Rule 27.

& As per N/ 26 observatues of Director please put up in 000 Fpw meetry.

Dy cro trows

25/3/13

Do ctour punting 18/25

P) o (APW)/south

The matter was Discussed in FPW

meeting on 26/9/23, on The Petrol pumps are covered under mercantile occupane as per clause 6.6.1.1 of NBC part 4. There the present blog being Comprised of Ground floor only (It < 9m) is not covered under Rule. & DFS Rules.

If approved, area officer concerned may be directed to take action accordingly

Submitted for.

8mh 61x123