



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/2023/SZ/ 309

Dated: . 16. 10./2023

FIRE SAFETY CERTIFICATE

Charitable Society, S.L. House at Kh. No. 215/70/2/1, Sarai Shahji, Malviya Nagar Road, New Delhi-110017 in the building comprised of Stilt, Ground plus one upper floor owned/occupied by Mr. Amit Bansal was issued FSC by this department vide letter no F6/DFS/MS/EH/2020/SZ/96 dated 01/07/2020. The restaurant premise was re-inspected by the officers concerned of this department on 06/10/2023 in the presence of Mr. Amit Bansal and found that the said restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the building/premises is fit for occupancy Class- D "Assembly Building" and validity upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ...1.6. 1.0. 1.2023 at New Delhi by.

(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE

Copy to: -

 The DHO (Green Park Zone), Public Health Department, MCD, Green Park, New Delhi-110016 (Ref. MHA Portal ID 2023092716514 dated 27/09/2023)

Conditions for the validity of Fire Safety Certificate:

 All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and

responsibility of the management.

3. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

4. The certificate may not be treated in any case for the regularization of the unauthorized

construction, if any. Basement shall be used as per building bye laws.

5. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on

www.dfs.delhigovt.nic.in.



> _	-				आज़ादी अमृत	का महोत्स	नत		
1	Nam	IN.	SPECTION DE	DODE	64		202		
alh	1	Sanding	SPECTION REPORT Shri Sukhan Lal Memorial Charitable Society, S. House, at Kh. No. 215/70/2/1, Sarai Shahji, Malvi						
2	Туре	of Occupancy	Nagar Road, New Delhi-110017						
3	Build	ling Comprised of	Assembly Building "Group-D" (Barat Ghar)						
4	Type	of Case	Stilt, Ground + One Upper floors						
5	Detai	ls of Previous NOC	Renewal Manager Plans and Republication of the Renewal						
6	Fire S	Safety Disease	F6/DFS/MS/EH/2020/SZ/96 dated 01/07/2020						
7	Date	Safety Directives Letter No of Inspection	F6/DFS/MS/EH/2005/718 dated 04/04/2005						
8	Name	of inspection	06/10/2023						
9	Nome	of the Inspecting Officers	DO (South) & ADO (BCP)						
10	HOIL	& Designation of Officers the building side	Mr. Amit Bansal						
10.0		of construction	1991-92						
11		cant letter No.	MHA Portal ID 2023092716514 dated 27/09/2023						
S. No	Preve	num standards on Fire ntion and Fire Safety U/R 33	Old NOC Requirement	NOC Provided at		Remarks MR/NMR			
1	Acces	s to Building.	1,00	110-10	TOTAL TOWNS TO DATE.	-			
		Road width	Required		6 m	195	MR		
AV.	•	Gate width	Required		4.5 m		N/A-		
		Width of internal road	-N/A-		-N/A-	-1	V/A-		
2	Numb	er, width, type & arrangement	of exits.	- union	of to assume that a		Contraction (
	a) Number of Staircase								
	*	Upper floors.	02 nos		03 nos		MR		
	*	Basement floor.	-N/A-		-N/A-	-N/A-			
	b) Wi	dth of Staircase		quar	thouse to agree of the				
1	*	Upper floors	Required 1.25 m, 1.15 m & 1.5 m (Iron)		ron)) MR			
	*	Basement floor	-N/A-	16131-11	-N/A-		-N/A-		
91	c) Pro	tection of exits		MICHIGO	amel allouis				
112	*	Fire check door	-N/A-	Lucid	-N/A-	-N	I/A-		
W	*	Pressurization	-N/A-		-N/A-		-N/A-		
UE SX	d) No. of continuous staircase to terrace		Required		02 nos		MR		
- 1	e) Wid	Ith of corridor	-N/A-		-N/A-	-N	/A-		
_	20 Total	r size	2 m	quin	2 m × 4	N	1R		
	-/ 7	rtmentation.	N. Carlotte		Author to proud				
	Fire check door.		-N/A-		-N/A-		/A-		
		Sealing of electrical shafts.	-N/A-		-N/A-	-N/A-			
		Fire rating of shaft door.	-N/A-	aut ron	-N/A-	-N	/A-		
4	•	Water curtain	-N/A-	an a	-N/A-	-N	/A-		
	•	Fire dampers.	-N/A-	DOTE CHE	-N/A-	-N	/A-		
-	Smale I	Management system.			araz of execute w	7,31273	115-15		
. !		Basement	30 ACPH	311 -50	NA	N	Α		
	· L	Jpper floors	12 ACPH		-N/A-	-N/A-			
. 1		tinguishers.			The same of	17 2			
1	Т	otal numbers	ISI marked		15 Nos	MR			
		ypes			ABC-10&CO ₂ -05	NAME OF THE PARTY			
	IS	SI Marking	SVEY. I		Provided MI		MR		
F	irst Aid	l Hose Reels.		1	NID PRICE OF	11-			
+	T	otal numbers on each floor	Hose Reel		Provided	M	MR		
	400	W.			12 000				

W

Ī



	The second secon			0		
T	Length of hose-reel hose.	ā ajā	Provided	MR		
7	Nozzle Diameter	acti	Provided	MR		
7	Automatic fire detection & alarming system.					
	Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooter's location	-N/A-	Provided smoke type	-N/A-		
		-N/A-	-N/A-	-N/A-		
		-N/A-	-N/A-	-N/A-		
		-N/A-	DG Set	-N/A-		
		-N/A-	Every floor	-N/A-		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	Required	Provided	MR		
10.						
	Basement. Upper floors Sprinkler above false ceiling	-NA-	-NA-	-NA-		
		-NA-	-NA-	-NA-		
		-NA-	-NA-	-NA-		
11.						
	Size of Riser / Down-comer	-NA-	100 mm	-NA-		
ar.	Number of Hydrant per floor Hose box.	-NA-	One	-NA-		
	Lentury Control	-NA-	One	-NA-		
12.	Yard Hydrants.		Wydia of systematic ulac	1		
	 Total number of hydrants. Hose box. 	-N/A-	Provided Provided	-N/A-		
13.	Pumping arrangements.	-11/74-	Flovided	-N/A-		
	Ground Level		TOO TO THE PROPERTY OF			
	10 to	-N/A-	1620 LPM	-N/A-		
	Discharge of main pump. Head of main pump. Number of main pumps. Jockey Pump output. Jockey Pump head.	-N/A-	70 m	-N/A-		
		-N/A-	One	-N/A-		
		-N/A-	180 LPM	-N/A-		
		-N/A-	70 m	-N/A-		
	 Standby Pump output. Standby Pump head. 	-N/A-	-N/A-	-N/A-		
	> Auto Starting/Manual	-N/A-	-N/A-	-N/A-		
	stopping.	-N/A-	-N/A-	-N/A-		
	➤ Pump house access.	-N/A-	-N/A-	-N/A-		
	Terrace Level	1	antiering by dibits	-14/A-		
	Discharge of pump.	450 LPM	Provided	MR		
	Head of pump.	40 m	Provided	MR		
	Power supply.	Required	Provided	MR		
	Auto starting of pump.	Required	Provided	MR		
14.						
	Underground tank capacity.	-N/A-	2,00,000 ltrs	-N/A		
	Draw-off connection.	-N/A-	-N/A-	-N/A		
	 Fire Service Inlet. Access to tank. 	-N/A-	-N/A-	-N/A		
	Overhead tank capacity.	-N/A-	-N/A-	-N/A		
	400-	5,000 ltrs	Provided	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.					
i I	Pressurization of lift shaft.	-N/A-	-N/A-	-N/A		
	 Pressurization of lift lobby. 	-N/A-	-N/A-			
	 Communication in lift car. 	Required	Provided	-N/A		
	Fireman's switch.	Required	Provided	MF		
			Tiorided) IVII		

आज़ादी का अमृत महोत्सव

	Lift signage.	Required	Provided	MR			
17 18.	Standby Power Supply	Required	Provided (DG Set)	MR			
	Refuge Area						
	Total area	-N/A-	-N/A-	-N/A-			
	Location	-N/A-	-N/A-	-N/A-			
19.	Fire Control Room.						
	 Detector System Panel. 	-N/A-	-N/A-	-N/A-			
	Flow Switch Panel.	-N/A-	-N/A-	-N/A-			
	PA system Panel. Battery backup Building floor plan	-N/A-	-N/A-	-N/A-			
		-N/A-	-N/A-	-N/A-			
		-N/A-	-N/A-	-N/A-			
20.	Special Fire Protection System	for the Protection of s	pecial Risk, if any.	-N/A-			

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued &

communicated by this department vide letter of even no 534 dated 25/09/2023.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2020/SZ/96 dated 01/07/2020, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer

Name: Sh. Manoj Kumar Sharma Design: DO (South) Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CFO (HO)

10 10 2022

Dinector

Anypolp

A approved for

1 letter in portup for

11/1

Director my

Mel

16/10/23

An.