



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F.6/DFS/MS/SZ/2023/EH 310

Dated: 17/10 /2023

FIRE SAFETY CERTIFICATE

Certified that M/s Batra Bros Food and Beverages Pvt. Ltd, (Café Delhi Heights), Shop/Property No. D-4, Ground Floor, Defence Colony, New Delhi-110024, comprised of Ground plus 2 upper floors but restaurant at ground floor only have complied with the fire prevention and Fire Safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by a team of officers concerned of this department on 10/10/2023 in the presence of Sh. Ashish Verma of the restaurant and observed that the that said premises is fit for mixed occupancy "Assembly" (Eating House) with effect from 17 / 10 /2023 for a period of Three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rules, 2010.

Director Delhi Fire Service

Copy to: -

 The Joint Commissioner of Police (Lic.), First Floor, Police Station Defence Colony, New Delhi-110049 (w.r.t. online ID: 2023091916126 dated 21/09/2023)

 M/s Batra Bros Food and Beverages Pvt. Ltd, (Café Delhi Heights IKIGAI), Shop No. D-4, Ground Floor, Defence Colony, New Delhi-110024

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

- All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".

	INSPECT	ON REPORT	1 Dayses Pyt	Ltd (Café	
1	Name & Address of the Building	Delhi Heights	Food and Beverage Pvt. IKIGAI) at D-4, Groun New Delhi-110024		
_		Defence Colony, New Delhi–110024 Group-D, "Assembly" (Restaurant at GF only) Ground & two upper floors.			
2	Type of Occupancy				
3	Building Comprised of		pper noors.		
4	Type of Case	New			
5	Details of Previous NOC	Nil			
6	Fire Safety Directives Letter No	Nil	1103		
7	Date of Inspection	10/10/2023	1. V. mar	· ·	
8	Name of the Inspecting Officers	ADO (SJ) Santo	sh Kumai		
9	Name & Designation of Officers from the building side	Mr. Ashish Verma			
10	Year of construction	1989		09/2023	
11	Applicant letter No.	MHA ID No. 20	23091916126 dated 21/	Remarks	
S.	Minimum standards on Fire Prevention and Fire Safety U/R 33	UBBL/NBC-2016 Requirement	Provided at Site	MR/NMI	
No. 1	Access to Building.		(MR	
-	Road width	6m	6m	MR	
	Gate width	4.5m	Abut on road	N/A	
	Width of internal road	N/A	N/A	IVI	
	Number, width, type & arrangement of	exits.	A STATE OF THE STA	2 171	
2	a) Number of Staircase	The College of	and the first	N/A	
	a) Number of Staffcase	N/A	Restt at GF only	1, 15000201202	
	Upper floors.Basement floor.	N/A	N/A	N/A	
	b) Width of Staircase	27/4	Restt at GF only	N/A	
	> Upper floors	N/A	N/A	N/A	
	> Basement floor	N/A	N/A		
	c) Protection of exits	L A F	N//A	N/A	
	> Fire check door	N/A	N/A	N/A	
	> Pressurization	N/A	N/A	N/A	
	- discount etaircase to terrace	N/A	N/A	N/A	
	- a widow	N/A	N/A	POSSESSES SECTION AND ADDRESS OF THE POSSESSES AND ADDRESS A	
		1.5m x 2 Nos	Provided	MR	
	Door size Compartmentation.	而巨烈	I place to the second		
3	L. Joan	N/A	N/A	N/A	
	o ting of electrical shafts.	N/A	N/A	N/A	
	Fire rating of shaft door.	N/A	N/A	N/A	
	Water curtain	N/A	N/A	N/A	
	Fire dampers.	N/A	N/A	N/A	
	Smoke Management system.	1/1=0	entre and a		
4.		30 ACPH	N/A	N/A	
	Basement Upper floor	12 ACPH	N/A	N/A	
	Fire Extinguishers.		and the		
5.	Total numbers	Required	08 Nos	MR	
	CONTRACTOR	ABC/CO ₂ /W.CO ₂	ABC & CO ₂ /	MR	
	Types ISI Marking	Required	Provided	MR	
6.	First Aid Hose Reels.	100			
	Total numbers on each floor.	One	Provided	MR	
	Length of hose-reel hose.	30m	Provided	MR	
	a Length of hose-rect huse				



N-5

7	Automatic fire detection & alarming s	ystem.		
20 14	Type of detectors	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System	N/A	N/A	N/A
10	Automatic Sprinkler System			(d = 1
	Basement	N/A	N/A	N/A
	Upper floors.	N/A	N/A	N/A
	 Sprinkler above false ceiling 	N/A	N/A	N/A
11	Internal Hydrants.			700
	Size of Riser/Down-comer	100 mm	100 mm	MR
	Number of Hydrant per floor	One at GF	One at GF	MR
	Hose box.	One at GF	One at GF	MR
12	Yard Hydrants.	4 = = 1. = 12.		V1109121X1
III	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13	Pumping arrangements.		****	- 1071
_	Ground Level			
	Discharge of main pump.	N/A	N/A	N/A
	> Head of main pump.	N/A	N/A	N/A
	> Number of main pumps.	N/A	N/A	N/A
	> Jockey Pump output.	N/A	N/A	N/A
	> Jockey Pump head.	N/A	N/A	N/A
	> Standby Pump output.	N/A	N/A	N/A
	> Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
	Pump house access.	N/A	N/A	N/A
	Terrace Level			
	➤ Discharge of pump.	450 LPM	450 LPM	MR
	➤ Head of pump.	40m	40m	MR
	➤ Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.		Mobile Town	
	 Underground tank capacity. 	N/A	N/A	N/A
	Draw-off connection.	N/A	N/A	N/A
	➤ Fire Service Inlet.	N/A	N/A	N/A
	> Access to tank.	N/A	N/A	N/A
	 Overhead tank capacity. 	20,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.		Last night 1	Type and the same
	 Pressurization of lift shaft. 	N/A	N/A	N/A
	 Pressurization of lift lobby. 	N/A	N/A	N/A
	 Communication in lift car. 	N/A	N/A	N/A
	Fireman's switch.	N/A	N/A	N/A
	Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
8	Refuge Area		Samuel Land	
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A

80

19	Fire Control Room.			
	 Detector system panel. 	N/A	N/A	N/A
	 Flow switch panel. 	N/A	N/A	N/A
	 PA system panel. 	N/A	N/A	N/A
	Battery backup.	N/A	N/A	N/A
	Building floor plan.	N/A	N/A ·	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The Fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection. The shortcoming issued by this department vide letter no F.6/DFS/MS/2023/547 dated 04/10/2023 found rectified.

Keeping in view of the substantially satisfactory compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, The Fire Safety Certificate, under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Santosh Kumar

Designation: ADO (SJ)

1

19/10/53 Nosogen